

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 63

Dated 25/.63/2022

FIRE SAFETY CERTIFICATE

Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (03 guest room + reception + 01 office), 1st floor to 4th floor (09 guest rooms at each floor + 01 pantry at each floor) and Terrace floor (kitchen for staff + 02 staff room found sealed) total 39 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/2019/NDZ/864 dated 22/04/19. Now, the premises was re-inspected by the officer concerned of this department on 16/03/22 in the presence of Sh. Anil Sharma (Owner) and found that the said guest house building having given an affidavit dated 05.12.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest room + reception + 01 office), 1st floor to 3rd floor (09 guest rooms at each floor), Total - 30 guest rooms up to third floor only with effect from for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ... 25 03 2022 ... at New Delhi by.

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Ref. letter No. ID no. 2022030903292 dated 09.03.22.
- Sh. Anil Sharma (Owner), "Legend International" Guest House located 8525, Arakashan Road, Pahar Ganj, New Delhi

Conditions for the validity of Fire Safety Certificate

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building:- "Legend International" Guest House

8525, Arakashan Road, Pahar Ganj, New

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 05 Upper floors (total 30 Guest rooms) Ground floor (03 guest room + reception + 01 office), 1st floor to 3rd floor (09 guest rooms at each floor + 01 pantry at each floor), 4th & 5th floor/ Terrace floor (kitchen for staff + 02 staff room) not in use as per

affidavit dated 05.12.2019.

3. Type of case:-Renewal

F6/DFS/MS/GH/2019/NDZ/864 dated 4. Details of previous FSC:-

22/04/19

N/A

5. Fire safety directives No.-

6. Date of inspection:-16/03/22

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer

Sh. Anil Sharma (Owner) From the building side:-

9. Year of construction:-2004

ID no. 2022030903292 dated 09.03.22. 10. Applicant's letter No:-

	•		Old Case		
Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing	Provided at site PSS	Remarks MR/NMR		
Access to Building					
1) Road width	06 mtr.	06 mtr.	MR		
2) Gate width	N/A	N/A	N/A		
3)Width of internal road	N/A	N/A	N/A		
Number, Width Type & Arrangement of Exits					
A. Number of staircases					
1. Upper floors	01 Nos.	01 Nos.	MR		
	N/A	N/A	N/A		
B. Width of staircase					
1. Upper floors	0.80 mtr.	1.20 mtr.	MR		
2. Basements	N/A	N/A	N/A		
		,			
	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021		
	N/A	N/A	N/A		
staircase to terrace	01	01	MR		
	N/A	N/A	N/A		
	1 mtr.	1 mtr.	MR		
	N/A	N/A	N/A		
2) Sealing of electrical shafts	N/A	N/A	N/A		
	N/A	N/A	N/A		
	N/A	N/A	N/A		
	N/A		N/A		
Smoke Management System		1 - //	14/11		
1) Basements	30 ACPH	N/A	N/A		
	Prevention and fire safety U/R 33 Access to Building 1) Road width 2) Gate width 3) Width of internal road Number, Width Type & Arr A. Number of staircases 1. Upper floors 2. Basements B. Width of staircase 1. Upper floors 2. Basements C. Protection of exits 1. Fire check door 2. Pressurization D. No. of continuous	Prevention and fire safety U/R 33 Access to Building 1) Road width 2) Gate width N/A 3)Width of internal road N/A Number, Width Type & Arrangement of Ex A. Number of staircases 1. Upper floors 2. Basements N/A B. Width of staircase 1. Upper floors 0.80 mtr. 2. Basements N/A C. Protection of exits 1. Fire check door Required as per G.N dated 27.05.19 2. Pressurization N/A D. No. of continuous staircase to terrace E. Width of corridor F. Door size I mtr. Compartmentation 1) Fire check door N/A 2) Sealing of electrical shafts N/A 3) Fire rating of shaft door 4) Water curtain N/A Smoke Management System	Prevention and fire safety U/R 33 Access to Building 1) Road width		

						465
	1 a) VI	12	a/c per	Natural/exhaust	N	/IR
	2) Upper floors	ho		fan	-	
	To the wishers	n n d dahan			A	(D
5.	Fire Extinguishers	1.5	Nos.	15 Nos.	_	IR
	1) Total numbers	AF	3C & CO2	ABC & CO2	-	IR
	2) Types		quired	Provided	N	IR .
	3) ISI marking	ICC	quirea			
6.	First-Aid Hose Reel	01		01	N	/IR
	1) Total number of eachfloor		mtr.	30 mtr.	N	/R
	2) Length of hose reel hose			05 mm	N	/R
	3) Nozzle diameter	05	mm			
7.	Automatic Fire Detection &	Ala	rming Syste	Not provided	L	ast dt.
	1) Type of detectors CO type	I Re	quii cu as	Not provided	3	.03.22 of
		per	G.N dated		C	mpliance
		27.	05.19			tended vide
						der dt.
						12.2021
	2) Location of main panel	N/	A	N/A		/A
	3) Location of repeater panel	N/	A	N/A		/A
	4) Alternate source of power	N/	A	N/A		/A
	5) Hooter's Location	N/		N/A		/A
	,		quired	Provided	M	
8.	MOEFA	Re	quired	Provided	M	R
9.	Public Address System		quiiva			
10.	Automatic Sprinkler System	N/	Δ	N/A	N	Α
	1) Basement	N/		N/A	N	Ά
	2) Upper floors	N/		N/A	N	'A
	3) Sprinkler above false	14/	Α.	* " =		
	ceiling					
11.	Internal Hydrants 1) Size of riser/down-comer	N/	Δ	N/A	N	Ά
	Number of hydrants per	N/		N/A	N	Ά
		1 177	•			
	floor 3) Hose box	N/A		N/A	N	Ά
		1				
12.	Yard Hydrants 1) Total number of hydrants	N/	A	N/A	N	
	2) Hose box	N/		N/A	N	A
	Pumping Arrangement	1				
13.	1) Ground level		N/A	N/A		N/A
		mp	N/A	N/A		N/A
	a) Discharge of main purb) Head of main pump	p	N/A	N/A		N/A
	c) Number of main pump	2	N/A	N/A		N/A
			N/A	N/A		N/A
	1 1		N/A	N/A		N/A
			N/A	N/A		N/A
	1 1	-	N/A	N/A		N/A
	g) Stand by pump head	\dashv	N/A	N/A		N/A
	h) Auto starting/Manual		14/17	1		
	stopping				\top	
	2) Terrace level		450 LPM	450 LPM	\top	MR
	a) Discharge of pump		30 mtr.	30 mtr.		MR
	b) Head of pump		Required	Provided	_	MR
	c) Power supply		Required	Provided		MR
	d) Auto starting of pump		Required	110,100	_	



4.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	 d) Over head tank capacity 	25000 ltr.	25000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A NA	
20.	Special Fire Protection System for Protection of special Risk, if any:				

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2019/NDZ/864 dated 22/04/2019 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - XDO (CC)

Arabbarres Pari pentent for Kenter,

MR

MR **V**R