GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/CGHS/WZ/ 1 >/

Dated: 95/03/2092

FIRE SAFETY CERTIFICATE

Certified that the Talagang Co-Op Group Housing Society Ltd. Plot No.49, Sec-13, Rohini, Delhi-85, comprised of Sixteen blocks, High rise-11, Low rise-05, has already been issued FSC by this department vide letter No. F.6/DFS/MS/2015/CGHS/WZ/14 dated 04.01.2016. The premises was re-inspected by the officer concerned of this department on 10.03.2022 in the presence of Sh. Sharad Poddar, Secretary and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Class Residential with effect from or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

DIRECTOR Ph; 011-23414000

Copy to:-

1. Joint Director (Bldg.) DDA, Vikas Sadan, INA, New Delhi.

2. The Hony. Secretary, Talagang Co-Op Group Housing Society Ltd. Plot No.49, Sec-13, Rohini, Delhi-85.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

1/37

INSPECTION REPORT

1. Name & address of the building: Talagang Co-Op Group Housing Society Ltd. Plot No.49, Sec-13,

Rohini, Delhi-110085.

2. Type of Occupancy : Residential Building "Group A-4"

3. Type of Case : Renewal (Total blocks-16, High rise-11 (Gr.+ 7) Low rise-5 (Gr.+3)

4. Details of Previous NOC : F.6/DFS/MS/2015/CGHS/WZ/14 dated 04.01.2016

5. Fire Safety directives letter No : F6/MS/DFS/86/CGHS/1005 dated 27.06.1986

6. Date of inspection : 10.03.2022

7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

8. Name and designation of officers

From the building side : Sh. Sharad Poddar, Secretary

9. Year of Construction : 1999

10	rear of Construction : 1999						
S. No.	. Minimum Standards on fire prevention	Rule 35 (6)	Provided at site	Remark MR/NM			
1.	and fire safety U/R 33 Access to building			IVIIVI			
	Road width	Accessible	e Accessible	MR			
	Gate width	Accessible		MR			
	Width of internal road	6.0m	6.0m	MR			
2.			0,0,11				
	Number, Width, Type & Arrangement of Exits d. Number of staircases						
	Upper Floors	03	Provided	MR			
	Basements	04	Provided	MR			
	e. Width of staircases	04	Tiovided	17110			
		NA	Provided	MR			
	Upper Floor						
	Basements	NA	Provided	MR			
	f. Protection of exits	NA	NA NA	NA			
	Fire check door	Required	Provided	MR			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	NA	NA	NA			
	Compartmentation						
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
	 Fire Rating of shaft door 	Required	Provided	MR			
	Water Curtain	NA	NA				
	 Fire Dampers 	NA	NA	NA NA			
1	Smoke Management System	1111	IVA	INA			
_	Basements	30 a/c per hour	Exhaust fan	MD			
-	Upper floors	12 a/c per hour		MR			
		12 a/c per nour	Natural ventilation	MR			
F	Fire Extinguishers						
	Total numbers	Required	Provided	MR			
	• Types	ABC/CO2	ABC/CO2	MR			
-	IS marking	ISI marked	Yes	MR			
Fi	irst-Aid Hose Reels						
	Total numbers on each floor	01	Provided	MR			
	Length of hose reel hose	30mm	Provided	MR			
-	Nozzle diameter	5m	Provided	MR			
Al	utomatic fire detection and alarming system						
	Type of detectorsLocation of Main Panel	NA	NA	NA			
		NA	NA	NA			
	 Location of Repeater Panel 	NA	NA	NA			

11/38

		,				
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
1	MOEFA	Required	Provided	MR		
	Public Address System	Required	Provided	MR		
	Automatic Sprinkler System					
	Basement	Required	Provided	MR		
	 Ground & Upper Floors 	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
	Internal Hydrants					
	Size of riser/down-comer	Required	Provided	MR		
	 Number of hydrants per floor 	01	Provided	MR		
	Hose Box	01	Provided	MR		
	Yard Hydrants					
	Total number of hydrants	Required	Provided	MR		
	Hose Box	Required	Provided	MR		
	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	Required	Provided	MR		
	➤ Head of Main pump	NA	Provided	MR		
	Number of main pumps	NA	Provided	MR		
	Jockey Pump out put	Required	Provided	MR		
	 Jockey pump head 	NΛ	Provided	MR		
	Standby Pump out put	Required	Provided	MR		
	➤ Standby Pump Head	NA	Provided	MR		
	➤ Auto Starting/Manual Stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level	, , , , , , , , , , , , , , , , , , , ,				
	Discharge of pump	Required	Provided	MR		
	> Head of the pump	40m	Provided	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
1.4	Captive Water Storage for fire fighting					
14.		2,00,000ltr	Provided	MR		
	 Underground tank capacity Draw-off connection 	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10,000 Ltr. Every	Provided	MR		
	,	high rise blk				
15.		Required	Provided	MR		
16.	Provision of Lifts.					
	 Pressurization of Lift Shaft 	NA	NA	NA		
	 Pressurization of Lift lobby 	NA	NA D	NA		
	 Communication In lift Car 	Required	Provided	MR		
	 Fireman's Grounding Switch 	Required	Provided	MR		
	 Lift Signage 	Required	Provided	MR		
17		Required	Provided	MR		
18		NA	NA	NA		
	Total AreaLocation	NA	NA	NA		
	A STATE OF THE PROPERTY AND ADDRESS OF THE PROPERTY OF THE PRO					
19		Required	Provided	MR		
7	 Detector System Panel 		Provided	MR		
	 Flow Switch Panel 	Required	Provided	MR		
	 PA System Panel 	Required	FIGVICE	IVIIV		

Battery backup	Required	Provided	MD
• Building Floor Plans 20. Special Fire Protection System for	Required	Provided	MR MR
Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 1592 dated 11.08.2021, the FSC issued vide letter no. .6/DFS/MS/2015/CGHS/WZ/14 dated 04.01.2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Office

Name: - D.B Mukherjee Designation:- DO/NW Signature of the Impecting O Name: - Ajay Kumar Sharma Designation:- ADO/Rohini

D.O. (WEST)/-98 DATED-21/3/2022

Der (HZ)

CAS

no And My

Amy Rohn

Directo My Mon 200

My 25/3/22

Committee