Dated: .23./.o.3./2022



No. F.6/DFS/MS/GH/2022/SZ/ [6]

## FIRE SAFETY CERTIFICATE

Certified that **M/s Hotel Anutham**, (A Unit of SACRED Homes Pvt Ltd) located at E-147, E Block, Saket, New Delhi 110017 comprised of Basement, Ground plus three upper floors (Basement & Ground floor others property) 1<sup>st</sup> floor reception & 07 G/Rooms, 2<sup>nd</sup> floor 08 G/Rooms and 3<sup>rd</sup> floor 02 Guest Rooms total 17 guest rooms owner/occupied by (A Unit of SACRED Homes Pvt Ltd) was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/2018/SZ/2490 dated 08-11-2018. The premise was re-inspected by the officer concerned of this department on 18/02/2022 in the presence of Mr. Gaurav and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Residential & Lodging"**, **Group-A**" (Guest House for 17 Guest rooms) with effect from the date of issue 23/03/2022 for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. M/s Hotel Anutham, (A Unit of SACRED Homes Pvt Ltd) located at E-147, E Block, Saket, New Delhi 110017.
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-49. (Ref. MHA Portal ID 2021102825378 dated 29/10/2021)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 7. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on **or before 31/03/2022** in compliance to the notification dated 27/05/2019 an as approved and extended the deadline for compliance time limit by the Hon'ble Minister (UD) vide letter no F5 (189)/AD/LB/2016/3618-37 dated 20/12/2021.



	DIODECTIO	N REPORT				
3		N REPORT  M/s Hotel Anutham, (A Unit of SACRED Homes				
i	Name & Address of the Building	Pyt Ltd) locate	d at E-147, E Block,	Saket, New		
		Dath: 110017				
	T	1 0 I adoing				
2	Type of Occupancy	Basement, Ground + 03 Upper Floors. (Basement &				
3	Building Comprised of	Ground Others property)				
4	Type of Case	Renewal F.6/DFS/MS/GH/2018/SZ/2490 dated 08-11-2018.				
5	Details of Previous NOC					
6	Fire Safety Directives Letter No	Nil 18/02/2022				
7	Date of Inspection	Sh. Rajesh Kumar ADO (BCP)				
8	Name of the Inspecting Officers	Mr. Gaurav				
9	Name & Designation of Officers					
	from the building side	2009 Guest house 1 <sup>st</sup> to 3 <sup>rd</sup> floor Total= 17 Guest Rooms.				
10	Year of construction	NAME A Ported ID 2021102825378 dated 29/10/2021				
11	Applicant letter No.	Old NOC	Provided at Site	Kemaiko		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements		MR/NMR		
1	Access to Building.		7 1.1	MR		
1	Road width	12 mtr	Provided	N/A		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	IN/A		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase			MR		
	> Upper floors.	01 Nos	Provided	N/A		
	Basement floor.	N/A	Others property	IN/A		
	b) Width of Staircase			MR		
	> Upper floors	0.90 cms	01 mtr (old case)	N/A		
	> Basement floor	N/A	Others property	N/A		
	c) Protection of exits		37/4	N/A		
	Fire check door as per clause 7.31	N/A	N/A	IN/A		
	in UBBL-2016	N/A	N/A	N/A		
	> Pressurization		01	MR		
	d) No. of continuous staircase to terrace	01	N/A	N/A		
	e) Width of corridor	N/A 01 mtr	Provided	MR		
	f) Door size	O1 IIII	Tiovided			
3	Compartmentation.	N/A	N/A	N/A		
	• Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	N/A	N/A	N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	• Fire dampers.		N/A N/A N/A  Circular dated 20/12/2021 amendment / modification			
4	Smoke Management system.	in (UBBL-2016 till 31/02/2022)				
	Basement	30 ACPH	Others property	N/A		
	Upper floors	12 ACPH	Exhaust fan provided	MR		
5	Fire Extinguishers.					
	Total numbers	Portable Fire	12 Nos	MR		
	• Types	Extinguishers	ABC type	MR		
	ISI Marking	ISI marked	Yes	MR		
6	First Aid Hose Reels.					
	Total numbers on each floor.	One	One	MR		
	Length of hose-reel hose.	30m 5mm	30m	MR		
	Nozzle Diameter  A detection & clerming system		5mm	MR		
7	Automatic fire detection & alarming system.	Circular dated 20/12/2021 amendment / modification in (UBBL-2016 till 31/02/2022)				
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		

N/16

_	8 MOEFA				
	9 Public Address System	Required	d Provided	MR	
	10 Automatic Sprinkler System	N/A	N/A	N/A	
	Basement			•	
		N/A	N/A	N/A	
	opper moors	N/A	N/A	N/A	
1	Sprinkler above false ceiling     Internal Hydronia	N/A	N/A	N/A	
	internal Hydrants.				
	<ul> <li>Size of Riser/Down-comer</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Number of Hydrant per floor</li> </ul>	N/A	N/A	N/A	
	• Hose box.	N/A			
1		IN/A	N/A	N/A	
	Total number of hydrants.	27/4	27/4	7	
	<ul> <li>Hose box.</li> </ul>	N/A	N/A	N/A	
13		N/A	N/A	N/A	
	arrangements.				
	• Ground Level  Discharge of main nume				
		N/A	N/A	N/A	
	Head of main pump.	N/A	N/A	N/A	
	rumber of main pumps.	N/A	N/A	N/A	
	Tulip output.	N/A	N/A	N/A	
	ramp nead.	N/A	N/A	N/A	
	<ul><li>Standby Pump output.</li><li>Standby Pump head.</li></ul>	N/A	N/A	N/A	
	Auto Starting/Manual Stopping	N/A	N/A	N/A	
	<ul><li>Pump house access.</li></ul>	14/11	N/A	N/A	
		N/A	N/A	N/A	
	Terrace Level     Discharge of nump	1			
	<ul><li>Discharge of pump.</li><li>Head of pump.</li></ul>	450 & 180 LPM	450 & 180 LPM	MR	
	Power supply.	35 m each	35m each	MR	
	<ul><li>Auto starting of pump.</li></ul>	Required	Provided	MR	
14	Captive water storage for fire fighting.	Required	Provided	MR	
	Underground tank capacity.	N/A	N/A	NI/A	
	> Draw-off connection.	N/A	N/A	N/A N/A	
	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	N/A	N/A	N/A	
	<ul> <li>Overhead tank capacity.</li> </ul>	5,000 Lts	5,000 Lts	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Communication in lift car.</li> </ul>	N/A	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A	
	Lift signage.	N/A	N/A	N/A	
17	Standby Power Supply	Required			
18	Refuge Area	Required	Provided (DG set)	MR	
	Total area	N/A	N/A	N/A	
	• Location	N/A	N/A		
9	Fire Control Room.	14/71	IV/A	N/A	
,	Detector system panel.	N/A	N/A	NI/A	
		N/A		N/A	
	• Flow switch panel.		N/A	N/A	
1	PA system panel.	N/A	N/A	N/A	
	Battery backup.	N/A	N/A	N/A	
	Building floor plan.	N/A	N/A	N/A	
	Special Fire Protection System for the	N/A	N/A	N/A	
	Protection of special Risk, if any.				

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 31/03/2022 in compliance to the notification dated 27/05/2019 an as approved and extended the deadline for compliance time limit by the Hon'ble Minister (UD) vide letter no F5 (189)/AD/ LB/2016/3618-37 dated 20/12/2021.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/GH/2018/SZ/2490 dated 08-11-2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of Inspecting Officer Name: Sh. Rajesh Kumar

ADO (BCP) Design:

approved, F.T. Letter in printip signature Pl

Dy Gols 2

Revalidate Asc uplouded on MMA Portel