475

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/

Dated :30./.03/2022

## **FIRE SAFETY CERTIFICATE**

Certified that the Maurya Assam Guest House located at 7963, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 upper floor, Ground floor (Reception + 01 guest rooms), 1st floor (03 guest rooms), 2nd floor (03 guest rooms), total 07 guest rooms owned/occupied by Maurya Assam Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2435 dated 30/10/18 ( for ground and two upper floors only) . Now, the premises was re-inspected by the officer concerned of this department on 10/03/22 in the presence of Manager and found that the said guest house building comprised of ground and four upper floors Ground floor (Reception + 01 guest rooms), 1st floor (03 guest rooms), 2nd floor (03 guest rooms) and 3<sup>rd</sup> floor & 4<sup>th</sup> floor shall not be used as per under taking dated 10.03.2022 has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 01 guest rooms), 1st floor to 2nd floor (03 guest rooms at each floor), total 07 guest rooms up to second floor only with effect from ... 3.0.1.0.3.1221 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 30. . 0.3. . . . . . . . . . . . at New Delhi by.

(**Dr. S.K.Tomar**)
Dy. Chief Fire Officer

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi : to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no 2022011900981 dated 08.02.22.
- 3. The Manager,

Maurya Assam Guest House 7963, Arakashan Road, Pahar Ganj, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N/28

INSPECTION	REPORT
------------	--------

1. Name & address of the building Maurya Assam Guest House at 7963,

Arakashan Road, Pahar Ganj, New Delhi

2. Type of occupancy:-Residential, Sub Division-A-1

Ground + 04 upper floor, total 07 guest rooms Ground floor (Reception + 01 guest rooms), 1<sup>st</sup> floor (03 guest rooms), 2<sup>nd</sup> floor (03 guest rooms) and 3<sup>rd</sup> & 4<sup>th</sup> floor will not use as per under taking

dated 10.03.2022

3. Type of case:-

No. F6/DFS/MS/GH/2018/NDZ/2435 dated 4. Details of previous FSC:-

30/10/18

Renewal

N/A 5. Fire safety directives No.-

10/03/22

6. Date of inspection:-

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Manager

9.	Year of construction:-	2007		
10.	Applicant's letter No:-		2011900981 dated 0	08.02.22.
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	06 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of E	xits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			1.65
	1. Upper floors	0.80 mtr.	0.93 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			-
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace		27/1	27/4
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	1.06 mtr.	MR
3.	Compartmentation			27/4
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		T	27/4
	1) Basements	30 ACPH	N/A	N/A Last dt.
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
5.	Fire Extinguishers			
	1) Total numbers	08 Nos.	08 Nos.	MR

## 4(23

			1000 0000	100
	2) Types	A	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			10
	1) Total number of eachfloo	r 01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &		tem	
/.	Type of detectors Co type	Required	Provided	MR
	2) I water of main panel	Gr. floor	Provided	MR
	2) Location of main panel		N/A	N/A
	3) Location of repeater panel		Provided	MR
	4) Alternate source of power	Gr. floor	Provided	MR
	5) Hooter's Location		N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	18/73	
10.	Automatic Sprinkler System	n	N/A	N/A
	1) Basement	N/A	N/A N/A	N/A
	2) Upper floors	N/A		N/A
	3) Sprinkler above false	N/A	N/A	1111
	ceiling			
11.	Internal Hydrants		NI/A	N/A
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	17/24
	floor			N/A
	3) Hose box	N/A	N/A	IVA
12.	Yard Hydrants			NI/A
14.	1) Total number of hydrants	N/A	N/A	N/A N/A
	2) Hose box	N/A	N/A	IVA
12	Pumping Arrangement			
13.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
			N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	- 11	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	14/11		
	stopping			
	2) Terrace level	450 LPM	450 LPM	MR
	a) Discharge of pump		30 mtr.	MR
	b) Head of pump	30 mtr.	Provided	MR
	c) Power supply	Required		MR
	d) Auto starting of pump	Required	Provided	IVIIC
		vo Fighting		
	Captive Water Storage for Fin	N/A	N/A	N/A
	1) Ulluci giodila alla	1 4/ / 1		
	capacity	NI/A	N/A	N/A
	a) Diaw-on comment	14/11	N/A	N/A
	b) The service inter	1 1/12		N/A
-	c) Access to tank	N/A	N/A	1 11 1

	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	- quired	Tiovided	IVIIC
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	<ul> <li>c) Communication in lift car</li> </ul>	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2435 dated 30/10/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended upto second floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO(CC)

inspirit sees

upwaded.