GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/169

Dated : 2.9./. 9.32022

FIRE SAFETY CERTIFICATE

Certified that the Rossette Guest House located at 8708, D.B.G. Road, Pahar Ganj, New Delhi comprised of Basement + Ground + 03 Upper floors, Basement (Storage purpose with separate exit & entry and same is other's property), Ground floor (reception + lobby + 06 guest rooms), 1st floor to 3rd floor (06 guest rooms at each floor), total 24 guest rooms owned/occupied by Rossette Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/481 dated 08/03/19 Now, the premise was reinspected by the officer concerned of this department on 24/03/22 in the presence of Sh. Vijay Bansal (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential. Sub Division-A-1 Ground floor (reception + lobby + 06 guest rooms), 1st floor to 3rd floor (06 guest rooms at each floor), total 24 guest rooms up to third floor only, with effect from .2.1.1.2.3.1.2012: for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 29/03/2022 at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2022030803216 dated 08.03.2022.
- 3. The Manager.

Rossette Guest House at 8708, D.B.G. Road, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. Any flammable material for interior decoration is prohibited.



INSPECTION REPORT HIS

1. Name & address of the building Rossette Guest House at 8708, D.B.G.

Road, Pahar Ganj, New Delhi Residential, Sub Division-A-1

2. Type of occupancy:-B + Gr. + 03 Upper floors (total 24 Guest rooms)

Basement (Storage purpose with separate exit & entry and it is other's property), Ground floor (reception + lobby + 06 guest rooms), 1st floor to 3rd floor

(06 guest rooms at each floor)

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2019/481 dated

08/03/19

5. Fire safety directives No.-N/A 6. Date of inspection:-24/03/22

7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

From the building side:-Sh. Vijay Bansal (Manager)

9. Year of construction:-2007

Online id no. 2022030803216 dated 08.03.2022. 10. Applicant's letter No:-

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	18 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Ar	rangement of Ex		
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	01 Nos.	01 Nos.	MR
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.23 mtr.	MR
	2. Basements	0.80 mtr.	1.23 mtr.	MR
	C. Protection of exits			
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			1111
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		4	IN/A
	1) Basements	30 ACPH	Exhaust fan	MR



M/26

	2) Upper floors	12 a/c per hour	Natural/Exhaust fan	MR
5.	Fire Extinguishers			
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	required	Tiovided	IVIIC
	1) Total number of each	01	01	MR
	floor			IVIIC
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst		
	1) Type of detectors Co Type	Required	Provided	MR
	2) Location of main panel	Required	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A		N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		•	
	1) Total number of hydrants	N/A		N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A		N/A
	a) Discharge of main	N/A	N/A	N/A
	pump	N/A	N/A	N/A
	b) Head of main pump	N/A N/A		N/A
	c) Number of main pump	N/A N/A		N/A
	d) Jockey pump out put	N/A N/A		N/A
	e) Jockey pump head	N/A N/A		N/A
	f) Stand by pump output	N/A N/A		N/A
	g) Stand by pump head			N/A
	h) Auto starting/Manual	N/A	11/17	11/43
	stopping			
	2) Terrace level	225 I DM	225 LPM	MR
-	a) Discharge of pump	225 LPM		MR
	b) Head of pump	30 mtr.	50 1	MR
	c) Power supply	1000	1101100	MR
	d) Auto starting of pump	Required	FIUVIUCU	1711

14.	Captive Water Storage for I	Fire Fighting		Tarri
14.	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	5000 ltr.	5000 ltr.	MR
	capacity	Required	Provided	MR
15.	Exit Signage.	Required	Tiovided	
16.	Provision of Lifts.			N/A
	a) Pressurization of lift shaft	N/A	N/A	
	b) Pressurization of lift	N/A	N/A	N/A
	c) Communication in	N/A	N/A	N/A
	lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A N/A	N/A	N/A
	e) Lift signage		Provided	MR
17.	Stand by Power Supply	Required	N/A	N/A
18.	Refuge Area	N/A		
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any: One ABC type fire	m for Protect	tion of special	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/481 dated 08/03/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

273/22

Dycho (Moz)

28/3/22

i putup for lecus forces

and seems in Plan

291212

