

FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[See sub-rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C 65

No.F.6/DFS/MS/Banquet/2022/NDZ/ 18

Dated: 23/03 /2022

FIRE SAFETY CERTIFICATE

Certified that the Gold Mines Banquets located at **Unit No.101 (First Floor) & Unit No. 201 (Second Floor)**, Plot No-C, Community Centre, Vivek Vihar, Shahdara, Delhi-110095, in a building comprising two basement, Ground plus nine upper Floors owned / occupied by M/S Gold Mines Banquets has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/Banquet/2019/1158 dated 31/05/2019. The premises was re-inspected by the officer concerned of Fire Service on 12.03.2022 in the presence of Sh. Krishna Jain and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class "Assembly Building/Banquet Hall" (Group-D) with effect from 23/03/2022 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on 23/03/2022 at New Delhi by.


(ATUL GARG)
DIRECTOR

Copy to :-

1. Authorised Signatory, Gold Mines Banquets located at Unit No.101 First Floor & Unit No. 201 Second Floor, Plot No-C, Community Centre, Vivek Vihar, Shahdara, Delhi-110095.
2. The Dy. Health Officer, East Delhi Municipal Corporation, Shahdara (South) Zone, Karkardooma, Delhi.

Conditions for the validity of Fire Safety Certificate:

1. **This FSC is valid for 1st and 2nd floor only.**
2. All the means of escape / entry / exit shall be kept free from any obstruction.
3. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
4. Any loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.
5. All the staff members must know the correct method of operation of fire fighting system.
6. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.
9. Basement shall be used as per BBL-1983.

INSPECTION REPORT

1. Name & address of the building: Gold Mines Banquets, unit no.101 F F & unit no. 201 S F, Plot No-C, Community Centre, Vivek Vihar, Shahdara, Delhi-110095.
 2. Type of Occupancy : Assembly (Banquet)
 3. Type of Case : Renewal
 4. Details of previous NOC : F6/DFS/MS/Banquet/2019/1158 dt. 31/05/2019
 5. Fire Safety directives Letter No. : F6/DFS/MS/2012/77 dated 25/06/2013
 6. Date of inspection : 12/03/2022
 7. Name of the Inspecting Officer : D.O (East)
 8. Name and designation of Officer from the building side : Sh. Krishna Jain
 9. Year of Construction : 2009
 10. Applicant's letter No. : 2022022602772 dated 03/03/2022

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	12 mtr	30 mtr.	MR
	• Gate width	4.5 mtr	4.5 mtr	MR
	• Width of internal road	06 mtr	06 mtr	MR
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	2	2	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	1.50mtr	1.50mtr & 1.25mtr	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	Required	Provided	MR
	d. No of continuous staircase to terrace	2	2	MR
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	2.00 mtr	2.0 mtr & 1.50 mtr	MR (Accepted as earlier)
3.	Compartmentation			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	4	6	MR
	• Types	ABC/CO ₂	Provided	M/R
	• IS marking	Required	Provided	M/R

6.	First - Aid Hose Reels			
	• Total numbers on each floor	2	2	MR
	• Length of hose reel hose	30mtr.	30mtr.	MR
	• Nozzle diameter	5 mm	5 mm	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Heat & Smoke	Provided	MR
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Battery & DG Set	Provided	MR
	• Hooters' Location	Different Location	Different Location	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	• Size of riser/down-comer	150 mm	150 mm	MR
	• Number of hydrants per floor	2	2	MR
	• Hose Box	2	2	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	04 nos.	MR
	• Hose Box	N/A	04 nos.	MR
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	N/A	2280 lpm	MR
	➤ Head of main pump	N/A	88 mtr	MR
	➤ Number of main pumps	N/A	02 nos	MR
	➤ Jockey pump out put	N/A	180 lpm	MR
	➤ Jockey pump head	N/A	88 mtr	MR
	➤ Standby Pump out put	N/A	2280 lpm	MR
	➤ Standby Pump Head	N/A	88 mtr	MR
	➤ Auto Starting/Manual stopping	N/A	Provided	MR
	➤ Pump House Access	N/A	Provided	MR
	• Terrace level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the pump	88 mtr	40 mtr	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	N/A	2,00,000 Ltr	N/A
	➤ Draw of connection	N/A	Provided	MR
	➤ Fire service inlet	N/A	Provided	MR
	➤ Access to tank	N/A	Provided	MR
	• Overhead Tank capacity	20,000Ltrs	20,000Ltrs	MR

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	Required	Provided	MR
	➤ Pressurization of lift lobby	Required	Provided	MR
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area			
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	Provided	N/A
	➤ Flow Switch Panel	N/A	Provided	N/A
	➤ PA System Panel	N/A	Provided	N/A
	➤ Battery backup	N/A	Provided	N/A
	➤ Building Floor Plans	N/A	Provided	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	Provided	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to renew Fire Safety Certificate.

[Signature]
14/03/22

Signature of the Inspecting Officer
Name: Ashok Kumar Jaiswal
Designation : D.O. (ED)

DY CFO (NDZ) B. Hall is at first second floor of A.H.P. Bldg. for renewal.
[Signature]
15/3/22



CFO (CB) - D/O
[Signature]
15/03/2022
HR

जुदा प्रदे वल्ले
का NOC है।

[Signature]
16/3/22

~~DO (ED)~~ हों। महोदय जिन्वर होटल का अनापत्ति प्रमाण प्रमाण पत्र संलग्न है।
17/03/2022

DY CFO (NDZ)
[Signature]
17/3/22

[Signature]