G13

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/ 382

Dated: 06/04/2022

FIRE SAFETY CERTIFICATE

Certified that the building of **Govt. Boys Sr. Sec. School,** Paprawat, New Delhi-110043, comprised of two blocks namely Block-A & Block-B. Each block is having ground plus one upper floor only, owned/occupied by the Govt. Boys Sr. Sec. School was issued FSC by this department vide letter no. F6/DFS/MS/School/2018/SZ/2150 Dated 19/09/2018. The school building was reinspected by the officer concerned of this department on 30/03/2022 in the presence of Sh. Bhim Singh (Vice-Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(SUNIL CHÁWDHARY) DY.CHIEF FIRE OFFICER DELHI FIRE SERVICE

74,

Copy to:-

- The Principal, Govt. Boys Sr. Sec. School, Paprawat, New Delhi-110043.
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: Govt. Boys Sr. Sec. School, Paprawat, New Delhi-110043. 2. Building comprised of 2 blocks A & B (each block is having ground plus one upper floor only)

3. Type of Occupancy Educational 4. Type of Case Renewal

Details of Previous NOC
Fire Safety directives letter No : 5. F6/DFS/MS/School/2018/SZ/2150 Dated 19/09/2018

F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

Date of inspection 30/03/2022 8. Name of Inspecting Officer9. Name and designation of officers A.D.O. R.K. Yadav

From the building side Sh. Bhim Singh (Vice-Principal)

10. Year of Construction

S. No.	Standards on the prevention and		Dir. Of Edu.		Remarks			
	lire s	afety U/R 33	Circular dt.	site	MR/NMR			
1.	Acce	ss to building	01.03.2011					
	Acce	Road width	A '11					
	Gate width		Accessible 4.5 m	Provided	M/R			
	Width of internal road		N/A	Provided N/A	M/R N/A			
2.	Num	ber, Width, Type & Arrangement of Exi		IN/A	IN/A			
	a. Nu	mber of staircases						
	•	Upper Floors	03 No's in each block	03 No's in each block) / / D			
	•	Basements	N/A		112/10			
	b. Wi	dth of staircases	N/A	N/A	N/A			
	•	Upper Floor						
	•	Basements	1.5 m	2X1.40 m & 1.45 M in bloc Λ & 1.50 MX3 in block-1				
	0 P-0	tection of exits	N/A	N/A	N/A			
	c. Pro	Fire check door						
		Pressurization	N/A	N/A	N/A			
		i ressurization	N/A	N/A	N/A			
	d. No	of continuous staircases to			IV/A			
		race	N/A	. N/A	21/4			
	e. Wi	d <mark>t</mark> h of Corridor	1.50 M	1.75 M in each block	N/A			
					M/R			
		or Size	1.0 M	1.07 M (Double Door)	M/R			
	Comp	artmentation		(Bouble Boot)				
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	N/A	Natural Ventilation				
	Fire Extinguishers							
	•	Total numbers	14 no's	Provided	M/R			
	•	Types	ABC/CO2 type	Provided	M/R			
	•	IS marking						
			ISI marked	ISI marked	M/R			

MID

·.	First-Aid Hose Reels	N/A	N/A	N/A				
	 Total numbers on each floor 	N/A N/A	N/A	N/A				
	 Length of hose reel hose 	N/A	N/A	N/A				
	Nozzle diameter		1071					
7.	Automatic fire detection and alarming system							
•	Type of detectors	N/A		N/A N/A				
	 Location of Main Panel 	N/A	N/A	N/A				
	 Location of Repeater Panel 	N/A	N/A	N/A N/A				
	Alternate source of power	N/A	N/A	N/A				
	Hooters' Location	N/A	N/A N/A	N/A				
	MOEFA	N/A	N/A N/A	N/A				
	Public Address System	N/A	14/71					
10.	Automatic Sprinkler System	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	Ground Floor Swinkler shows false ceiling	N/A	N/A	N/A				
	Sprinkler above false ceiling Internal Hydrants	14/11						
1.	тпегнаі пунтаніз		1	NI/A				
	Size of riser/down-comer	N/A	N/A	N/A N/A				
	 Number of hydrants per floor 	N/A	N/A	N/A N/A				
	Hose Box	N/A	N/A	IN/A				
2.	Yard Hydrants							
	Total number of hydrants	N/A	N/A	N/A				
	•	N/A	N/A	N/A				
	Hose Box Provide A programents	1471						
3.	Pumping Arrangements							
	Ground Level	21/4	N/A	N/A				
	Discharge of main Pump	N/A		N/A				
	> Head of Main pump	N/A	N/A					
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A				
	Jockey Pump out putJockey pump head	N/A	N/A	N/A				
	Standby Pump out put	N/A	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A				
	Auto Starting/Manual Stopping	N/A	N/A	N/A				
			N/A	N/A				
		N/A N/A	N/A N/A	N/A				
	Pump House Access	IN/A	1WA	14/12				
	Terrace level	N/A	N/A	N/A				
	Discharge of pump		N/A	N/A				
	> Head of the pump	N/A N/A	N/A N/A	N/A				
	> Power Supply		N/A N/A	N/A				
	> Auto Starting of pump	N/A	IN/A	INIA				
	Captive Water Storage for fire fighting							
•	 Underground tank capacity 	N/A	N/A	N/A				
	> Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	N/A	N/A	N/A				
	Access to tank	N/A	N/A	N/A				
	Overhead Tank capacity		N/A	N/A				
	,	N/A	N/A	N/A				
		N/A	IN/A	17/7				



16.	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	(No Lift) N/A			
	 Pressurization of Lift lobby Communication In lift Car 	N/A	N/A	N/A			
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
17.	Standby power supply	N/A	N/A	N/A			
18.	Refuge Area.						
	➤ Total Area ➤ Location	N/A	N/A	N/A			
		N/A	N/A	N/A			
19.	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch PanelPA System Panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2018/SZ/2150 Dated 19/09/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

31/2/22

1 /2-8/

Et hetter

put up of

up for

, soznakno place RCci

Maroler A

M.S. W

Sypor.