GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001**

No. F6/DFS/MS/School/2022/NDZ/ 350

DELHI (-47
PLACE

Dated: 31 | 03 | 2022

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Secondary School located at Welcome Colony, Delhi-110053, comprised of ground plus three upper floors (two separate blocks) & ground plus one upper floor, owned/occupied by Girls Secondary School was issued FSC vide letter No.-F6/DFS/MS/School/2017/1866 dated 27/12/17 (G+3) & F6/DFS/MS/School/2019/2355 dated 20/12/19 (G+1). The school building was re-inspected by the officer concerned of this department on 07/03/2022 in the presence of Mr. Inderjeet Kumar Jain, Estate Officer of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from 31/03/2017 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 31/03/2024 at New Delhi by

(Dr. S. K. Tomar) Dv. Chief Fire Officer

K 10ml 3113122

To.

The Principal,

Govt. Girls Secondary School located Welcome Colony,

Delhi-110053

Copy:-

The Dy. Director of Education,

B-Block, Yamuna Vihar, Delhi-110053

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.njc.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form T [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : Govt. Girls Sec. School, Welcome Colony,

Building is comprised of Delhi-110053

: G+3 Two Separate Blocks (New Building)

& G+1 floor (old Building block) 3. Type of Occupancy

: Educational 4. Type of Case : Renewal

5. Details of Previous NOC letter : F.6/DFS/MS/School/2017/1866 dt 27/12/17 (G+3)

F.6/DFS/MS/School/2019/2355 dt 20/12/19 (G+1) 6. Fire Safety directive letter No. : NBC Part - IV & DoE Circular 01/03/2011

7. Date of Inspection : 07/03/2022

8. Name of the Inspecting officers : ADO (Shd) 9. Name and designation of Officer

from the building side : Mr. Inderjeet Kumar Jain, Estate Officer 10. Year of Construction

: 1998 & 2017 11. Applicant's letter No : GGSS/WC/2021/76 Dated- 08/12/2021

Sr.	Minimum Standards on Fire	NBC Part IV	Provided at Site	Remarks			
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMI			
01	Access to Building						
	 Road width 	06m	06m	MR			
	 Gate width 	4.50 m	4.50 m	MR			
	 Width of internal road 	N/A	N/A	N/A			
02	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	• Upper floor (G+3)	02 nos.	02 nos.	MR			
	,	01 in each	01 in each block				
		block					
	• Upper floor (G+1)	01 no.	02 nos.	MR			
	 Basement 	N/A	N/A	N/A			
	B. Width of Staircases						
	• Upper floor (G+3)	1.50 mtr	1.82 mtr	MR			
	• Upper floor (G+1)	1.50 mtr	1.60 mtr & 1.13 mtr	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of Exits						
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of Continuous Staircases to	01 no. in each	01 no. in each block	MR			
	Terrace	block					
	e. Width of Corridor	1.50 mtr in	1.76 mtr (G+3)	MR			
	c. width of Collidor	each block	1.50 mtr (G+1)				
	f. Door Size	01m	1.08 mtr & 01 mtr	MR			
03	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers	N/A	N/A	N/A			
04	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	24 nos.	28 nos.	MR			
	• Types	ABC /CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			

	F13						
06	First-Aid-Hose Reels.						
	Total numbers on each floor • Length of hose reel hose	01 no. in each block	01 in each block	MR			
	Nozzle diameter	30 m	30 m	MR			
	Nozzie diameter	05 mm	05 mm	MR			
)7	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
)9	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	·	NI/A	N/A	N/A			
	Basement	N/A	N/A N/A	N/A			
	• upper floor	N/A	N/A N/A	N/A			
1 1	• sprinkler above false ceiling Internal Hydrants	N/A	IN/A	14/21			
- 1	•	N/A	N/A	N/A			
	size of riser/down-comer Number of hydrents per floor	N/A N/A	N/A N/A	N/A			
	Number of hydrants per floorHose box	N/A	N/A N/A	N/A			
12	Yard Hydrants.	IV/A	IVI	. 1/ 4 1			
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.	1 1/7 1					
	Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	 Number of main pumps 	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	Pump house access	N/A	N/A	N/A			
	➤ Terrace Level (G+3)						
	Discharge of pump	450 lpm each block	450 lpm each block	MR			
	Head of the pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
	•						
1	Continu Water Co. C. S.						
4	Captive Water Storage for Fire Fighting.						
	 Underground tank capacity 	N/A	N/A	N/A			
	 Draw-off connection 	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	 Access to tank 	N/A	N/A	N/A			
	• Overhead tank capacity (G+3)	10,000 ltrs each block	10,000 ltrs each block	MR			
	Exit Signage.		CIUCK				

kir 98

d

re

o. 55 is

> er ar

16	Provision of Lifts.					
	Pressurization of lift shaftPressurization of lift lobby	N/A	N/A	N/A		
	 Communication in lift car Firemen's grounding switch 	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Lift signage	N/A	N/A	N/A		
7	Standby Power S.	N/A	N/A	N/A		
8	Standby Power Supply Refuge Area.	N/A	N/A	N/A		
9	Total areaLocationFire Control Room	N/A N/A	N/A N/A	N/A N/A		
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	 PA system panel 	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
30	Building floor plans	N/A	N/A	N/A		
0	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rule. The FSC issued vide letter No. F.6/DFS/MS/School/2017/1866 dated 27/12/17 (G+3) & F.6/DFS/MS/School/2019/2355 dated 20/12/19 (G+1) renewal under rule 37 of the Delhi Fire Service Rule, 2010 is recommended.

Signature of the Inspecting Officer
Name :- Deepak Kumar
Designation :- A.D.O (Shd)

DO(FD)

(1) Inspection was carried out on

7/3/2022 but put up on today.

Why?

(2) Speak about point No-6

Ato 1 shop.

Sir, my Computed was not working properly. And printer also. In future case will dealt timely submitted pl.

DO(EN). 1103/2021

Jule 21/03/2022

D. T-0.