

FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE [See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2022/NDZ/357

Dated: 04 / 04 /2022

FIRE SAFETY CERTIFICATE

Certified that the Lovely Public Senior Sec. School located at Priyadarshini Vihar Near bank Enclave, Delhi-110092, comprised of Ground + 3 Upper Floors & a separate multipurpose hall cum sports court on ground floor owned / occupied by Lovely Public Senior Sec. School has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/School/2019/NDZ/172 dated 23/01/2019. The premises was re-inspected by the officer concerned of Fire Service on 30.03.2022 in the presence of Dr. Bhawana Malik (Principal) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class "Educational" (Group-B) with effect from \(\frac{\text{OU}}{\text{OU}} \) \(\frac{\text{OU}}{\text{2022}} \) for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on OY 104 12022 at New Delhi by.

(Dr. S.K. TOMAR)

DY. CHIEF FIRE OFFICER.

of Alb

Copy to :-

1. The Principal, Lovely Public Senior Sec. School, Priyadarshini Vihar Near bank Enclave, Delhi-110092.

2. The Director of Education (Land & Estate), Lucknow Road, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape / entry / exit shall be kept free from any obstruction.

- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire fighting system.

- 5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
- 6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Lovely Public Senior Sec. School, Priyadarshini Vihar Near bank Enclave, Delhi-110092.

: Educational

 Type of Occupancy
 Building Comprised of : Ground + 3 upper floors & a separate multipurpose

hall cum sports court on ground floor.

: Renewal

5. Details of previous NOC No. F6/DFS/MS/School/2019/NDZ/172 dated 23/01/2019

6. Fire Safety directives Letter No.: NBC (Part-IV) 7. Date of inspection : 30/03/2022 8. Name of the Inspecting Officer : D.O. (East) : 30/03/2022

9. Name and designation of Officer

: Dr. Bhawana Malik (Principal) from the building side

: 1966 10. Year of Construction

10. \	ear of Construction	: 1966	n@gmail.com.da	ited 24/03/22		
	Year of Construction Applicant's letter received through	Requirements	Provided at	Remarks		
S	Minimum standards on fire	As per NBC	site	MR/NMR		
No		As per NBC	Site			
	U/R 33					
1.	Access of building	6 m	20 m	MR		
	Road width	4.5 m	7m	MR		
	• Gate width		NA	NA		
	• Width of internal road	NA Cavita	IVA	107		
2	Number, width, Type & Arrangements of exits					
	a. Number of staircases	2	3	MR		
	• Upper floors	3	NA NA	NA		
	• Basements	NA	NA	IVA		
	Width of stuircases		1.50	NAD.		
	 Upper floors 	1.50 m	1.50 m each	MR		
	 Basements 	NA	NA	NA		
	Protection of exits					
	 Lire check door 	NA	NA	NA		
	• Pressurization	NA	NA	NA		
	b. No of continuous	2	2	MR		
	staircase to terrace					
	e. Wildth Of Corridor	1.50 m	1.5 m	MR		
	d. Door Size	1.0 m (Class Room)	Provided	MR		
		1.50 m (Hall)	1.50 m x 7	MR		
3	Con rous antation					
	 ide check door 	NA	NA	NA		
	Scaling of electrical	NA	NA	NA		
	in its					
	Rating of shaft	NA	NA	NA		
	Grant Contract of the Contract			1.07		
	4 Ler Curtain	NA	NA	NA		
		NA	NA	-		
1.	Smalte a augements System		140	NA		
	ments	NA	NA			
- 1	* grer floors	NA		NA		
	Fire "x" nishers	IVA	NA	NA		
-	* . al numbers	1.1				
		1-4	20	MR		
	: Tymes	ABC /Co ₂	Provided	MR		
	- Degarking	181 Marked	Provided	MR		



D

			R) 10	
6. F	irst - Aid Hose Reels	-		MR
	 Total numbers on each floor 	2	2	
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR
	Nozzle diameter	5 mm	5 mm	MR
7.	Automatic fire detection and al	arming system		NA
	 Type of detector 	NA	NA	NA NA
	 Location of Main Panel 	NA	NA	NA NA
	 Location of Repeater Panel 	NA	NA	
	• Alternate source of	NA	NA	NA NA
	Hooters' Location	NA	NA	NA NA
8.	MOEFA	NA	Provided	NA NA
9.	Public Address System	NA	Provided	IVA
10.	Automatic Sprinkler System		NI A	NA
	 Basements 	NA	NA	NA NA
	 Upper Floor 	NA	NA	NA NA
	Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	• Size of riser/down-	NA	100 mm	NA
	Number of hydrants per floor	NA	02 no.	NA
	Hose Box	NA	02 no.	NA
12.	Yard Hydrants			110
	 Total number of hydrants 	NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements			
	 Ground Level 		1	NIA
	 Discharge of main pump 	NA	NA	NA NA
	Head of main pump	NA	NA	NA NA
	 Number of main pumps 	NA	NA	NA NA
	 Jockey pump out put 	NA	NA NA	NA NA
	Jockey pump head	NA	NA	NA NA
	Standby Pump out put	NA NA	NA NA	NA NA
	Standby Pump HeadAuto Staring/Manual	NA NA	NA	NA NA
	stopping	107		
	 Pump House Access 	NA	NA	NA
	 Terrace level 			1
	Discharge of pump	900 LPM	900 LPM	MR
	Head of the pump	40 MH	40 MH	MR
	Power supply	Required	Provided	MR
	Auto starting of pump	Required	Provided	MR
1	4. Captive water Storage for fir	re fighting		
	Under ground tank capacity	NA	NA .	NA
	 Draw of connection 	NA	NA	NA
	Fire service inlet	NA	NA	NA
Ì	Access to tank	NA	NA	NA
	 Overhead Tank capacity 	10,000 Ltrs	10,000 Ltrs.	MR
		38	8	

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts		rrovided	IVIIX
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of lift lobby	NA	NA	NA
	Communication in lift Car	NA	NA	NA
	Fireman's Grounding Switch	NA	NA	NA
	Lift Signage	NA	NA	NA
17.	Standby power supply	NA	NA	NA
18.	Refuge Area			
	Total area	NA	NA	NA
	Location	NA	NA	NA NA
19.	Fire control room			
	Detector system panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20.	Special Fire Protection	NA	NA	NA
	Systems for Protection of			,
	special Risks, if any;			

Note:- General requirements for schools as per Director of Education circular dated 01/03/2011 / NBC (Part-IV)

- Escape route- Clear
- 2. LPG cylinders in laboratories :- Nil
- 3. Electric wiring:- Conduit Wiring MCB and ELCB..... Electric circuit :- MCB Provided
- 4. Electric meter board / switch board panel .:- Not Under the staircase
- 5. Basement use as per BBL 1983 :- N/A
- 6. Emergency telephone no. board :- Displayed
- 7. Generator set: :- at the terrace

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/School/2019/NDZ/172 dated 23/01/2019 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer : Ashok Kumar Jaiswal

Designation: Divisional Officer (East)

F.T. is added for symattine please.