

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F.6/DFS/MS/School/2022/SZ/440

Dated: 22/04/2022

FIRE SAFETY CERTIFICATE

Certified that the Govt. Co-ed. Sarvodaya Vidyalaya, Dichaon Kalan, New, New Delhi-110043, comprised of four blocks namely A & B block is having ground plus three upper floors, and C & D block is having ground plus one upper floor, owned/occupied by Govt. Co-ed. department vide Sarvodaya this Vidyalaya issued FSC by was F.6/DFS/MS/School/2017/SZ/1334 dated 08/09/2017. The school was re-inspected by the officer concerned of this department on 06/04/2022 in the presence of Sh. Harkesh (HOS). The school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of Delhi Fire Service Rules 2010 and found that the building is fit for occupancy "Educational Building" with effect from . 22/04. 2022 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on $\frac{22}{04}\frac{1}{2022}$ at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

3

d

ıe

n

in

or

Copy to:-

 The Principal, Govt. Co-ed. Sarvodaya Vidyalaya, Dichaon Kalan, New Delhi-110043

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Govt. Co- ed. Sarvodaya Vidyalaya, Dichaon Kalan, New Delhi-110043

Building comprised of 4 blocks (A & B block having G+3, C &D Blocks having G+1)

3. Type of Occupancy Educational 4. Type of Case5. Details of Previous NOC Renewal

F.6/DFS/MS/School/2017/SZ/1334 dated 08.09.17

06/04/2022

6. Fire Safety directives letter No
7. Date of inspection
8. Name of Inspecting Officer A.D.O. R.K.yadav

9. Name and designation of officers

From the building side Sh. Harkesh (HOS) 10. Year of Construction 2013-14 & 2017

11. Applicant's letter No. Outdoor diary no. 7142 dated 08/03/2022

. No.	Minimum	Standards on fire prevention and	d NBC/BBL	Provided at	Remarks				
	fire safety	U/R 33	requirements	site	MR/NMR				
	Access to	building							
	• R	oad width	Accessible 06 m	06 m	M/R				
	• G	ate width	4.5 m	5.8 m	MR				
	• W	idth of internal road	N/A	N/A	N/A				
•	Number, Width, Type & Arrangement of Exits								
	a. Numbe	er of staircases							
	• 1	Upper Floors	02 No.'s in Λ & C-blk & 01 no in B & D-blk	Provided	M/R				
	•]	Basements	N/A	N/A	N/A				
	b. Width	of staircases							
	•	Upper Floor	2X1.7 m in A-blk	2X1.7 m in A-b	lk M/R				
			1X1.7 m in B-blk	1X1.7 m in B-b					
			2x1.6 in C-blk	2x1.6 in C-blk					
	•	Basements	1X1.5 M in D blk	1X1.5 M in D b					
			N/A	N/A	N/A				
		tion of exits							
	1	Fire check door	N/A	N/A	N/A				
	•	Pressurization	N/A	N/A	N/A				
	d Na	of continuous staircases to							
	d. No. o	of continuous staircases to	Required	Provided	M/R				
		h of Corridor		1.70/1.5 m					
	e. widt	ii oi comuoi	1.50 m	1.70/1.3 m	M/R				
	f. Door	Size	1.0 m	1.02/1.15/1.12 n	n M/R				
3.	Compar	tmentation							
		Fire check door	N/A	N/A	N/A				
		Sealing of electrical shafts	N/A	N/A	N/A				
		Fire Rating of shaft door	N/A	N/A	N/A				
	1	Water Curtain	N/A	N/A	N/A				
	•	Fire Dampers	N/A	N/A	N/A				
4.	Smoke	Management System	1						
		Basements	N/A	N/A	N/A				
	•	Upper floors	Required	Natural ventilatio	m M/R				
5.	Fire Ex	tinguishers			145				
		Total numbers	32 Nos.	Provided	M/R				
	1 1	Types	ABC/CO ₂ type	Provided	M/R				
		IS marking	ISI marked	Provided	M/R				

	No. of the Park						
١.	First-Aid Hose Reels Total numbers on each floor	Two in A blk &	Provided	M/R			
	Length of hose reel hose	One in B blk	Provided	M/R			
	Nozzle diameter	30 m 5 mm	Provided	M/R			
	Automatic fire detection and alarming system	1 3 111111 1					
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A		N/A			
	Location of Repeater Panel	N/A					
	Alternate source of power	N/A		N/A			
	Hooters Location	N/A		N/A N/A			
	MOEFA	N/A		N/A			
	Public Address System	N/A		N/A			
	Automatic Sprinkler System	17/73	19/71	19/71			
	Basement	N/A	N/A	N/A			
	 Ground Floor 	N/A		N/A			
	 Sprinkler above false ceiling 	N/A		N/A			
	Internal Hydrants			//1			
	 Size of riser/down-comer 	100 mm	Provided	M/R			
	 Number of hydrants per floor 	2 Nos.	2 Nos.	M/R			
	Hose Box	2 Nos.	2 Nos.	M/R			
2.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
•	Hose Box	N/A	N/A	N/A			
3.	Pumping Arrangements		Provided Provided N/A N/A N/A N/A N/A N/A N/A N/A N/A N/				
13.	• Ground Level						
	Discharge of main PumpHead of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A		N/A			
	➤ Auto Starting/Manual Stopping	N/A					
		N/A		N/A			
	➤ Pump House Access	N/A		N/A			
	Terrace level		17/7	N/A			
	Discharge of pump	450 LPM in A & B block	Provided	M/R			
	Head of the pump	30 m	Provided	M/R			
	Power Supply	Required		M/R			
	Auto Starting of pump	Required	Provided	M/R			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	NI/A			
	Draw-off connection	N/A		N/A			
	Fire service inlet	N/A		N/A			
	> Access to tank	N/A		N/A			
	Overhead Tank capacity	10000 ltrs in A		N/A			
5.	Exit Signage.	& B block		M/R			
	БВ	Required	Provided	M/R			

06

M/Diti		MO LI	No Lift		
Marwision of Lifts. Pressurization of Lift Shaft	N/A	N/A	N/A		
Pressurization of Lift lobby	N/A	N/A	N/A		
• Communication In lift Car	N/A	N/A	N/A		
 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
• Lift Signage	N/A	N/A	N/A		
Standby power supply	N/A	N/A	N/A		
Standby power supply					
Refuge Area.					
Total Area	N/A	N/A	N/A		
> Location	N/A	N/A	N/A		
	1N/ /A	1 1// 1			
. Fire Control Room					
	21/4	N/A	N/A		
Detector System Panel	N/A	N/A	N/A		
Flow Switch Panel	N/A		N/A		
PA System Panel Pattern healtyp	N/A	N/A	N/A		
Battery backupBuilding Floor Plans	N/A	N/A			
Dunding 1 tool 1 talls	N/A	N/A	N/A		
). Special Fire Protection System for Protection of	N/A	N/A	N/A		

 d_{e_d}

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings was issued vide letter no. F.6/DFS/MS/School/2020/SZ/587 dated25/08/2020 has been complied.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter no.F.6/DFS/MS/School/2017/SZ/1334 dated 08/09/2017 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer 20.

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Syclopson

AMULT

Thelter a put up for sign