

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/ 2022/SZ/ () () 3

Dated:

25/04/2022

FIRE SAFETY CERTIFICATE

Certified that the **Janak Puri Club**, Plot No. 17, Janak Puri District Centre Complex, Janak Puri, New Delhi-110058 comprised of Two Basements, Ground Plus three upper Floors (2nd Basement is sealed). The first basement is used as parking, ground floor having reception, dining halls, kitchen, bar & offices, first floor having party hall, kitchen, card room, carom room, second floor having halls and third floor having 07 guest rooms owned/occupied by Janak Puri Club was issued FSC by this department vide letter no. F.6/DFS/MS/2019/SZ/897 dated 26/04/2019. The Club building was re-inspected by the officers concerned of this department on 20/04/2022 in the presence of Sh. Om Prakash (General Secretary) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules 2010 and that the building/ premises (**Except second basement**) is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed under.

Issued on 25) 64/2-22 at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER DELHI FIRE SERVICE

9015

Copy to:-

The Manager, Janak Puri Club, Plot No. 17, Janak Puri District Centre Complex, Janak Puri, New Delhi-110058

Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 10. In case of usage of second basement the FSC will be null and void.

	N 0	INSPECTIO address of the building: Janak Puri Cl	lub, Plot No17, Jana	k Puri District Cer	itre Complex,			
	1. Name &	Janak Puft, F	New Denn-110036					
	2. Building	comprised of : Two baseme scaled with	nts, ground plus three brick wall.	upper floors but s	second baseme	ent is		
		(1)°	Assembly Building.					
		occupancy						
		£ Previous NOC : 1.6/DFS/M	IS/2019/SZ/897 dated					
	5. Details o	sty directives letter No : F6/MS/DFS	01.03.2006					
	6. Fire Safety directives letter No : F6/MS/DFS/BP/2006/513 dated 01.03.2006 7. Date of inspection : 20/04/2022							
	8. Name of	Inspecting Officer : D.O Vedpa	l Chhikara & A.D.O.	R.K.Yadav				
	9. Name ar	nd designation of officers						
	From the	e building side : Sh. Om Pri	akash (General Secret	ary)				
	10. Year of	Construction : 2006-2013						
	11 Applica	nt's letter No. : ID No. 202	22040405516 dated 04					
	Minimum St	andards on fire prevention and fire	NBC/BBL	Provided at	Remarks MR/NMR			
).	safety U/R 3	3	Requirements	site	WIR/INIVIN			
	Access to bu		12	Provideo	1 1	M/R		
		l width	12 m 05 m	Provided		M/R		
		width	05 m N/A	N/A		N/A		
		th of internal road	IN/A	14/1				
	Number, W	idth, Type & Arrangement of Exits						
	a. Number		GF to FF 04 no.'s &	& Provideo	d	M/R		
	• Up	per Floors	FF to SF 03 no.'s & SF to TF 02 no.'s	k	,	****		
	• Ba	sements	Basement to GF 0- no.'s & ramp		d b	M/R		
	b. Width of	staircases		GF to FF 2.35, 1	50 (03	M/R		
	• U	oper Floor	1.50 m	no.'s), FF to SF no.'s) & SF to TI 1.22 m	1.50 (03	VI/ IX		
		sements	1.50 m	1.50 (04 no.'s)	& ramp	M/R		
	c. Protection	on of exits re check door			, , ,	1 / D		
		ressurization	Required	Provide		M/R		
	· F	essurization	N/A	N/A		N/A		
	d. No. of	continuous staircases to						
	terrace		Required	Provide		M/R		
		of Corridor	1.50 m	2.70m	. 1	M/R		
	f. Door	Size	1.50 m in hall (0 no.'s)& 2.0 m restaurant		m in	M/R		
3.	Compart	mentation						
	_ F	ire check door	Required	Provide	ed	M/R		
		caling of electrical shafts	Required	Provide	ed	M/R		
		ire Rating of shaft door	N/A	N/A		N/A		
		Vater Curtain				N/A		
	• F	ire Dampers	N/A N/A	N/A N/A	to the common process of the common party of t	N/A		
4.	Smoke N	lanagement System	19//4	19/71		1.471		
				1.1	Comp	M/D		
	• 1	3asements	Required	Exhaust Provid	led	M/R		
	• (Opper floors	Required	Provid	ed	M/R		
5.	Fire Ext	inguishers						
3.		The second control of the second seco	25 no.'s	Provid	led	M/R		
J.		Total numbers	25 HO. 8	110110				
J.	1	Fotal numbers Types	W/CO ₂ / CO ₂ typ ISI marke	e Provid	and the same of th	M/R		

1740

	First-Aid Hose Reels				
			Provided	M/R	
	Total numbers on each floor	Two	Provided	M/R	
	 Length of hose reel hose 	30 m	Provided	M/R	
	Nozzle diameter	5 mm	Provided	111/1	
	Automatic fire detection and alarming system Provided Provided				
	 Type of detectors 	Required		M/R M/R	
	 Location of Main Panel 	Required	Ground Floor		
	 Location of Repeater Panel 	Required	First Floor	M/R	
	Alternate source of power	Required	Provided	M/R	
	Hooters' Location	Required	At Exits	M/R	
	MOEFA	Required	Provided	M/R	
	Public Address System	Required	provided	MR	
	Automatic Sprinkler System			M/R	
	• Basement	Required	Provided	M/R	
	Ground Floor	Required	Provided	N/A	
	Sprinkler above false ceiling	N/A	N/A	IN/A	
	Internal Hydrants			1 4/D	
	Size of riser/down-comer	Required	Provided	M/R M/R	
	 Number of hydrants per floor 	Two GF, FF & SF/One TF	Provided	VI/ K	
	 Hose Box 	Required	Provided	M/R	
	Yard Hydrants	Required			
•	Total number of hydrants	Seven	Provided	M/R	
	Hose Box	Seven	Provided	M/R	
3.	Pumping Arrangements				
	Ground Level	2200 1 704	Duranidad	M/R	
	Discharge of main Pump	2280 LPM	Provided	M/R	
	Head of Main pumpNumber of main pumps	60 mtrs.	Provided		
	> Jockey Pump out put	One	Provided	M/R	
	> Jockey pump head	Required	Provided	M/R	
	Standby Pump out put	60 mtrs.	Provided	M/R	
	Standby Pump Head	2280 LPM	Provided	M/R	
	> Auto Starting/Manual Stopping	60 mtrs.	Provided	M/R	
		Required	Provided	M/R	
	➤ Pump House Access	Required	Provided	M/R	
	 Pump House Access Terrace level 		Provided	M/R	
	Discharge of pump	900 LPM	Provided	M/R	
	> Head of the pump	40 mtrs.	Provided	M/R	
	> Power Supply	Required	Provided	M/R	
	> Auto Starting of pump	Required	Provided	M/R	
4.	Captive Water Storage for fire fighting				
	Underground tank capacity	50000 Ltrs	Provided	M/R	
	> Draw-off connection	Required	Provided	M/R	
	Fire service inlet	Required	Provided	M/R	
	> Access to tank	Required	Provided	M/R	
	 Overhead Tank capacity 	10,000 Ltrs.	Provided.	M/R	
		Required	Provided	M/R	
15.	Exit Signage.	1		IVI/IC	

Ja

W

	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		Required	Provided	M/R			
		Required	Provided	M/R			
S	tandby power supply	Required	Provided	M/R			
	Refuge Area.						
	> Total Area	N/Λ	N/A	N/A			
	> Location	N/A	N/A	N/A			
I	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued vide letter no. F6/DFS/MS/2022/SZ/607 Dated 16/03/2022 has been complied.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/2019/SZ/897 dated 26/04/2019 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Office

: R. K. Yadav Name Designation: ADO (JKP)

Signature of the Inspecting Officer : Vedpal Chhikara

Designation: DO (South West)

Dy. C.F.O (South