

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/School/2022/SZ/

Dated 95, 4,2022

FIRE SAFETY CERTIFICATE

Certified that Rao Bir Singh Public School located at Gali No 2, Near Oberoi Farm, Vill. Kapashera, New Delhi 110037 comprised of Ground plus two upper floors owned/occupied by Rao Singh Public School, **FSC** was issued by this department F6/DFS/MS/School/2019/SZ/532 dated 14/03/2019. The premises was re-inspected by officer concerned of this department on 09/04/2022 in presence of Mr. Sudha Vats (Manager) and observed that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class "Educational Building" Group-B, with effect from the 35/4/2022 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 25 4 2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER

Copy to: -

 The Manager, Rao Bir Singh Public School, Gali No 2, Near Oberoi Farm, Vill. Kapashera, New Delhi 110037

2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.



	INSPECTION	ON REPORT	(3-12-20-days) Alextin Alextin and Alextin de Carlos and Alextin and Alextin de Carlos a	tioner phase than will be recover a remarket shall be	
1	Name & Address of the Building	Rao Bir Singh Public School, Gali No 2, Near Oberoi			
		Farm, Vill. Kapashera, New Delhi 110037			
2	Type of Occupancy	Educational, Group-B (School)			
3	Building Comprised of	Ground plus Two upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	The second secon	ool/2019/SZ/532 dated 1-	THE RESERVE OF THE PARTY OF THE	
7	Fire Safety Directives Letter No Date of Inspection		Safety/2011/3298 to 3398 dat	cd 01.03.2011	
8	Name of the Inspecting Officers	09-04-2022	a ADO (DCD)		
9	Name & Designation of Officers	Sh. Rajesh Kumar ADO (BCP)			
	from the building side	Mr. Sudha Vats (Manager)			
10	Year of construction	2006 - 2011			
11	Applicant letter No.	Gmail of dated 2	5-03-2022		
S. No.	Minimum standards on Fire Prevention	As per old	Provided at Site	Remarks	
	and Fire Safety U/R 33	NOC	Trovided at Site	MR/NMR	
1	Access to Building.				
	Road width	06m	06 mtr	MR	
	Gate width	4.5m	Provided	NMR	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of ex				
	a) Number of Staircase			or an executive of the control of the	
	Upper floors.	02 No	Provided	MR	
	Basement floor.	-NA-	-NA-	-NA-	
	b) Width of Staircase				
	Upper floors	1.5m / 0.75m	1.30m & 1.25 mtr	MR	
	> Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits				
	> Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	One	Provided	MR	
	e) Width of corridor	1.50 m	Provided	MR	
	f) Door size	1m	Provided	MR	
3	Compartmentation.	11	Tiovida	IVIX	
	Fire check door.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.		. 17.1	1 -11/1-	
	Basement	30 ACPH	Exhaust fan provided	MR	
	Upper floors	12 ACPH		-	
		12 ACFT	-NA-	-NA-	
5.	Fire Extinguishers.	OCN	10.37		
	Total numbers	06 Nos	10 Nos	MR	
	• Types	ABC / CO2	ABC & Co2	MR	
	ISI Marking	ISI mark	Provided	MR	
6.	First Aid Hose Reels.	0.0.1.1			
	Total numbers on each floor.	02 Nos	Provided	MR	
	 Length of hose-reel hose. 	30m	Provided	MR	
	Name Diameter	5mm	Provided	MR	
	Nozzle Diameter	Jiiiii			
7	Automatic fire detection & alarming system.	Jilli	Tiovided	WIK	

NIB

	Location of Main Panel			
		-NA-	-NA-	-NA-
	Bootaton of Repeater Panel	-NA-	-NA-	-NA-
	internate source of power	-NA-	-NA-	-NA-
8.	Hooter's location MOEFA	-NA-	-NA-	-NA-
9.		-NA-	Provided	-NA-
10.	Public Address System	-NA-	NA	-NA-
10.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
•••	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.			1471
	 Size of Riser/Down-comer 	-NA-	-NA-	-NA-
	 Number of Hydrant per floor 	-NA-	-NA-	-NA-
	 Hose box. 	-NA-	-NA-	-NA-
12.	Yard Hydrants.		1471	-NA-
	 Total number of hydrants. 	-NA-	-NA-	NIA
	Hose box.	-NA-		-NA-
13.	Pumping arrangements.	-11/7-	-NA-	-NA-
	Ground Level			-
	Discharge of main pump.	NIA T		-
	 Head of main pump. 	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping		-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level	-NA-	-NA-	-NA-
	Discharge of pump.	450 LPM	D	
	Head of pump.		Provided	MR
	Power supply.	40m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.	-NA-	314	
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	10, 000 ltrs	-NA-	-NA-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	-NA-	NIA	1
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.		-NA-	-NA-
17.	Standby Power Supply	-NA-	-NA-	-NA-
18.	Refuge Area	-NA-	-NA-	-NA-
10.				
	Total area	-NA-	-NA-	-NA-
	 Location 	-NA-	-NA-	-NA-

19.	Fire Control Room.			
	 Detector system panel. Flow switch panel. PA system panel. 	-NA-		
		-NA-	-NA-	-NA-
			-NA-	-NA-
	Batton: best	-NA-	-NA-	
	Battery backup. Building floor plan.	-NA-	-NA-	-NA-
20		-NA-		-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.		-NA-	-NA-
		-NA-	-NA-	-NA-

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/School/2019/SZ/532 dated 14/03/2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (SD)