

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2022/ 460

Dated: 26/4/2022

FIRE SAFETY CERTIFICATE

Certified that the building of Sarvodaya Kanya Vidyalaya No.-1, C-Block, Janakpuri, New Delhi-110058, having four blocks namely A block comprised of ground plus two upper floors & B, C and D blocks is comprised of ground plus one upper floor only, owned/occupied by Sarvodaya Kanya Vidyalaya No.-1 was issued fire safety certificate by this department vide letter no. F6/DFS/MS/School/2015/SZ/1436 dated 07.08.2015. The school building was inspected by the officer concerned of this department on 20/04/2022 in the presence of Sh. Rajesh Kumar Gill (Estate Manager) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class 'Educational' w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as Junder.

Issued on_#New Delhi.

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. The Principal, Sarvodaya Kanya Vidyalaya No.-1, C-Block, Janakpuri, New Delhi-110058.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

INSPECTION REPORT Name & address of the building: Building comprised of Sarvodaya Kanya Vidyalaya No.-1, C-Block, Janakpuri, New Delhi-4 blocks, Block-A (G+2) & Block-B, C & D (G+1) 3. Type of Occupancy Type of Case Educational 5. Details of Previous NOC Renewal 6. Fire Safety directives letter No F6/DFS/MS/School/2015/SZ/1436 dated 07.08.2015 (G+II Block) Date of inspection N/A8. Name of Inspecting Officer 20/04/2022 9. Name and designation of officers A.D.O.R.K. Yadav From the building side 10. Year of Construction Sh. Rajesh Kumar Gill (Estate Manager) 11. Applicant's letter No. 1974-75 (G+II Block) & Before 2018 Block-B, C & D S. No. Minimum Standards on fire prevention and SKV/No.1/C/BLK/JP/EM/2022/65 dated 25/02/2022 fire safety U/R 33 NBC/ Dt. of edu. Provided at site Remarks Access to building Requirement MR/NMR Road width Accessible 06 mtrs. Gate width Provided MR Provided MR. 4.5 mtrs Width of internal road 2. Number, Width, Type & Arrangement of Exits N/A N/A N/A a. Number of staircases Upper Floors 02 No's in Blk-A, 04 No's in Blk-Λ, 02 MR 02 no.'s in Blk-B no. in Blk-B, 03 no.'s 03 no.'s in Blk-C in Blk-C & 02 no. in Basements 02 no.'s in Blk-D Blk D N/A b. Width of staircases N/A N/A 1.5M/additional Upper Floor 1.50 (02 no. 's) & 1.30 (02 staircase of .75M if M/R no.'s) in Blk-A & 1.4 M & less than 1.5 M & 1.5M in Blk-B, 3X 1.5 M in Basements Blk-C &2X1.5 M in Blk D 1.5 M N/A N/A N/A Protection of exits Fire check door N/A N/A N/A Pressurization N/Λ N/A N/A d. No. of continuous staircases to Required terrace Two MR 1.50 M Width of Corridor 2.40/1.5 M M/R Door Size 1.0/1.20 M .96 & 1.0 M in Blk-A. M/R .90 & 1.2 M in Blk-B.C & D 3. Compartmentation (double door) Fire check door N/A N/A Sealing of electrical shafts N/A Fire Rating of shaft door N/A N/Λ N/Λ Water Curtain N/A N/A Fire Dampers N/A N/A N/A N/A N/A 4. N/A Smoke Management System N/A Basements N/A N/A Upper floors N/A Required Natural M/Rventilation 5. Fire Extinguishers Total numbers 34 no's Provided Types ABC/CO₂ type M/RIS marking Provided M/R ISI marked Provided M/R

to Appl

i.	First-Aid Hose Reels	Aller I		
	 Total numbers on each floor in block A 	Two	Provided	M/R
	 Length of hose reel hose 	30 mtrs	Provided	M/R
	Nozzle diameter	5 mm	Provided	M/R
	Automatic fire detection and alarming system	The second of th	anni de participato de la companio por la companio de la companio de la companio de la companio de la companio	
	 Type of detectors 	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
3.	MOEFA	N/A	N/A	N/A
),	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System		1	
	Basement	N/A	N/A	N/A
	 Ground Floor 	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants	1,	1	1
	Size of riser/down-comer	N/A	100 mm	M/R
	 Number of hydrants per floor 	N/A	Two	M/R
	Hose Box	N/A	Two	M/R
12.	Yard Hydrants	-	1	
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements		1	1
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	-
	Standby Pump out put	N/A		N/A
	Standby Pump Head		N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	2X450 LPM	Provided	M/R
	Head of the pump	30 mtrs	Provided	M/R
	Power Supply	Required	Provided	M/R
	Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	
	Draw-off connection	N/A		N/A
	Fire service inlet		N/A	N/A
	Access to tank	N/A	Provided	N/A
	 Overhead Tank capacity 	N/A	N/A	N/A
15.	E.4 C:	10000 ltrs	Provided	M/R
ıJ,	Exit Signage.	Required	Provided	M/R



16.	Provision of Lifts.	The second secon	All the second leaves of the second leaves and the second leaves are second leaves are second leaves and the second leaves are				
	(No Lift)						
	Pressurization of Lift ShaftPressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
_		N/A	N/A	N/A			
7.	Standby power supply	N/A	N/A	N/A			
8.	Refuge Area.						
	> Total Area	21/4					
	► Location	N/A	N/A	N/A			
		N/A	N/A	N/A			
9.	Fire Control Room						
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection. The shortcomings was issued vide letter no.F6/DFS/MS/School/2018/SZ/2920 dated 06/07/2018 has been complied.

In view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2015/SZ/1436 dated 07.08.2015 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer 4/2022

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

D.O. (South West)

Julia p Fit

AW (SUB)

FT heller is put up for high please

Dycro(sp)

A.

284/202

(Sarvodaya Kanya Vidyalaya No.-1, C-Block, Janakpuri, New Delhi-110058)