



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2022/ 204

Dated: 99 04 2022

## FIRE SAFETY CERTIFICATE

Certified that the Standard Hotel located at 17, Netaji Subhash Marg, Daryaganj, New Delhi comprised of Ground + Mezzanine + 03 upper floors, Ground floor (reception), Mezzanine floor (other office), 1st floor (11 guest rooms), 2nd floor (06 guest rooms), 3rd floor (05 guest rooms + 01 store room + staff kitchen + 01 staff room), total 22 guest rooms owned/occupied by Standard Hotel was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2018/1490 dated 25.06.2018. Now, the premise was re-inspected by the officer concerned of this department on 14.04.2022 in presence of Sh. S.K Singh (Manager) and found that the said guest house building having Ground floor (reception), Mezzanine floor (other office), 1st floor (11 guest rooms), 2nd floor (05 guest rooms + 01 staff room), 3rd floornot in use as per undertaking dated 14.04.2022. A total of 16 guest rooms has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, Ground floor (reception), Mezzanine floor (other office), 1st floor (11 guest rooms), 2<sup>nd</sup> floor (05 guest rooms), 3<sup>rd</sup> floor- not in use as per undertaking dated 1,4.04.2022. A total of 16 guest rooms only up to 2<sup>nd</sup> floor only with effect from .....22 04 2022 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of Delhi Fire Service Rules 2010, printed below. 

211412

(Dr. S.K. Tomar)
Dy. Chief Fire Officer

Tel: 011-23412025

## Copy to:-

- The Joint Commissioner of Police (Licensing), 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi. w.r. to Online application I.D.2022032604229 dated 26.03.2022
- 2. The Licensee, M/s Standard Hotel at 17, Netaji Subash Marg, Daryaganj, New Delhi. Conditions for the validity of Fire Safety Certificate:-
- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (1) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

			INSI	PECTION REPORT		- I G Marri		
1	Name & address of the building  M/s Standard Guest House, situated at 17, N.S Ma  Darya Ganj, Delhi.					7, N.S Mar		
2	Buil	ding	is comprised of	Ground + Mezzanine + 03 upper floors Ground floor - reception Mezzanine floor - other office  1st floor - 11 guest rooms  2nd floor - 05 guest rooms  3rd floor - not in use (Affidavit attached) Terrace - Tower + Generator + water tank				
3	Тур	e of (	Occupancy	Residential Group A-1				
4	Type	e of (	Case	Renewal		2010		
5	Details of Previous FSC			F6/DFS/MS/GH/NDZ/20	18/1490 dated 25.06.	2018		
6	Fire Safety direction letter No  Date of Inspection			Nil				
7				14.04.2022				
8	Name of the Inspecting Officers			Sumit Kumar ADO (SPM				
9	Name of the designation of Officer from the building side			Mr. Satish (Manager)				
10	Yea	r of C	Construction	1940				
11	Applicant's letter No			Online application I.D.2022032604229 dated 26.03.2022				
S.N				Requirement/ Existing fire safety arrangements	Provided at Site	Remarks MR/NMR		
				arrangements				
1			to building oad width	NA (Spl.area)	06 mtrs.	NA		
	a	1	ate width	NA (Spi.arca)	NA	NA		
	c		idth of internal road	NA	NA	NA		
2	Nı	ımbe	er, Width, Type and Arranger	nent of Exits				
	A		Number of staircases			T		
	1	a	Upper floor	01 nos.	01 nos.	MR		
		b	Basement	NA.	NA	NA		
	В	1	Width of staircases					
		a	Upper floor	1.18 mtr.	1.18 mtrs.	MR		
	_	b	Basement	NA	NA	NA		
	C	Pr a	otection of exits Fire check door	(Required as per GN dated 27.05.2019)	Provided	MR		
		b	Pressurization	NA	NA	NA		
	D			01 nos.	01 nos.	MR		
	D	E Width of corridor		NA	NA	NA		
	F		or size	0.94 mtr.	0.94 mtr.	MR		
i		_	rtmentation	0.74 mu.	0.74 mu.	IVIK		
	a	Fire	check door	NA	NA	214		
	b		ling of electrical shafts	NA	NA NA	NA NA		
	С			NA	NA	NA NA		
	d		ter curtain	NA	NA	NA NA		
	e Fire dampers			NA	NA	NA NA		
l	Sm		Management System.			14/7		
	a	Bas	ement	NA	NA	137:		
	b			Natural/Ventilated	Natural	NA		
					· · · · · · · · · · · · · · · · · · ·	MR		

	Fire	Ext	inguisher					
	a	Total	numbers	15 nos.	16 nos.	MR		
	b	Type	S	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR		
	c	ISI n	narking	Required	ISI marked			
			l-Hose Reels.	Required	Required ISI marked MR			
	a	a Total numbers of each floor		01 nos.	01 nos, each at 1st &2 <sup>nd</sup> floor	MR		
	b	Len	gth of hose reel hose	30 mtr.	30 mtr.	MR		
	c	Noz	zle diameter	5 mm	5 mm	MR		
7	Au	tom	atic fire detection and alarming sy	ystem.				
	a	a Type of detectors		CO detectors (required as per GN dated 27.05.2019)	Provided	MR		
	b		ocation of main panel	At ground floor	Provided	MR		
	c		ocation of repeater panel	NA	NA	NA		
	d		lternate source of power	NA	NA	NA		
	e	_	ooters	NA	NA	NA		
8	M	OEF	<sup>C</sup> A	NA	Provided	NA		
9			address System.	Required	Provided	MR		
10	A	uton	natic Sprinkler System.		- London			
	a	ba	sement	NA	NA	NA		
	b	up	per floor	NA	NA	NA		
	c	Sp	rinkler above false ceiling	NA	NA	NA		
11		Internal Hydrants						
	a	siz	e of riser/down-comer	NA	Provided	NA		
	b		umber of hydrants per floor	NA	Provided	NA		
	c		ose Box	NA	Provided	NA		
12		Yard Hydrants.			1.0.1000			
12	-		·	NA	NA	NA		
	a	_	otal number of hydrants					
	b		ose Box	NA	NA	NA		
13	F	ump	oing Arrangements.					
	A	4	Ground Level					
		a	0 1	NA	NA	NA		
		b	Head of Main Pump	NA	NA	NA		
		С	Number of main pumps	NA	NA	NA		
		d	Jockey pump out put	NA	NA	NA		
		e	Jockey pump head	NA	NA	NA		
		f		NA	NA	NA		
		9		NA	NA	NA		
		h	<u> </u>		NA	NA		
		i		NA	NA	NA		
		В	Terrace Level					
	-		Discharge of pump	450 LPM	Provided	MR		
				30 mtr.	Provided	MR		
			Head of the Pump	Jo ma.				
		-	c Power supply	Required	Provided	MR		

-	Captive Water Storage for Fire F	ighting.		NA
-4-1	Last 1 amound tank canacity	NΛ	NΛ	
- 11	60	NΛ	NA	NA NA
	Tank to the last	NΛ	NA	NA NA
		NA	NΛ	MR
		2,500 ltrs	25,00 ltrs	MR
5	e Overhead Tank capacity  Exit Signage.	Required	Provided	IVIK
6	Provision of Lifts.			
0	Clift Chaft	NA	NA	NA NA
	C1'01-11-	NA	NA	NA
	i lift cor	NA	NA	NA NA
	c Communication in lift car	NA	NA	
	d Firemen's grounding switch	NΛ	NA	NA
	e Lift Signage	Required	Provided	MR
17	Standby power supply			
18	Refuge Area.		N.A	N.A
	a Total area	N.A	N.A	N.A
	b Location	N.A	IV.A	
19	Fire Control Room		NA	NA
	a Detector system panel	NA	NA NA	NA
	b Flow switch panel	NA	NA NA	NA
	c PA system panel	NA	NA NA	NA
	d Battery backup	NA	NA NA	NA
	e Building Floor Plans	NA Sanagial	NA NA	NA
20	Special Fire Protection system	147.		
	Risks, if any:			

The fire protection systems provided in the building were tested, checked at random and found not functional at the time of inspection.

If agreed and in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1490 dated 25.06.2018 is recommended to be renewed up to 2<sup>nd</sup> floor only under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Sumit Kumar

Designation ADO (SPM)

F.T. letter is Put up for Signature, Please