

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/NDZ/2022/ 214

Dated: 02/05/2022

FIRE SAFETY CERTIFICATE

Certified that the Arjun Guest House located at 5084, Main Bazar, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (shops + reception), 1st floor (04 guest rooms), 2nd floor (06 guest rooms + 02 store) and 3rd floor (06 guest room), total 16 guest rooms owned/occupied by Arjun Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/68 dated 08/01/19. Now, The premises was re-inspected by the officer concerned of this department on 25/04/22 in the presence of Sh. Vijay (Manager) and found that the said guest house building, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor -reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms) and 3rd, floor (06 guest room), total 15 guest rooms up to third floor only, with effect from . 02 05 22 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ... 02. 05. Do? Lat New Delhi by.

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2022040405501 dated 05.04.2022.
- 3. The Manager, Arjun Guest House 5084, Main Bazar, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry. 9. Any flammable material for interior decoration shall strictly be prohibited.

NAME CHON BLOODS

INSPECTION REPORT

Name & address of the building:- Arjun Guest House at 5084, Main Bazar,

Type of occupancy:- Pahar Ganj, New Delhi Residential, Sub Division

Residential, Sub Division-A-1 Gr. + 03 Upper floors (total 15 Guest rooms)

Circumd floor (shops + reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms + 02 store) and 3rd

3. Type of case:- Renewal

3. Type of case:4. Details of previous FSC:Renewal
No.F6/DFS/MS/GH/NDZ/2019/68 dated

08/01/19.

5. Fire safety directives No. 6. Date of inspection: N/A
 25/04/22

Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Sh. Vijay (Manager)

Year of construction:-

1997

10. Applicant's letter No:- Online id no. 2022040405501 dated 05.04.2022.

S.No.	Minimum Standards on fire	Requirement	Provided at site	Old Case Remarks			
		Existing fire	riovided in site	MR/NMR			
	U/R 33	safety		Morning			
	Access to Building	arrangements					
••	The state of the s	NV.	0.5				
	2) Gate width	N/A	06 mtr.	MR			
	, , , , , , , , , , , , , , , , , , , ,	N/A	N/A	N/A			
,	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arrangement of Exits A. Number of staircases						
	Number of staircases Upper floors	01.31					
	2. Basements	01 Nos. N/A	01 Nos.	MR			
	B. Width of staircase	IN/A	N/A	N/A			
	1. Upper floors	0.80 mtr.	0.97 mtr.	1			
	opper moore	o.oo mu.	0.97 mu.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits			IVA			
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	N/A	N/A	N/A			
	staircase to terrace		\	TWA.			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	1 mtr.	1 mtr,	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts		N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System	LIMA	IN/A				
	1) Basements	30 ACPH	N/A	121/4			
	2) Upper floors	12 a/c per	Exhaust fan	N/A			
	-, -, -, -, -, -, -, -, -, -, -, -, -, -	hour	Exhaust ran	MR			
5.	Fire Extinguishers	lioui					
-	1) Total numbers	00 1					
	2) Types	08 Nos.	08 Nos.	MR			
_	2) 1) 100	ABC & C	O2 ABC & C	O2 MR			

_		1						
	3) ISI marking	Required	Provided	MR				
6.	First-Aid Hose Reel							
	1) Total number of eachfloo	or 01	01	MR				
	2) Length of hose reel hose	30 m	30 m	MR				
	3) Nozzle diameter	05 mm	05 mm	MR				
7.	Automatic Fire Detection & Alarming System							
	1) Type of detectors CO	Required	Provided	MR				
	2) Location of main panel	Required	Provided	MR				
	3) Location of repeater pane	1 N/A	N/A	N/A				
	4) Alternate source of power	Required	Provided	MR				
	5) Hooter's Location	Required	Provided	MR				
8.	MOEFA	N/A	N/A	N/A				
9.	Public Address System	N/A	N/A	N/A				
10.	Automatic Sprinkler System		1111	1771				
	1) Basement	N/A	N/A	N/A				
	2) Upper floors	N/A	N/A	N/A				
	3) Sprinkler above false	N/A	N/A	N/A				
	ceiling		1772	1111				
11.	Internal Hydrants							
	1) Size of riser/down-comer	N/A	N/A	N/A				
	2) Number of hydrants per	N/A	N/A	N/A				
	floor		13/71	1 VA				
	3) Hose box	N/A	N/A	N/A				
12.	Yard Hydrants		1771	17/1				
	1) Total number of hydrants	N/A	N/A	N/A				
	2) Hose box	N/A	N/A	N/A				
13.	Pumping Arrangement		1 11/11	IVA				
	Ground level	N/A	N/A	N/A				
	 a) Discharge of main 	N/A	N/A	N/A				
	pump	1,,,,,	IV/A	IN/A				
	b) Head of main pump	N/A	N/A	N/A				
	c) Number of main	N/A	N/A	N/A				
	p um p		13/74	IN/A				
	 d) Jockey pump out put 	N/A	N/A	N/A				
	e) Jockey pump head	N/A	N/A	N/A N/A				
	f) Stand by pump	N/A	N/A	N/A N/A				
	output		- " - "	14/14				
	g) Stand by pump head	N/A	N/A	N/A				
	h) Auto starting/Manual	N/A	N/A	N/A N/A				
	stopping			IN/A				
	2) Terrace level							
	a) Discharge of pump	180 LPM	180 LPM	MD				
	b) Head of pump	30 mtr	30 mtr	MR				
	c) Power supply	Required	Provided	MR				
	d) Auto starting of	Required	Provided	MR				
	pump	required	Frovided	MR				
4.	Captive Water Storage for Fire Fighting							
		V/A	NI/A					
	capacity	V/A	N/A	N/A				
		N/A	21/4					
	connection	N/A	N/A	N/A				
	1	J/A	21/4					
	-) The service fillet	V/A	N/A	N/A				

	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft	N/A	N/A	N/A
	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	 c) PA system panel 	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	NA		

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/68 dated 08/01/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only,

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)

182 294,22 2-1-22 29/4/22 Dycfo (462)

1 23/4/2x

ADOCCO

As a porto pro

sut up for new Peru

exercitors

150mg

nojn