(186

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/School/2022/SZ/4-08

Dated: 12 04/2022

FIRE SAFETY CERTIFICATE

Certified that the Birla Vidya Niketan School (Higher Secondary School) located at Pushp Vihar, Sector-IV, New Delhi-110017, comprised of basement, ground plus three upper floors owned/occupied by Birla Academy of Art and Culture was issued FSC by this department vide letter No. F.6/MS/DFS/School/2019/SZ/736 dated 05-04-2019. The premises was re-inspected by officer concerned by this department on 29/03/2020 in the presence of Mr. C.L. Mishra (Manager-Admin) of the school and observed that the school premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" Group-B (School) as above with effect from 120.14. 2022 for period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of conditions mentioned below.

Issued 12 04 /2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

(

- 1. Mr. C.L. Mishra (Manager-Admin) Birla Vidya Niketan, Pushp Vihar-IV, New Delhi-17
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition
 at all time as seen during inspection. Any loss of life property due to non-functional fire safety
 measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	INSPECTIO	N REPOR	r		the second flower had believed reputing	
1	Name & Address of the Building	Birla Vidya Niketan School (Higher Secondary				
		School), Pushp Vihar, Sector-IV, New Delhi-17				
2	Type of Occupancy	Educational, Group B (School)				
3	Building Comprised of	Basement, Ground + 03 upper floors				
4	Type of Case	Renewal				
5	Details of Previous NOC	F 6/MS/DFS/School/2019/SZ/736 dated 05-04-2019				
0	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2013/13 dated 21/03/2013				
7	Date of Inspection	29-03-2022				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)				
0	Name & Designation of Officers	Mr. C.L. Mishra (Manager-Admin)				
	from the building side					
10	Year of construction	2015				
11	Applicant letter No.	Gmail of dated 21-03-2022				
S. No.	Minimum standards on Fire Prevention	Requirements		Provided at Site	Remarks	
	and Fire Safety U/R 33				MR/NMR	
1	Access to Building.					
	Road width	9 mtr		12 mtr	MR	
	Gate width	6 mtr		Provided	MR	
	Width of internal road	6 mtr		Provided	MR	
2	Number, width, type & arrangement of ex	its.				
	a) Number of Staircase					
	Upper floors.	05 Nos		Provided	MR	
	Bäsement floor.	03 Nos		Provided	MR	
	b) Width of Staircase					
	➤ Upper floors	GF to		m, 1.50m, 1.50m, 1.50 & 1.40m 2 nd Floor- 2m (Canteen Block)		
	➢ Basement floor	1.5m	1	.52m, 1.50m & 1.50m	MR	
	c) Protection of exits	1		ter en californi più con casa di la segli di segli esterno ancia a ci di acceso e segli e		
	Fire check door	Required -NA-		Provided	MR	
	> Pressurization			-NA-	-NA-	
	d) No. of continuous staircase to terrace	Require		01 No	MR	
	e) Width of corridor	-NA-		-NA-	-NA-	
	f) Door size	lm		Provided	MR	
3	Compartmentation.	1		Trovided	IVIIC	
	Fire check door.	Required		Provided	MR	
	Sealing of electrical shafts.	Required		Provided	MR	
	Fire rating of shaft door.	-NA-		-NA-	-NA-	
	Water curtain	-NA-	CONTRACTOR CONTRACTOR STREET	-NA-	-NA-	
	Fire dampers.	-NA-		-NA-	-NA-	
4	Smoke Management system.	-UA-		-14/7-	-INA-	
•	Basement	30 ACI	DIT	Provided exhaust fan	MD	
				and the state of t	-	
	• Upper floors	12 ACI	ΥН	Natural Ventilation	MR	
5	Fire Extinguishers.					
	Total numbers			40 Nos	MR	
	Types	ISI marked		ABC & CO2	MR	
	 ISI Marking 			Provided	MR	
6	First Aid Hose Reels.		Office was to be made a contract.			
	The second secon		And the second	BF-03, UF-04 Nos	MR	
	Total numbers on each floor.	1				
	 Total numbers on each floor. Length of hose-reel hose. 	Hose-r	eel	30m each	MR	

Birla Vidya Niketan School (Higher Secondary School), Pushp Vihar, Sector-IV, New Delhi



	Total area	-NA-	-NA-	-NA-
18	Refuge Area	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided (DG set)	MR
	Lift signage.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Communication in lift car.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
16	Provision of Lifts.			
15	Exit Signage.	Required	Provided	MR
	Overhead tank capacity.	25,000 Ltr	25,000 Ltr	MR
	Access to tank.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
•	Underground tank capacity.	-NA-	-NA-	-NA-
14	Captive water storage for fire fighting.			
	Auto starting of pump.	Required	Provided	MR
	Power supply.	Required	Provided	MR
	Head of pump.	40m	40m	MR
	> Discharge of pump.	1620 LPM	1620 LPM	MR
	Terrace Level			1
	Pump house access.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	 Head of main pump. 	-NA-	-NA-	-NA-
	Discharge of main pump.	-NA-	-NA-	-NA-
	Ground Level			
13	Pumping arrangements.	-1418-	-11/1-	-1 N A
	Hose box.	-NA-	-NA-	-NA
	Total number of hydrants.	-NA-	-NA-	-NA
12	Yard Hydrants.			1.21
	Hose box.	04 Nos	Provided	MR
	 Number of Hydrant per floor 	04 Nos	Provided	MR
	Size of Riser/Down-comer	150 mm	Provided	MR
11	Internal Hydrants.			
	Sprinkler above false ceiling	-NA-	-NA-	-NA
	Upper floors	-NA-	-NA-	-NA
	Basement	Required	Provided	MR
10	Automatic Sprinkler System			
9	Public Address System	Required	Provided	MF
8	MOEFA	Required	Provided	MF
	Hooter's location	Every floor	Provided	MF
	 Alternate source of power 	Required	Provided	MF
	 Location of Repeater Panel 	-NA-	-NA-	-NA
	 Location of Main Panel 	Required	Smoke type Ground floor	MF
	 Type of detectors 	Required	Smoke time	1 1

Birla Vidya Niketan School (Higher Secondary School), Pushp Vihar, Sector-IV, New Delhi

19.	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	 Battery backup. 	-NA-	-NA-	-NA-
•	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-NA

The Fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/MS/DFS/School/2019/SZ/736 dated 05-04-2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

approved, f.t. fettel et forting

Design: ADO (BCP)