

FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI


No.F6/DFS/MS/SZ/2021/ 124

Dated: 6/7/21

FIRE SAFETY CERTIFICATE

Certified that the M/s One Eight (A Unit of Silver-view Café Pvt. Ltd.) located at GF-05 & 101, Worldmark-2, Aerocity, IGI Airport, New Delhi-110037, comprised of 3 Basements, Mezzanine, Ground & Six Upper Floors. But restaurant is at Ground Floor & 1st Floor only owned / occupied by A Unit of Silver-view Café Pvt. Ltd., was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2018/SZ/2215 dated 01/10/18. The premises was re-inspected by the officer concerned of this department on 30/06/2021 in the presence of Sh. Nitin Kumar (GM) and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class "Assembly" Group-D (Restaurant) with effect from 6/7/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on6/7/21..... at New Delhi by.


(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (S.Z.).

Copy to:-

1. DHO, South MCD, Public Health Department, Najafgarh Zone, Dhansa Stand, Najafgarh, New Delhi-110043.
2. Joint Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi-110049.
3. Sh. Vartik Tihara, M/s One Eight (A Unit of Silver-view Café Pvt. Ltd.) located at GF-05 & 101, Worldmark-2, Aerocity, IGI Airport, New Delhi-110037.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape / entry / exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
3. Any loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of fire fighting system.
5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.
9. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010.

INSPECTION REPORT

Covered area of the restaurant is 111m² and as per NBC (Part-IV) the no. of occupants comes out to be Approx. 62 (111/1.8=61.66). Thus capacity of restaurant is 62 persons which is covered under DFS Act 2007, Rules 2010. Subsequently inspection of Eating House is carried out as per NBC (Part-IV).

1. Name & address of the building: **M/s One Eight (A Unit of Silver-view Café Pvt. Ltd.) at GF-05 & 101, Worldmark-2, Aerocity, IGI Airport, New Delhi-110037.**
2. Type of Occupancy : **Assembly (Group-D) (Eating House) (3 Basement, Mezzanine, Ground & Six Upper Floors. But restaurant is at ground floor & 1st floor only.**
3. Type of Case : **Renewal**
4. Details of pervious NOC : **F6/DFS/MS/EH/2018/SZ/2215 dated 01/10/18 (For EH) & Workmark-2 (Asset No.8) FSC No. F6/DFS/MS/Mixed/SZ/2020/533 dated 21/12/2020)**
5. Fire Safety directives Letter No. : **Nil**
6. Date of inspection : **30/06/2021**
7. Name of the Inspecting Officer : **A.D.O. (S.J.)**
8. Name and designation of Officer from the building side : **Sh. Nitin Kumar (GM)**
9. Year of Construction : **2014**
10. Applicant's letter : **MHA Id-2021042513180 dated 27/12/2020**

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements BBL / NBC	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	Restt within	As above	MR
	• Gate width	workmark-2 Aerocity	As above	NA
	• Width of internal road		As above	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	Provided & Maintained by Bldg. Mgmt.		
	• Upper floors	2	As above	MR
	• Basements	NA	As above	NA
	b. Width of staircases	Provided & Maintained by Bldg. Mgmt.		
	• Upper floors	1.5mtr	As above	MR
	• Basements	NA	As above	NA
	c. Protection of exits	Provided & Maintained by Bldg. Mgmt.		
	• Fire check door	NA	As above	NA
	• Pressurization	NA	As above	NA
	d. No of continuous staircase to terrace	Required	As above	MR
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	2 exit	2m & 1.5m	MR
3.	Compartmentation	Provided & Maintained by Bldg. Mgmt.		
	• Fire check door	NA	As above	MR
	• Sealing of electrical shafts	NA	As above	MR
	• Fire Rating of shaft door	NA	As above	MR
	• Water Curtain	NA	As above	NA
	• Fire Dampers	NA	As above	NA
4.	Smoke managements System	Provided & Maintained by Bldg. Mgmt.		
	• Basements	30 a/c per hour	N/A	NA
	• Upper floors	12 a/c per hour	Exhaust fans Provided	MR
5.	Fire Extinguishers	Provided & Maintained by Bldg. Mgmt.		
	• Total numbers	6	Provided	M/R
	• Types	ABC / CO ₂	ABC & CO ₂	M/R
	• ISI marking	Required	Provided	M/R

Alg

First - Aid Hose Reels		Provided & Maintained by Bldg. Mgmt.		
• Total numbers on each floor	One	As above	MR	
• Length of hose reel hose	30 Mtr.	As above	MR	
• Nozzle diameter	5 mm	As above	MR	
7. Automatic fire detection and alarming system (Provided & Maintained by Bldg. Mgmt.)				
• Type of detector	N/A	As above	N/A	
• Location of Main Panel	N/A	As above	N/A	
• Location of Repeater Panel	N/A	As above	N/A	
• Alternate source of power	NA	As above	NA	
• Hooters' Location	NA	As above	NA	
8. MOEFA	Required	As above	MR	
9. Public Address System	NA	As above	NA	
10. Automatic Sprinkler System (Provided & Maintained by Bldg. Mgmt.)				
• Basements	NA	As above	NA	
• Upper Floor	NA	As above	NA	
• Sprinkler above false ceiling	NA	As above	NA	
11. Internal Hydrants (Provided & Maintained by Bldg. Mgmt.)				
• Size of riser/down-comer	NA	As above	NA	
• Number of hydrants per floor	NA	As above	NA	
• Hose Box	NA	As above	NA	
12. Yard Hydrants (Provided & Maintained by Bldg. Mgmt.)				
• Total number of hydrants	NA	As above	NA	
• Hose Box	NA	As above	NA	
13. Pumping Arrangements (Provided & Maintained by Bldg. Mgmt.)				
• Ground Level				
➤ Discharge of main pump	NA	2280LPM	NA	
➤ Head of main pump	NA	105m	NA	
➤ Number of main pumps	NA	Two	NA	
➤ Jockey pump out put	NA	2 x 180 LPM	NA	
➤ Jockey pump head	NA	105m	NA	
➤ Standby Pump out put	NA	2280 LPM	NA	
➤ Standby Pump Head	NA	105m	NA	
➤ Auto Starting/Manual stopping	NA	Provided	NA	
➤ Pump House Access	NA	Provided	NA	
• Terrace level				
➤ Discharge of pump	450 LPM	As above	MR	
➤ Head of the pump	40 Mtr	As above	MR	
➤ Power supply	Required	As above	MR	
➤ Auto starting of pump	Required	As above	MR	
14. Captive water Storage for fire fighting (Provided & Maintained by Bldg. Mgmt.)				
• Underground tank capacity	NA	1,00,000 ltr	NA	
➤ Draw of connection	NA	As above	NA	
➤ Fire service inlet	NA	As above	NA	
➤ Access to tank	NA	As above	NA	
• Overhead Tank capacity	10,000 ltr	20,000 ltr	MR	

N/A

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	(Provided & Maintained by Bldg. Mgmt.)		
	➤ Pressurization of Lift Shaft	N/A	As above	N/A
	➤ Pressurization of lift lobby	N/A	As above	N/A
	➤ Communication in lift Car	N/A	As above	N/A
	➤ Fireman's Grounding Switch	N/A	As above	N/A
	➤ Lift Signage	N/A	As above	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area	(Provided & Maintained by Bldg. Mgmt.)		
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room	(Provided & Maintained by Bldg. Mgmt.)		
	➤ Detector system panel	N/A	As above	N/A
	➤ Flow Switch Panel	N/A	As above	N/A
	➤ PA System Panel	N/A	As above	N/A
	➤ Battery backup	N/A	As above	N/A
	➤ Building Floor Plans	N/A	As above	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	As above	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2018/SZ/2215 dated 01/10/18 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Ashok Kumar Jaiswal
27/12/2021

Signature of the Inspecting Officer
Name : Ashok Kumar Jaiswal
Designation : A.D.O. (S.J.)

Recd. on
05/07

D O (S.J.)

*Recd. on
05/07*

Defo (S.J.)

F.T. please.

A D O (S.J.)

F.T. is put up for signature please

Ashok Kumar Jaiswal

04/07/20

[Signature]

M.S. cell