

C/82

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/School/2022/SZ/ 309

Dated: 23/03/2022

FIRE SAFETY CERTIFICATE

Certified that **Birla Vidya Niketan School (Primary Block)** located at **Pushp Vihar, Sec-IV, New Delhi-110017** comprised of basement, ground + 03 upper floors was issued Fire Safety Certificate by this department vide letter no. F6/MS/DFS/School/2018/2526 Dated 24-11-2018. The premises was re-inspected by officer concerned by this department on 17/03/2022 in the presence of Mr. C. L Misra (Estate Manager) of the school and observed that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class **"Educational"** Group-B (School) as above with effect from 23/03/2022 for period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of conditions mentioned below.

Issued 23/03/2022 at New Delhi by


(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. The Principal, Birla Vidya Niketan School (Pry Block), Pushp Vihar, Sec-IV, New Delhi-17
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054


Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT

1	Name & Address of the Building	Birla Vidya Niketan School (Primary Block) Pushp Vihar, Sector-IV, New Delhi-110017		
2	Type of Occupancy	Educational, Group -B (School)		
3	Building Comprised of	Basement, Ground + 03 upper floors.		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/MS/DFS/School/2018/2526 Dated 24-11-2018		
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2013/13 Dated 21-03-2013		
7	Date of Inspection	17-03-2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. C.L. Mishra (Estate Manager)		
10	Year of construction	2015		
11	Applicant letter No.	Gmail of dated 22-11-2021		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR
1.	Access to Building.			
	• Road width	06 mtr	12 mtr	MR
	• Gate width	4.5 mtr	6 mtr	MR
	• Width of internal road	6 mtr	Provided	MR
2.	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	05 Nos	Provided	MR
	➤ Basement floor.	03 Nos	Provided	MR
	b) Width of Staircase			
	➤ Upper floors	1.50 mtr	1.5m x 4 nos. & 1.25m x 1 no. (Iron)	MR
	➤ Basement floor	1.50 mtr	1.5m each	MR
	c) Protection of exits			
	➤ Fire check door	Required	Provided	MR
	➤ Pressurization	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	Required	03 Nos	MR
	e) Width of corridor	1.5m	Provided	MR
	f) Door size	1m	Provided	MR
3.	Compartmentation.			
	• Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	-NA-	-NA-	-NA-
	• Water curtain	-NA-	-NA-	-NA-
	• Fire dampers.	-NA-	-NA-	-NA-
4.	Smoke Management system.			
	• Basement	30 ACPH	Exhaust fan provided	MR
	• Upper floors	12 ACPH	Natural Ventilation	MR
5.	Fire Extinguishers.			
	• Total numbers	Required	40 Nos	MR
	• Types	ABC / CO2	ABC & CO2	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	BF-03 & UF-04	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR

Birla Vidya Niketan School (Primary Block) at Pushp Vihar, Sector-IV, New Delhi

19.	Fire Control Room.			
	• Detector system panel.	-NA-	-NA-	-NA-
	• Flow switch panel	-NA-	-NA-	-NA-
	• PA system panel.	-NA-	-NA-	-NA-
	• Battery backup.	-NA-	-NA-	-NA-
	• Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-NA-
The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.				
Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/MS/DFS/School/2018/2526 Dated 24-11-2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.				
Accordingly DEA is put up for approval and signature please.				
<p style="text-align: right;">  Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP) </p>				

~~DO (SD)~~

AD
21/03/22


DeFO(SD)




ADO (BCP)

As approved, F.S. letter is put up for your signature pl

AD
23/3

DeFO(SD)




M.S. Cell
