MUDD GASTES



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/2022/Bnqt/NDZ/ワッツ

Dated: 10/05/2022

## FIRE SAFETY CERTIFICATE

Certified that the Assembly Building at Plot No 5, Community Center, Yamuna Vihar, Delhi-110053, comprised of basement, ground plus two upper floors only(Second floor having Three rooms), owned/occupied by M/s Indore Infracon Pvt. Ltd. was issued FSC vide letter No. F6/ DFS/MS/2019/NDZ/1046 dated 17/5/19. The premises was re-inspected by the officer concerned of this department on 18/04/2022 in the presence of Mr. Vivek Jain, Owner and found that the building have complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that building is fit for basement, ground plus two upper floors occupancy class 'Assembly Building' "Group-B" with effect from Indiana. For a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr. S.K Tomar) Dy.Chief Fire Officer

To,

Sh. Vivek Jain M/s Indore Infracon Pvt. Ltd Plot No 5, Community Center, Yamuna Vihar, Delhi-110053

MHA ID- 2022011000565 dated-12/1/22

Copy to,

Deputy Health Officer, Shahdara south zone, Karkardooma, East Delhi Municipal Corporation Delhi-32

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

Name & address of the building

Building is comprised of

Type of Occupancy 3.

4. Type of Case

5 Details of Previous NOC letter

6. Fire Safety directive letter No.

Date of Inspection

8. Name of the Inspecting officers

9 Name and designation of Officer from the building side

10. Year of Construction

11. Applicant's letter No

Assembly building at Plot No 5, Community

Center, Yamuna Vihar, Delhi-110053

Basement, Ground plus two upper floors (Second floor having Three Rooms)

Assembly Building

Renewal

: F6/ DFS/MS/2019/NDZ/1046 dated 17/5/19

: F6/DFS/MS/BP/2011/1935 dated 10/08/11

: 18/04/22

: D.O A.K Jaiswal & ADO Mehmood

: Mr. Vivek Jain

: 2011

: MHA Id- 2022011000565 dated 12/1/22

r. lo.	Minimum Standards on Fire	NBC/BBL	Provided at Site	Remarks				
1	Prevention and Fire Safety U/R33	Requirement		MR/NMR				
'	Access to Building MR/NMR							
	<ul> <li>Road width</li> </ul>	06 mtr.	07 mtr.	MR				
	<ul> <li>Gate width</li> </ul>	06 mtr.	06 mtr.	MR				
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A				
)2	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases							
	<ul> <li>Upper floor</li> </ul>	02 nos	02 nos	MR				
	<ul> <li>Basement</li> </ul>	02 nos	02 nos + 01 Ramp					
	B. Width of Staircases	52 1100	oz nos i o i Namp	MR				
	Upper floor	02 mtr & 1.50 mtr	02 mtr & 1.50 mtr	MR ·				
	Basement	02 mtr & 2.40 mtr	02 mtr & 2.40 mtr	MR /				
	c. Protection of Exits	2.40 1110						
	Fire check door	Required	Described					
	Pressurization	Required	Provided	MR				
	d. No. of Continuous Staircases to Terrace	02 no.	Provided 02 no.	MR MR				
	e. Width of Corridor	N/A	N/A	N/A				
	f. Door Size	02 mtr	02 mtr	MR				
03	Compartmentation.							
	Fire check door	Required	Provided	MR				
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Sealed	MR				
	<ul> <li>Fire rating of shaft door</li> </ul>	02 hrs	02 hrs	MR				
	<ul> <li>Water curtain</li> </ul>	N/A	N/A	N/A				
	Fire dampers	N/A	N/A	N/A				
04	Smoke Management System.							
	Basement	Required	Provided	145				
	Upper floor	Required	Provided	MR				
05.	Fire Extinguishers	required	Fiovided	MR				
	Total numbers	07 nos.	10 nos	MR				
	<ul> <li>Types</li> </ul>	ABC /CO <sub>2</sub>	ABC & CO2	MR				
	<ul> <li>IS marking</li> </ul>	ISI marked	Provided	MR				

Mille

06	First-Aid-Hose Reels.					
	Total numbers on each Branch	04				
	Congui of nose real hand	01 nos	01 nos	N		
07	TUZZIM MIDMOTO	30 mtr	30 mtr			
07	Automatic Fire Detection and At	05 mm	05 mm	N		
-	Automatic Fire Detection and Alarm	ning System.	00 111111	M		
	Type of detectors					
	Location of main popul	Heat & Smoke		M		
	Location of repeater name	Control room	Provided			
	Alternate source of power	Security roon	Provided	MI		
	boulde of power	Battery & DG	Provided	MI		
00	Hooter	Set		M		
80	MOEFA	staircase	Provided	MF		
09	Public Address System.	Required	Provided			
10	Automatical System.	Required	Provided	MF		
	Automatic Sprinkler System.	750	Provided	MR		
	Basement					
	• upper floor	Required	Provided			
	• Sprinkler above 6.4	Required		MR		
11	<ul> <li>sprinkler above false ceiling</li> <li>Internal Hydrants</li> </ul>	N/A	Provided	MR		
	The right and		N/A	N/A		
	size of riser/down-comer	100 mm				
	Number of hydrants per floor	01 nos.	100 mm	MR		
12			01 nos.	MR		
	Yard Hydrants.	01 nos.	01 nos.	MR		
	Total number of hydrants					
	1 IUSE DOV	02 nos	02 nos			
13	Pumping Arrangements.	02 nos	02 nos	MR		
			02 1103	MR		
	Ground Level					
	Discharge of main pump					
	Head of main pump	2850 lpm	2850 lpm			
	Number of main pumps	70 mtr	70 mtr	MR		
	Jockey pump out put	02 nos.	02 nos.	MR		
	Jockey pump head	180 lpm	190 1-	MR		
	Sump Pump	70 mtr	180 lpm	MR		
	Standby pump out put     Standby	Required	70 mtr Provided	MR		
	Standby pump head	2850 lpm	2850 lpm	MR		
	Auto starting /manual stopping     Pump bouse	70 mtr	70 mtr	MR		
	Pump house access     Toggethat the property of the prope	Required	Provided	MR		
	> Terrace Level	Required		MR		
ŀ			Provided	MR		
	Discharge of pump     Head of the	NIA				
	read of the numb	N/A	N/A			
	· Ower Supply	N/A	N/A	N/A		
4	, alo starting of pure.	N/A N/A	N/A	N/A		
.	Captive Water Storage for Fire Fighting.	14/74	N/A	N/A		
	<u> </u>			N/A		
	Cridel diolind table	50.000 ::				
		50,000 ltr	50,000 ltr			
	" " e service inlet	Required	Provided	MR		
	Access to tank     Overboad to tank	Required	Provided	MR		
5	Overhead tank capacity  Exit Signage	Required 10,000 ltr	Provided	MR		
	Exit Signage.		10,000 ltr	MR		
		Required	Provided	MR		



024

R	
$\sim$	
_	
_	
R	
_	
•	
$\sim$	
R	
-	
`	
~	
?	
•	
7	
3	
`	
≺ .	
`	
3	
_	
~	
`	

16	Provision of Lifts.						
	Pressurization of lift shaft	Required	Provided	MR			
	Pressurization of lift lobby	Required	Provided	MR			
	Communication in lift car	Required	Provided	MR			
	Firemen's grounding switch	Required	Provided	MR			
	Lift signage	Required	Provided	MR			
17	Standby Power Supply	Required	Provided	MR			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	<ul> <li>Location</li> </ul>	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	Required	Provided	MR			
	Flow switch panel	Required	Provided	MR			
	PA system panel	N/A	N/A	N/A			
	Battery backup	Required	Provided	MR			
	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to issue Fire Safety Certificate under the rule 35 of Delhi Fire Service, rules 2010.

Note:- Since the earlier FSC No. F6/DFS/MS/2016/NDZ/897 DATED. 01/03/2016 & F6/DFS/MS/2019/NDZ/1046 DATED:- 17/05/2019 was issued by our Fire Department Which is a clerical mistake as Commercial Building but now this building comprised of Basement, Ground plus Two upper floor is running a banquet hall and the classification of said buildings changed as NBC part-IV Group-D which is Classified as a Assembly Building.

If Approved we may issue fresh Fire safety Certificate.

Signature of the Inspecting Officer

Name

:- A.K Jaiswal

Designation

:- D.O (ED)

Signature of the Inspecting Officer

Name

:- Mehmood

Designation :- A.D.O (T.P)

- Hes per abon londs
The checked the his
The checked 1.5 and
There care ford 1.5 and
There care for his