

9/15

274

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No.F6/DFS/MS/School/SZ/2022/ 504

Dated: 11/05/2022

FIRE SAFETY CERTIFICATE (FSC)

Certified that the **Notre Dame School located at Badarpur Thermal Power Station Staff Colony, New Delhi-110044**, comprised of Ground + 02 upper floors was inspected by Assistant Divisional Officer (M. Road) from this department on 28.04.2022 in the presence of Mr, Sunil (Admin. Officer), and found that the school building has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and the building (Ground floor + 02 upper floors) is fit for occupancy of Group B "**Educational Building**" with effect from 11/05/2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 11/05/2022 at New Delhi by


(Atul Gang)

Director

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
2. The Principal, Notre Dame School located at Badarpur Thermal Power Station Staff Colony, New Delhi-44.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. This FSC is valid for School running at Ground + 2 upper floors only.

INSPECTION REPORT

1	Name & address of the building	Notre Dame School, Badarpur Thermal Power Station Staff Colony, Badarpur, New Delhi 110044.		
2	Building is comprised of	Ground + 02 upper floor		
3	Type of occupancy	Educational		
4	Type of case	New Case		
5	Details of previous FSC	Nil		
6	Fire safety direction letter no.	F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011.		
7	Date of inspection	28.04.2022		
8	Name of the inspecting officers	Rajesh Kumar Shukla ADO (M. Road)		
9	Name of the designation of officer from the building side	Mr. Sunil (Admin. Officer)		
10	Year of construction	1992		
11	Applicant's letter no.	Email dated 11.04.2022		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement as per DOE Circular dated 01.03.2011	Provided at site	Remarks MR/NMR
1	Access to Building:			
	A	Road width	6.0 mtrs.	6.0 mtrs. MR
	B	Gate width	NA	NA NA
	C	Width of internal road	NA	NA NA
2	Number, Width, Type and Arrangement of Exits:			
	A	Number of staircases		
	a	Upper floor	2 nos.	02 nos. MR
	b	Basement	NA	NA NA
	B	Width of staircases		
	a	Upper floor	1 staircase of 1.50 mtrs or if main staircase width is < 1.50 mtrs an additional staircase of 0.75 mtrs width is required.	1.36 meters & 1.43 to 1.55 meters. MR
	b	Basement	NA	NA NA
	C	Protection of exits		
	a	Fire check door	NA	NA NA
	b	Pressurization	NA	NA NA
	D	No. of continuous staircases to terrace	01 no.	01 no. MR
	E	Width of corridor	NA	NA NA
	F	Door size	1 mtrs. (class room)	1 mtrs. (class room) MR
3	Compartmentation:			
	A	Fire check door	NA	NA NA
	B	Sealing of electrical shafts	NA	NA NA
	C	Fire rating of shaft door	NA	NA NA
	D	Water curtain	NA	NA NA
	E	Fire dampers	NA	NA NA
4	Smoke Management System:			
	A	Basement	NA	NA NA
	B	Upper floor	NA	Natural NA

Notre Dame School, BTPS Colony, Badarpur, New Delhi - 44.

5.	Fire Extinguisher:				
	A	Total numbers	10 nos.	Provided	MR
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C	ISI marking	Required	Required	MR
6	First-aid-Hose Reel:				
	A	Total numbers of each floor	01 no.	Provided	MR
	B	Length of hose reel hose	30 mtrs.	Provided	MR
	C	Nozzle diameter	5 mm	Provided	MR
7	Automatic Fire Detection and Alarming System:				
	A	Type of detectors	NA	NA	NA
	B	Location of main panel	NA	NA	NA
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	NA	NA	NA
	E	Hooters	NA	NA	NA
8	MOEFA:		NA	NA	NA
9	Public Address System:		NA	NA	NA
10	Automatic Sprinkler System:				
	A	Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants:				
	A	Size of riser/down-comer	NA	NA	NA
	B	Number of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	NA
12	Yard Hydrants:				
	A	Total number of hydrants	NA	NA	NA
	B	Hose box	NA	NA	NA
13	Pumping Arrangements:				
A	Ground level				
	a)	Discharge of main pump	NA	NA	NA
	b)	Head of main pump	NA	NA	NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual stopping	NA	NA	NA
	i)	Pump house access	NA	NA	NA
B	Terrace Level				
	a)	Discharge of pump	450 LPM	Provided	MR
	b)	Head of the pump	40 mtrs.	Provided	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting:				
	A	Underground tank capacity	NA	NA	NA
	B	Draw-off connection	NA	NA	NA
	C	Fire service inlet	NA	NA	NA
	D	Access to tank	NA	NA	NA
	E	Overhead tank capacity	10,000 Ltrs	Provided	MR

15	Exit Signage:	Required	Provided	MR
16	Provision of Lifts:			
	A Pressurization of lift shaft	NA	NA	NA
	B Pressurization of lift lobby	NA	NA	NA
	C Communication in lift car	NA	NA	NA
	D Firemen's grounding switch	NA	NA	NA
	E Lift signage	NA	NA	NA
17	Standby Power Supply:	NA	NA	NA
18	Refuge Area:			
	A Total area	NA	NA	NA
	B Location	NA	NA	NA
19	Fire Control Room:			
	A Detector system panel	NA	NA	NA
	B Flow switch panel	NA	NA	NA
	C Pa system panel	NA	NA	NA
	D Battery backup	NA	NA	NA
	E Building floor plans	NA	NA	NA
20	Special Fire Protection systems for protection of special Risks, if any:	NA		NA

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The said school is running in ground + 02 upper floors building in a building allotted to the school by Badarpur Thermal Power Station (BPTS) administration. It has no history of NOC/FSC from this department. The copy of letter of recognition by Directorate of Education: Delhi is placed on file at C-10, 11 which may be deemed as date of initial operation of the School in the said premises. The fire safety provisions of all existing schools (operational before 2011) are determined by Directorate of Education circular no. F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011. This inspection has accordingly been conducted as per the said circular.

The fire safety systems as required under the said circular were randomly checked, tested and was found functional at the time of inspection.

In view of the substantial compliance of fire prevention and fire safety provisions as required under Rules, the issuance of FSC to the School is recommended.

Accordingly, DFA is put up for approval & signature Please.

Signature of the Inspecting Officer

Name : Rajesh Kumar Shukla

Designation ADO (M. Road)

DO (SD)

DeFO (S2)

C.F.O. Vmgh
9/5/2022
Director
9/5/22

Amu/mn