DELHI LACE Dated: 1705 7022 GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001**

No.F.6/DFS/MS/School/2022/SZ/524

FIRE SAFETY CERTIFICATE

Certified that the Mount Litra Zee School (Primary) running at ground & first floor only in a building comprised of basement, ground plus three upper floor, (basement closed, ground & first floor school, second & third floor being used as residence of owner) located at C-17, Kiran garden, Adjoining Mahalaxmi Dharamkanta, Uttam Nagar New Delhi-110059, owned/occupied by Mount Litra Zee School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and verified by the officer concerned of this department on 23/04/2022 in the presence of Sh. Mukul Jain (Director) and found that the building (GF & FF) is fit for occupancy "Educational Building" with effect from 12 15 22 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 171.05 2022 at New Delhi by

Copy to:-

The Director, 1.

Mount Litra Zee School (Primary),

C-17, Kiran garden, Adjoining Mahalaxmi Dharamkanta, Uttam Nagar New Delhi-59.

Director of Education, 2.

Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. Basement use as per BBL.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the schedule of Delhi Fire Service Rules 2010, form is www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Mount Litra Zee School (Primary), C-17, Kiran garden, Adjoining 1. Name & address of the building:

Mahalaxmi Dharamkanta, Uttam Nagar New Delhi-59.

B, G+3 upper floors but school is running at ground plus one upper 2. Building is comprised of

floor only basement closed, second & third floor used for residence.

Type of Occupancy Educational 3.

4. Type of Case New N/A 5. Details of Previous NOC

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Fire Safety directives letter No

23/04/2022 7. Date of inspection A.D.O. R.K. Yadav

8. Name of Inspecting Officer

9. Name and designation of officers

Sh. Mukul Jain (Director) From the building side

10. Year of Construction 1998

	Applica	nt's letter No. : Nil dated 05/0		D 11.1.4	Damarla
S. No.		um Standards on fire prevention and	Requirement	Provided at site	Remarks MR/NMR
		fety U/R 33 s to building		site	MICHINIC
l.	Acces	s to building			
		Road width	06 m	09 mtrs	M/R
		Gate width	N/A	N/A	N/A
		Width of internal road	N/A	N/A	N/A
2.		er, Width, Type & Arrangement of Exits			
••		, , , , , , , , , , , , , , , , , , , ,			
	a. Nu	mber of staircases			
	•	Upper Floors	2 No.	2 No.	M/R
	•	Basements	N/A	. N/A	N/A
	b. Wi	dth of staircases			
		Upper Floor	1.5 m & .75 m	1.5 m & 1 m	M/R old existing bldg
		Basements	N/A	N/A	N/A
	c. Pro	tection of exits			
	•	Fire check door	N/A	N/A	N/A
	•	Pressurization	N/A	N/A	N/A
			IN/A	IN/A	IVA
	d. N	o. of continuous staircases to	127	1.37) //D
		rrace	1 No.	l No.	M/R
	e. W	idth of Corridor	1.5 m	1.5 m	M/R
	f. D	oor Size	1.0 m	1.0 m	MR
3.	Com	partmentation			
		Fire check door	N/A	N/A	N/A
		Sealing of electrical shafts			
		Fire Rating of shaft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
		Fire Dampers	N/A	N/A	N/A
		•	N/A	N/A	N/A
4.	Smol	ke Management System			
	•	Basements	Required	Provided	M/R
	•	Upper floors	Required	Natural Ventilation	MR
5.	Fire	Extinguishers		•	
		Total numbers	06 no's	Provided	M/R
		Types	ABC/CO ₂ type	Provided	M/R
		IS marking	101	ISI marked	M/R
			ISI marked	151 marked	



6.	First-Aid Hose Reels			_
	Total numbers on each floor	N/A	Provided	M/R
	Length of hose reel hose	N/A	Provided	M/R
	Nozzle diameter	N/A	Provided	M/R
7.	Automatic fire detection and alarming system			
/ •	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
0	MOEFA	N/A	N/A	N/A
8. 9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	27/4	27/4	NI/A
	Basement	N/A N/A	N/A N/A	N/A N/A
	Ground Floor			N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants	XT/ A	100MM	M/R
	Size of riser/down-comer	N/A	1 No.	M/R
	Number of hydrants per floor	N/A	1 No.	M/R
	Hose Box	N/A	I No.	WER
2.	Yard Hydrants	2.11	N1/A	NI/A
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements			
	 Ground Level 			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out putJockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	 Auto Starting/Manual Stopping 			N/A
		N/A	N/A	
	•	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	450 LPM	M/R
	> Head of the pump	N/A	40 M	M/R
	> Power Supply	N/A	Provided	M/R
	Auto Starting of pump	N/A	Provided	M/R
4.	Captive Water Storage for fire fighting			
••	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank			
	 Overhead Tank capacity 	N/A	N/A	N/A
	·	N/A	10,000 Ltrs	MR
5.	Exit Signage.	Required	Provided	M/R



N. W. W. C.

1	•
\sim	2

16.	Provision of Lifts.	Provision of Lifts. (No Lift					
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	* N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
17.	Standby power supply	N/A	N/A	N/A			
18.	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19.	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	• Flow Switch Panel	N/A	N/A	N/A			
	PA System PanelBattery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the above compliance of the minimum standards of fire prevention and fire safety measures in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education it recommended to grant Fire Safety Certificate.

Note:- Building is comprised of basement, ground plus three upper floors but school running at ground & first floor only, Second and third floor being used as residence of owner.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

6/5/2022

\$ 115

a 151 202

Dineta 1008 2007

Do Intelhi