488



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 2 3 9

Dated 1.7.105/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Amax Inn Guest House located at 8145/6, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms + 01 Office + 01 store + 01 lift), 1st floor to 3rd floor (07 guest rooms at each floor), 4th floor (05 guest rooms) total 28 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/790 dated 10/04/19. Now, the premises was re-inspected by the officer concerned of this department on 13/05/22 in the presence of Sh. Manish (Manager) and found that the said guest house building having given an affidavit dated 05.12.2019 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (01 guest rooms), 1st floor to 3rd floor (07 guest rooms at each floor total 22 guest rooms up to third floor, with effect from 10 guest rooms at each floor total 22 guest rooms up to third floor, with effect from 10 guest rooms at each floor total 22 guest rooms up to third floor, with effect from 10 guest rooms at each floor total 22 guest rooms up to third floor, with effect from 10 guest rooms at each floor total 22 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor, with effect from 10 guest rooms up to third floor guest rooms up to third floor guest rooms up to third fl

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2022042908779 dated 29.04.2022.
- The Manager, M/s Amax Inn Guest House 8145/6, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of Fire Safety Certificate

- 1. This FSC shall stand null and void if number of lodgers are more than 10 at any one floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 10. Any flammable material for interior decoration is prohibited.

41/54

INSPECTION REPORT

1. Name & address of the building

M/s Amax Inn Guest House located at 8145/6, Arakashan Road, Pahar Ganj, New Delhi

Type of occupancy:-

(

Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 22 Guest rooms) Ground floor (Reception + 01 guest rooms + 01 Office + 01 store + 01 lift), 1st floor to 3rd floor

(07 guest rooms at each floor), 4th floor/terrace (05 guest rooms)not in use as per affidavit dated 05.12.2019

3. Type of case:-

Renewal

4. Details of previous FSC:-

F6/DFS/MS/GH/NDZ/2019/790 dated

10/04/19.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

13/05/22

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

Sh. Manish (Manager)

From the building side:9. Year of construction:-

1995

Applicant's letter No:-

2022042908779 dated 29.04.2022

Old Case S.No. Minimum Standards on fire Requirement Provided at site Remarks Prevention and fire safety Existing PSS MR/NMR U/R 33 1. Access to Building 1) Road width Spl. area 3.5 mtr. Street & MR 10 mtr. away from main road 2) Gate width N/A Directly accessible MR from 3.5 mt, street 3)Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 0.80 mtr. 1.28 Mtr. MR 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor N/A N/A N/A F. Door size N/A N/A N/A 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. Smoke Management System 1) Basements 30 ACPH N/A N/A 2) Upper floors 12 a/c per Exhaust fan MR hour

w/88

5.	Fire Extinguishers					
J.	1) Total numbers	12 Nos.	12.31			
	2) Types		12 Nos.	MR		
	3) ISI marking	ABC & CO2		MR		
-		Required	Provided	MR		
6.	First-Aid Hose Reel	0.1				
	1) Total number of eachfloor		01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors CO	Required	Provided	MR		
	2) Location of main panel	Ground floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Each floor	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System		Tiovided	IVIIC		
10.	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	IVA	IVA	IV/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A N/A	N/A		
	floor	IN/A	IN/A	IN/A		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants	IN/A	IN/A	IN/A		
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A N/A		
13.	Pumping Arrangement	IVA	IVA	IN/A		
10.	1) Ground level	N/A	N/A	NI/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump	IN/A	N/A	N/A		
	b) Head of main pump	N/A	N/A	NIA		
	c) Number of main	N/A	N/A	N/A		
	pump	14/74	IN/A	N/A		
	d) Jockey pump out put	N/A	N/A	71/4		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A		N/A		
	g) Stand by pump butput	N/A N/A	N/A	N/A		
	h) Auto starting/Manual	N/A N/A	N/A	N/A		
	stopping	IN/A	N/A	N/A		
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 I D) 4	-		
	b) Head of pump		450 LPM	MR		
	c) Power supply		40 mtr.	MR		
	d) Auto starting of pump		Provided	MR		
14.	Cantive Water Standard Co. E.	Required	Provided	MR		
	Captive water Storage for Fire Fighting					
	capacity	N/A	N/A	N/A		
	a) Draw-off connection	NI/A				
		N/A	N/A	N/A		

	W/ 66				
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	Required	Provided	MR	
	d) Fireman's switch	Required	Provided	MR	
	e) Lift signage	Required	Provided	MR	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System Risk, if any: One ABC type at elenear generator found provided.	MR			

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/790 dated 10/04/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only,

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: - ADO (CC)

tun Pheuse.

uppoaded