GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/ 55

Dated: 90/05/2022

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C Primary School,** Mohan Nagar (Previously known as Vashistha Park-II) New Delhi-110046 comprised of ground plus one upper floor, owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2019/SZ/784 dated 10/04/2019. The school building was re- inspected by the officer concerned of this department on 09/05/2022 in the presence of Smt. Saroj (Principal) and found that the School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 20 05 7022 at New Delhi.

(SUNIL'CHAWDHARY) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Principal,
 S.D.M.C Primary School,
 Vashistha Park-II, New Delhi-110046
- Director of Education, S.D.M.C, Civic Centre, Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT

S.D.M.C Primary School, Mohan Nagar, New Delhi-110046

ground plus one floor Educational

Renewal F.6/DFS/MS/School/2019/SZ/784 dated 10/04/2019

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

 Name & address of the building
 Building comprised of
 Type of Occupancy
 Type of Case
 Details of Previous NOC
 Fire Safety directives letter No
 Date of inspection
 Name of Inspecting Officer
 Name and designation of officers
 From the building side
 09/05/2022 A.D.O. R.K.Yadav

From the building side Smt. Saroj (Principal)

10. Year of Construction
11. Applicant's letter No. 2003 Nil de

S. No.		Applicant's letter No. : Nil dated 12/04/2022						
S. NO.	safety	um Standards on fire prevention and fire U/R 33	Dir. of Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR			
1.	Access to building							
		Road width	Accessible	Provided	MR			
		Gate width	4.5 mtrs	3.65 & 1.3 mtrs.	MR, being old case			
		Width of internal road	N/A	N/A	N/A			
2.	Number, Width, Type & Arrangement of Exits							
	a Nu	mber of staircases						
	a. Iva	Upper Floors		02 1) (D			
		Basements	02 no.'s	02 no.'s	MR			
	b Wi	dth of staircases	N/A	N/A	N/A			
	0. WI	1						
		Upper Floor Basements	1.50 m	1.70 & 1.70 m	MR			
	•	Basements	N/A	N/A	N/A			
	c. Pro	tection of exits	N/A	N/A	N/A			
	•	Fire check door Pressurization	N/A	N/A	N/A			
		1 ressurization						
	d. No	. of continuous staircases to	N/A	N/A	N/A			
	terrace		1.50 m	2.40 m	MR			
	e. Width of Corridor		1.0 m	1.0 m (double	MR			
		ass room Door Size	1.0 111	door)	MIK			
3.	Comp	artmentation		,				
		Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A	N/A				
		Fire Rating of shaft door			N/A			
		Water Curtain	N/A	` N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
		The Dampers	N/A	N/A	N/A			
١.	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Natural Ventilation provided	MR			
5.	Fire Extinguishers							
	•	Total numbers	05 No's	Provided	MR			
	•	Types	ABC/CO ₂ type	Provided	MR			
	•	IS marking	ISI marked	ISI marked	MR			
6.	First-	aid Hose Reels						
		Total numbers on each floor	N/A	N/A	N/A			
		Length of hose reel hose	N/A	N/A	N/A			
		Nozzle diameter	N/A		N/A			
	1			N/A	IN/A			

7.	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A N/A	N/A		
	 Hooters' Location 	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
10						
10.	Automatic Sprinkler System	N/A	N/A	N/A		
	Basement Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants	1471				
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	· N/A	N/A		
13.	Pumping Arrangements					
	Ground Level			NT/A		
	Discharge of main Pump	N/A	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A		
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	> Pump House Access					
	Terrace levelDischarge of pump	N/A	N/A	N/A		
	> Head of the pump	N/A	· N/A	N/A		
	> Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
				27/4		
	Overhead Tank capacity	N/A	N/A	N/A		
15.		N/A N/A	N/A N/A	N/A N/A		
	Overhead Tank capacity		N/A (I	N/A No Lift)		
	Overhead Tank capacity Exit Signage. Provision of Lifts.		N/A	N/A No Lift) N/A		
	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A (I N/A N/A	N/A No Lift) N/A N/A		
	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby	N/A N/A	N/A (I	N/A No Lift) N/A		
	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft	N/A N/A N/A	N/A (I N/A N/A	N/A No Lift) N/A N/A		
	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car	N/A N/A N/A N/A N/A	N/A (I N/A N/A N/A N/A N/A	N/A No Lift) N/A N/A N/A		
16.	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	N/A N/A N/A	N/A (I N/A . N/A . N/A	N/A No Lift) N/A N/A N/A N/A		
16.	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	N/A N/A N/A N/A N/A N/A	N/A (I N/A N/A	N/A No Lift) N/A N/A N/A N/A N/A N/A		
16.	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area.	N/A N/A N/A N/A N/A N/A N/A N/A	N/A (I N/A . N/A . N/A N/A N/A N/A N/A	N/A No Lift) N/A N/A N/A N/A N/A N/A N/A		
15	Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	N/A N/A N/A N/A N/A N/A	N/A (I N/A N/A	N/A No Lift) N/A N/A N/A N/A N/A N/A		

19.	e re C	ontrol Room			
	•	Detector System Panel	N/A	N/A	N/A
	PA System PanelBattery backup	Flow Switch Panel	N/A	N/A	N/A
			N/A	N/A	N/A
			N/A	, N/A	N/A
			N/A	N/A	N/A
20.	Special special	Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/784 dated 10/04/2019 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Ogero (\$2)

A D O (D)

For better is put up for sognature put light of the l