GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

5.F6/DFS/MS/School/SZ/2022/ 584

OF DELHI

11-110 001

Dated: 2705/2022

FIRE SAFETY CERTIFICATE

Certified that the Sunshine Public School located at D-1/201, Vishwakarma Colony, Jaitpur Extn., Badarpur, New Delhi-44, comprised of Ground floor only was granted Fire Safety Certificate by this department vide letter no.- F6/DFS/MS/School/2018/SZ/1364 dated 13.06.2018. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 11.05.2022 in the presence of manager and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Director of Education and the building (Ground floors only) is fit for occupancy of Group B "Educational Building" with effect from Issued on ... 2. 2022 at New Delhi by

(Sunil Chawdhary)

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- 2. Sunshine Public School located at D-1/201, Vishwakarma Colony, Jaitpur Extn., Badarpur, New Delhi-44.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

			INSP	ECTION REPOR	Γ			
1	1	Van	e & address of the building	Sunshine Pub Vishwakarma Badarpur, New	•	l at D-1/201 pur Extn.		
2	Building is comprised of			Ground floor o	nly			
3	T	Type of occupancy		Group B -Educa	Group B –Educational Building			
4	Type of case		of case	Renewal				
5	Details of previous FSC Fire safety direction letter no.			F6/DFS/MS/School/2018/SZ/1364 dated 13.06.2018 F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011				
6								
7	D	ate	of inspection	11.05.2022				
8	Name of the inspecting officers			Rajesh Kumar S	hukla, ADO (M.Ro	ad)		
9	N	ame	e of the designation of	,				
10	Y	ear	of construction	2007 Letter no. nil dated 07.04.2022				
11			cant's letter no.					
S.No	M	iniı	num standard of fire		Provided at site	Remarks MR/NMR		
	33	1		Circular dated 01.03.2011				
1	Access to Building:							
	A		load width	Accessibility (6.0 mtr)	Accessibility (6.0 mtr)	MR		
	В	_	Sate width	NA	NA	NA		
2	C	_	Vidth of internal road	NA CF :	NA	NA		
2	_	Number, Width, Type and Arrangement of Exits: A Number of staircases						
	A	-		NIA	annual Garage	214		
		a	Upper floor	NA	ground floor only	NA		
	D	b	Basement /idth of staircases	NA	NA	NA		
	В	-		NIA	NA	NA		
		a	Upper floor	NA	NA	NA		
	C	b	Basement rotection of exits	NA	NA	NA		
	C	a	Fire check door	NA NA	NA NA	NA		
-		_	Pressurization Pressurization	NA	NA	NA NA		
	D	N		NA	NA	NA		
	E	W	idth of corridor	NA	NA	NA		
	F	D	oor size	1 mtrs.	Provided	MR		
3	Co	npa	rtmentation:					
	A	Fi	re check door	NA	NA	NA		
	В	Se	aling of electrical shafts	NA	NA	NA		
	C	Fi	re rating of shaft door	NA	NA	NA		
	D	W	ater curtain	NA	NA	NA		
	E		e dampers	NA	NA	NA		
4	Smo	ke	Management System:					
_	A		sement	NA	NA	NA		
	В	Up	per floor	NA	NA	NA		

	5. Fire Extinguisher:							
		A Total numbers	04 nos.	04 nos.	MR			
		B Types	CO ₂ & ABC	CO ₂ & ABC	MR			
		C ISI marking	Required	Provided	MR			
6	1	First-Aid-Hose Reel:						
	1	Total numbers of each floor	NA	NA	NA			
	1	B Length of hose reel hose	NA	NA	NA			
	(NA	NA	NA			
7								
	A	Type of detectors	NA	NA	NA			
	E		NA	NA	NA			
	(Location of repeater panel	NA	NA	NA			
	D	Alternate source of power	NA	NA	NA			
	E		NA	NA	NA			
8		10EFA:	NA	NA	NA			
9		ublic Address System:	NA	NA	NA			
10		utomatic Sprinkler System:						
10	A	•	NA	NA	NA			
	В		NA	NA	NA			
	C		NA	NA	NA			
11		iternal Hydrants:						
11	_	Size of riser/down-comer	NA	NA	NA			
	A	Number of hydrants per floor	NA	NA	NA			
	B	Hose box	NA	NA	NA			
	C		1					
12	-	ard Hydrants:	NA	NA	NA			
	A	Total number of hydrants		NA	NA			
	В	Hose box	NA	INA	1471			
13	Pu	Pumping Arrangements:						
Α	(Ground level						
	a)	Discharge of main pump	NA	NA	NA			
	b)	Head of main pump	NA	NA	NA			
	c)	Number of main pumps	NA	NA	NA			
	d)	Jockey pump out put	NA	NA	NA			
	e)	Jockey pump head	NA	NA	NA			
	f)	Standby pump out put	NA	NA	NA			
	g)	Standby pump head	NA	NA	NA			
-	h)	Auto starting /manual	NA	NA	NA			
	,	stopping						
-	i)	Pump house access	NA	NA	NA			
3	Terrace Level							
	a)	Discharge of pump	NA	NA	NA			
r	b)	Head of the pump	NA	NA	NA			
-		Power supply	NA	NA	NA			
	c)	1 over suppry			NA			

Sunshine Public School located at D-1/201, Vishwakarma Colony, Jaitpur Extn., Badarpur, New Delhi-44

Sunshine Public School located at D-1/201, Vishwakarma Colony, Jaitpur Extn., Badarpur, New Delhi-44

14	Captive Water Storage for Fire Fighting:							
	A	Underground tank capacity	NA	NA	NA			
	В	Draw-off connection	NA	NA	NA			
	C	Fire service inlet	NA	NA	NA			
	D	Access to tank	NA	NA	NA			
	E	Overhead tank capacity	NA	NA	NA			
15	Ex	it Signage:	NA	NA	NA			
16	Pro	Provision of Lifts:						
	A	Pressurization of lift shaft	NA	NA	NA			
	В	Pressurization of lift lobby	NA	NA	NA			
	C	Communication in lift car	NA	NA	NA			
	D	Firemen's grounding switch	NA	NA	NA			
	E	Lift signage	NA	NA	NA			
17	Sta	andby Power Supply:	NA	NA	NA			
18	Re	Refuge Area:						
	A	Total area	NA	NA	NA			
	В	Location	NA	NA	NA			
19	Fire Control Room:							
	A	Detector system panel	NA	NA	NA			
	В	Flow switch panel	NA	NA	NA			
	C	PA system panel	NA	NA	NA			
	D	Battery backup	NA	NA	NA			
	E	Building floor plans	NA	NA	NA			
20		ecial Fire Protection systems for			NA			
	protection of special Risks, if any:							

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If approved & keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2018/SZ/1364 dated 13.06.2018 is recommended to be renewed.

Signature of the Inspecting Officer

Name Rajesh Kumar Shukla Designation ADO (M. Road)

O(SD) LIVIZIOS

Defora

1 Listas las

ADD MRN

Fi is fut pla

24/5/2

M.S. cell