GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated: 83/86/2822

NO. F6/DFS/MS/2022/WZ/ 246

FIRE SAFETY CERTIFICATE

51/20. No. Kh. at located 51/19,51/18,51/13,51/27,51/14,51/15,50/11,50/10,51/6,51/7,51/8,51/9,51/2 and 51/1,G.T. Karnal Road, resort Bakoli, Alipur, Delhi-36 comprised of Basement, Ground Floor (Kitchen, Restaurant & 11 Guest Rooms) & First floor (20 Guest Rooms) Total 31 Guest Rooms owned / occupied by M/s Rishi Buildcon Pvt. Ltd. was issued fire safety certificate vide Letter no. F6/DFS/MS/2019/669 dated 29.03.2019. The premise was re-inspected by the officer concerned of this department on 27.05.2022 in the presence of Sh. Ashok Yadav and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under "Class Residential Motel Building Excluding temporary structure assembly" with effect from 6.3. 66.25.22... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on .02/06/2022. at New Delhi by

(Dharampal Bhardwaj) Dy.Chief Fire Officer WEST ZONE

MIR

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.
- 9. This FSC is valid for exiting pucca structure /building as earlier approved by this department.

Copy to:

1. Bine Salam Motels (village Bakoli, Main G.T.K Road, Delhi-36.

INSPECTION REPORT

Name & address of the building

: M/s Blue Sapphire Motel and Resort (Rishi Building Pvt. Ltd.)

GT Karnal road, Bakoli, Alipur, Delhi-36.

Type of Occupancy

: Residential

Building Comprised

: Basement(Services), Ground(Kitchen, Restaurant, 11 Guest Rooms) &

First Floor (20 Guest Rooms)

Type of Case

: Renewal

Details of previous NOC 5.

dated 29/03/2019 : F6/DFS/MS/2019/669

6. Fire Safety directives letter No

: F6/MS/DFS/BP/2005/626 dated 21/03/2005

7. Date of inspection

: 27.05.2022

8. Name of the Inspecting Officers

: ADO, R.K.Sinha

9. Name and designation of officers

: Sh. Ashok Yadav

from the building side 9. Year of Construction

: ----

10. Applicant's letter No.

MHA Application No. 2022051810598 dated -18.05.2022

	Minimu	m Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR
1	Access to	building			
	•	Road width	9 m	9 m	MR
	•	Gate width	05m	05m	MR
	•	Width of internal road	06 m	06 m	MR
2	Number	, Width, Type & Arrangement of Exits	•		
	a. Numb	er of staircases			
	•	Upper Floors	07	Provided	MR(First floor has opening to terrace)
			10	Provided	MR(NOC issued as per req. to travel distance
	•	Basements			reduced as
	b. Widtl	of staircases			amendment(30 m)
	•	Upper Floors	1.25 m	Provided	MR
	•	Basements	1.25 m	Provided	MR
	c. Prote	ction of exits	1.23 111	11011404	
	•	Fire check door	Required	Provided	MR
	•	Pressurization	NA	NA	NA
	d. No.	of continuous staircases to terrace			
			01	03	MR



N-40

	f. Door Size	1.5 m	Provided	140
	Compartmentation.	1 m	l m	MR
				MR
	Fire check door	Required		
	 Sealing of electrical shafts 	Required	Provided	MR
	 Fire Rating of shaft door 		Provided	MR
	Water Curtain	Required	Provided	MR
	Fire Dampers	Required	Provided	MR
	Smile	Required	Provided	
	Smoke Management System.			MR
	Basements			
	Upper floors	30 a/c per hour	Exhaust fan	MR
		12 a/c per hour	Provided	
	Fire Extinguishers		Trovided	MR
	Total numbers			
	• Types	25	30	MR
	ISI marking	ABC & Co2	ABC & Co2	MR
	First-Aid Hose Reels. Yes Yes			
				MR
	rotal numbers on each floor	04	04	
	• Length of hose reel hose	30m		MR
	Nozzle diameter		30m	MR
	Automatic fire detection and alarming system. 5mm 5mm			MR
	Type of detectors			
	Location of Main Panel	Smoke /Heat	Provided	MR
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
	MOEFA	NA	NA	
	Public Address System.	Required	Provided	NA
0	Automatic Sprinkler System.	Required	Provided	MR MR
	Sprinkler System.			
	Basement	Required	Provided	
	Upper Floor	Required	Provided	MR
	 Sprinkler above false ceiling 			MR
		NA	NA	NA



0
6

	Internal Hydrants		Provided	MR			
		100mm		MR			
	Size of riser/down-comer	04	Provided Provided	MR			
	Number of hydrants per floor	04	Provided				
	Hose Box						
				MR			
2	Yard Hydrants.	Required	Provided				
	Total number of hydrants		Provided	MR			
		Required	110110				
	Hose Box						
	Pumping Arrangements.						
	Pumping Arang		ango leem	MR			
	Ground Level	2280 lpm	2280 lpm				
	- Cmain Pump		Provided	MR			
		40 m	Provided	MR			
	> Head of Main pump	03		MR			
	Number of main pumps	180 lpm	Provided	MR			
	Jockey Pump out put	40 m	Provided	MR			
	Jockey pump head	2280 lpm	2280 lpm				
	n. P. me out put		Provided	MR			
		40 m		MR			
	> Standby Pump Head	Required	Provided	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
	Auto Starting/ Manual stopping	Requires					
	> Pump House Access		Provided	MR			
	Terrace level	900 lpm	the state of the s	MR			
	> Discharge of pump	40 m	Provided				
			Provided	MR			
	Head of the pump	Required		ME			
	> Power Supply	Required	Provided	36235			
	 Auto Starting of pump 	Regulato					
	Captive Water Storage for fire fighting.						
1	Captive Water Storage for in Cag	1,00,000 ltr.	Provided	MR			
	Underground tank capacity	1,00,000 111		MR			
		Required	Provided				
	> Draw-off connection	Required	Provided	MR			
	> Fire service inlet		Provided	MR			
	> Access to tank	Required					
		10,000 ltr	Provided	MR			
	Overhead Tank capacity	10,000 10		MR			
		Required	Provided	19635			
	Exit Signage.						
)	Provision of Lifts.						
	TL & Shaft	Required	Provided	MR			
	Pressurization of Lift Shaft	Required	Provided	MR			
	 Pressurization of Lift lobby 	Kedanea					



		N- 10		
		,	Provided	MR
•	Communication In lift Car	Required	Provided	MR
1	Fireman's Grounding Switch	Required		MR
	• Lift Signage	Required	Provided	MR
		Required	Provided	
Sta	andby power supply			
Re	fuge Area.		N/A	N/A
	> Total Area	N/A	N/A	N/A
		N/A	N/A	
	> Location			MR
9 Fi	re Control Room	Required	Provided	
	 Detector System Panel 	NA	NA	NA
	 Flow Switch Panel 		Provided	MR
	 PA System Panel 	Required		NA
	 Batter backup 	NA	NA	NA
	 Building Floor Plans 	NA	NA	NA NA
			NA	1121
20 S	pecial Fire Protection Systems for Protection of special Risks, if any:	NA		

The fire protection systems provided in the building were tested/ checked randomly and

Keeping in view of the deemed compliance of the minimum standards on fire prevention found in good working conditions. and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/2019/669 dated 29.03.2019 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

> Signature of the Inspecting Officer Name: - Rajeev Kumar Sinha

Designation: - ADO/BW

Presolven (-T lite ~ prop for presolven)

presolven Cerl