

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/ 607

Dated: 01/06/2022

**FIRE SAFETY CERTIFICATE**

Certified that the building of Sarvodaya Kanya Vidyalaya, Vikas Puri (District Centre), New Delhi-18, is having Six blocks (Pry wing ground floor only, SPS G+1, Middle wing ground floor only, Vocational wing G+1, Main building G+2 upper floors & MP hall ground floor only), owned/occupied by Sarvodaya Kanya Vidyalaya. The School building was inspected by the officer concerned of this department on 13/05/2022 in the presence of Smt. Neeti Tiwari (Principal) and found that the school building have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/FireSafety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on..... 01/06/2022 ..... at New Delhi.

(AJUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. The Principal,  
Sarvodaya Kanya Vidyalaya,  
Vikas Puri (District Centre), New Delhi-18.
2. Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi - 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

**INSPECTION REPORT**

- 1 Name & address of the building
- 2 Building comprised of
- 3 Type of Occupancy
- 4 Type of Case
- 5 Details of Previous NOC
- 6 Fire Safety directives letter No
- 7 Date of inspection
- 8 Name of Inspecting Officer
- 9 Name and designation of officers  
From the building side
- 10 Year of Construction

Sarvodaya Kanya Vidyalaya, Vikas Puri (District Centre), New Delhi-18  
Six blocks (Pry wing ground floor only, SPS G+1, Middle wing ground floor only, Vocational wing G+1, Main building G+2 Upper floor only & mp hall ground floor only)  
Educational  
New  
N/A  
N/A  
13/05/2022  
A D O R K Yadav  
Smt Neeti Tiwari (Principal)  
Before 2010 (Main Block, Pry Blk, Voc Blocks) &  
2019 (New Bldg, MP Hall/Auditorium & New SPS Block)  
SKV/DC/VP/2022/215 dated 27/04/2022

11. Applicant's letter No

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	UBBL-16 /NBC-17 requirements	Provided at site	Remarks MR/NMR
1.	<b>Access to building</b>			
	<ul style="list-style-type: none"> <li>• Road width</li> <li>• Gate width</li> <li>• Width of internal road</li> </ul>	Accessible (06 mtrs ) 4.5 mtrs. N/A	Available 06 mtrs N/A	MR MR N/A
2.	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	<ul style="list-style-type: none"> <li>• Upper Floors</li> <li>• Basements</li> </ul>	02 no's in MB, N Bldg, 03 no's New SPS blk & 01 no each in Voc blks	Provided	MR
	b. Width of staircases	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Upper Floor</li> <li>• Basements</li> </ul>	1.50 & 75 M	1.30 M each in M blk, 1.50 m each in N bldg, 1.5 m in N SPS blk, 1.50 m each in voc blk	MR
	c. Protection of exits	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Pressurization</li> </ul>	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Required	Provided	M/R
	e. Width of Corridor	1.5 m	2.45 m in M blk, 2.95m in N bldg, 1.50 m in Voc blk & 1.50 m in N SPS blk	M/R
	f. Class Room Door Size	1.0 m in M blk, Voc Blk, Pry blk & New SPS blk & 1.20 m in N bldg & 2.0 cms in MP Hall	1.0 m each in M blk, Voc Blk, Pry blk, New blk & 1.2 m each in N bldg, & 2.0 m (06 no's) in MP hall	M/R
3.	<b>Compartmentation</b>			
	<ul style="list-style-type: none"> <li>• Fire check door</li> <li>• Sealing of electrical shafts</li> <li>• Fire Rating of shaft door</li> <li>• Water Curtain</li> <li>• Fire Dampers</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	<b>Smoke Management System</b>			
	<ul style="list-style-type: none"> <li>• Basements</li> <li>• Upper floors</li> </ul>	N/A	N/A	N/A
		Required	Natural ventilation provided	M/R
5.	<b>Fire Extinguishers</b>			
	<ul style="list-style-type: none"> <li>• Total numbers</li> <li>• Types</li> <li>• ISI marking</li> </ul>	30 no's ABC/CO <sub>2</sub> type ISI marked	Provided	M/R
			Provided	M/R
			Provided	M/R

6.	<b>First-Aid Hose Reels</b> <ul style="list-style-type: none"> <li>Total numbers in M blk, N bldg, MP hall</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	One/floor	Provided	M/R
		30 mtrs	Provided	M/R
		5 mm	Provided	M/R
7.	<b>Automatic fire detection and alarming system</b> <ul style="list-style-type: none"> <li>Type of detectors</li> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8.	<b>MOEFA</b>	N/A	N/A	N/A
9.	<b>Public Address System</b>			
10.	<b>Automatic Sprinkler System</b> <ul style="list-style-type: none"> <li>Basement</li> <li>Ground Floor in MP hall wooden stage</li> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
		Required	Provided	M/R
		N/A	N/A	N/A
11.	<b>Internal Hydrants</b> <ul style="list-style-type: none"> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
12.	<b>Yard Hydrants</b> <ul style="list-style-type: none"> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
13.	<b>Pumping Arrangements</b> <ul style="list-style-type: none"> <li>Ground Level <ul style="list-style-type: none"> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/Manual Stopping</li> </ul> </li> <li>Pump House Access</li> <li>Terrace level <ul style="list-style-type: none"> <li>Discharge of pump</li> <li>Head of the pump</li> <li>Power Supply</li> <li>Auto Starting of pump</li> </ul> </li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		450 LPM each in M blk, N bldg, MP hall	Provided	M/R
		30 mtrs	Provided	M/R
		Required	Provided	M/R
Required	Provided	M/R		
14.	<b>Captive Water Storage for fire fighting</b> <ul style="list-style-type: none"> <li>Underground tank capacity <ul style="list-style-type: none"> <li>Draw-off connection</li> <li>Fire service inlet</li> <li>Access to tank</li> </ul> </li> <li>Overhead Tank capacity</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		10000 ltrs each in M blk & N Bldg & 5000 ltrs in MP hall	Provided	M/R
Required	Provided	M/R		
15.	<b>Exit Signage.</b>			

N/10

16.	Provision of Lifts.			No Lift
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued vide letter No. F6/DFS/MS/School/2019/SZ/6334 dated 23/10/2019 has been complied.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under rule 35 of the Delhi Fire Service Rules 2010 it is not recommended to grant Fire Safety Certificate.

Note:- Main block has been demolished at present only six blocks are there.

Signature of Inspecting Officer *R K Yadav*  
 Name:- R K. Yadav  
 Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

*19/10/22*

*23/5/2022*

*24/10/22*

*25/10/22*

*ADD (JANAKPURI)*