

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2022/SZ/ 172

Dated 13./.0.6/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Mala Akbari Restaurant, (Unit of Mala Akbari Hospitality North Pvt Ltd) located at T-304, 3rd Floor, Ambience Mall, Plot No 2, Nelson Mandela Marg, New Delhi 110070 Comprised of 03 Basements, Ground Plus Three Upper Floors owned/occupied by Unit of Mala Akbari Hospitality North Pvt Ltd) was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/2011/176 Dated 31/01/2011 for the name of Zambar Restaurant. The restaurant premise was re-inspected by the officer concerned of this department on 04/06/2022 in the presence of Mr. Manoj (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at 3rd Floor only) with effect from 1.3.1.9.2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13 / 06 /2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049.

2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016. (Ref. MHA Portal ID 2022050509450 dated 17/05/2022)

3. M/s Mala Akbari Restaurant, (Unit of Mala Akbari Hospitality North Pvt Ltd) located at Shop No T-304, 3rd Floor, Ambience Mall, Plot No 2, Nelson Mandela Marg, New Delhi 110070

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



	INSPECTIO	ON REI	PORT				
1	Name & Address of the Building	INSPECTION REPORT me & Address of the Building M/s Mala Akbari Restaurant, (Unit of Mala Akbari Hospitality North Pvt Ltd) Shop No T-304, 3 rd Floo					
1	Name & Address of	Ambience Mall, Plot No 2, Nelson Mandela Marg, New Delhi 110070. Assembly Building "Group-D" Restaurant			ndela Marg,		
2	Type of Occupancy	Assemi	or Pacer	ment, Ground + 03 upper	floors		
3	Building Comprised of	Three t	al /Name	Change			
4	Type of Case	Kenew	C/MC/EL	1/2011/176 Dated 31/01/	2011 for the		
5	Details of Previous NOC	F.6/DFS/MS/EH/2011/176 Dated 31/01/2011 for the name of Zambar Restaurant,					
		Nil					
6	Fire Safety Directives Letter No	04/06/2022					
7	Date of Inspection						
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP) Mr. Manoj (Manager)					
9	Name & Designation of Officers						
	from the building side	2010 Restaurant running at 3 rd Floor in					
10	Year of construction	Ambiance Mall building.					
		MHA I	Portal 20	22050509450 dated 17/05	/2022		
11	Applicant letter No. Minimum standards on Fire Prevention		/ BBL	Provided at Site	Remarks		
S. No.	and Fire Safety U/R 33	Requi	rement		MR/NMR		
1	and Fire Safety U/R 33 Access to Building. FSC No.F.6/DFS/MS/M	all/2020/	SZ/56 Dat	ted 21/01/2020 of Ambienc	MR		
	Road width	Kesta	uran		N/A		
	Gate width	within	n Mall	As above	N/A		
	Width of internal road			As above	1472		
2							
	a. Number of Staircase	riovided & MD					
	• Upper floors		Nos	As above	N/A		
	Basement floor	N/A		As above			
	b. Width of Staircase	Provided & Maintained by Ambiance Mall			MR		
	Upper floors	Required		As above	N/A		
	Basement floor	N/A					
	c. Protection of exits	Provided & Maintained by Ambiance Mal			MR		
	• Fire check door		uired	As above	N/A		
	Pressurization		/A	As above	MR		
	- N Continuous staircase to terrace		uired	As above	N/A		
	e. Width of corridor	1	/A	N/A	MR		
	f. Door size	2 Exits		2 m lm & 1 m			
3	Compartmentation.	Provided & Maintained by Ambiance Ma			MR		
3	• Fire check door.		uired	As above	N/A		
	Sealing of electrical shafts.		/A	As above	N/A		
	Fire rating of shaft door.		/A	N/A N/A	N/A		
	Water curtain		/A		N/A		
	• Fire dampers.	N	/A	N/A			
4.	Smoke Management system.		Provided & Maintained by Ambience Mall				
71	Basement		/A	As above	MR		
	• Upper floors	Req	uired	Exhaust fans provided	IAIIC		
5.	Fire Extinguishers.			2637	MR		
	Total numbers	05 Nos	Nos	06 Nos.	MR		
	Types			ABC-04, W.CO ₂ -02	MR		
	ISI Marking	ISI m	arked	Provided			
6.	First Aid Hose Reels.	Pr	ovided &	Maintained by Ambie	HCC MINH		



	 Total numbers on each floor. 		One in Restaurant	MR	
	 Length of hose-reel hose. 	Hose Reel	30m	MR	
	Nozzle Diameter		5mm	MR	
7	Automatic Fire Detection and Alarming s	ystem. (Provided	stem. (Provided & Maintained by Ambience Mall)		
	 Type of detectors 	Required	Smoke & Heat	MR	
	 Location of Main Panel 	Required	As above	MR	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	 Alternate source of power 	Required	As above	MR	
	 Hooter's location 	Required	As above	MR	
8.	MOEFA	Required	As above	MR	
9.	Public Address System	Required	As above	MR	
10.	Automatic Sprinkler System	Provided & Maintained by Ambience Mall			
	Basement	Required	As above	MR	
	 Upper floors 	Required	Provided in Restt.	MR	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11.	Internal Hydrants.	Provided & Maintained by Ambience Mall			
	Size of Riser/Down-comer	Required	As above	MR	
	 Number of Hydrant per floor 	Required	As above	MR	
	Hose box.	Required	As above	MR	
12.	Yard Hydrants.	Provided &	Maintained by Ambien		
	 Total number of hydrants. 	N/A	As above	N/A	
	• 2. Hose box.	N/A	As above	N/A	
13.	Pumping arrangements.			1.771	
	Ground Level	Provided & Maintained by Ambience Mall			
	Discharge of main pump.	4500 LPM	As above	MR	
	Head of main pump.	70 mtr	As above	MR	
	Number of main pumps.	Two	As above	MR	
	Jockey Pump output.	450 LPM	As above	MR	
	Jockey Pump head.	70 mtr	As above	MR	
	Standby Pump output.	4500 LPM	As above	MR	
	Standby Pump head.	70 mtr	As above	MR	
	Auto Starting / Manual Stopping.	Required	As above	MR	
	Access to pump house	Required	As above	MR	
	Terrace Level	Provided & Maintained by Ambience Mall			
	Discharge of pump.	N/A	N/A	N/A	
	Head of pump.	N/A	N/A	N/A	
	Power supply.	N/A	N/A	N/A	
	Auto starting of pump.	N/A	N/A	N/A	
14.	Captive water storage for Fire Fighting.	Provided &	Maintained by Ambier		
	 Underground tank capacity. 	5,00,000 Ltr	As above	MR	
	Draw-off connection.	Required	As above	MR	
	Fire Service Inlet.	Required	As above	MR	
	Access to tank.	Required	As above	MR	
	 Overhead tank capacity. 	20,000 Ltr	As above	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.		Maintained by Ambier		
	 Pressurization of lift shaft. 	N/A	N/A	N/A	
	 Pressurization of lift lobby. Communication in lift car. 	N/A	N/A	N/A	



	•	Fireman's switch.	N/A	N/A	N/A
		Lift signage.	N/A	N/A	N/A
17	Stand	by Power Supply	Required	Provided (DG Set)	MR
18.	Refug	e Area			
	Total areaLocation	N/A	N/A	N/A	
		N/A	N/A	N/A	
19.	Fire C	ontrol Room.	Provided & Maintained by Ambience Mall		
	Detector System Panel.	N/A	As above	N/A	
	•	Flow Switch Panel. PA system Panel.	N/A	As above	N/A
	 PA system Panel. Battery backup Building floor plan 	N/A	As above	N/A	
		N/A	As above	N/A	
		N/A	As above	N/A	
20.		l Fire Protection System for the tion of special Risk, if any:	N/A	As above	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/2011/176 Dated 31/01/2011 for the name of Zambar Restaurant, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Rajesh Kumar

Designation: ADO / BCP

DO (SD)

DOMOR yester for your synature P/ Dy (fols 2 A M.S. Off