

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/ 6 60

Dated: 16 06 2022

FIRE SAFETY CERTIFICATE

Certified that the C.R. Oasis Convent Sr. Sec. School, Pole New Line, Village & P.O.-Paprawat, Najafgarh, New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by C.R. Oasis Convent Sr. Sec. School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2019/SZ/1000 dated 10/05/2019. The school building was re- inspected by the officer concerned of this department on 11/06/2022 in the presence of Sh. S.K.Bhardwaj (Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(SUNIL CHAWDHARY) Dy. CHIEF FIRE OFFICER

Copy to:-

The Principal,
 C.R. Oasis Convent Sr. Sec. School,
 Pole New Line, Village & P.O.- Paprawat, Najafgarh, New Delhi-110043

 Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.



INSPECTION REPORT

C.R. Oasis Convent Sr. Sec. School, Pole New Line, Village & P.O.-1. Name & address of the building

Paprawat, Najafgarh, New Delhi-110043

Ground plus one upper floor. Building comprised of 2.

Educational

3. Type of Occupancy

F.6/DFS/MS/School/2019/SZ/1000 dated 10/05/2019 4. Type of Case

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 5. Details of Previous NOC 6. Fire Safety directives letter No

11/06/2022 7. Date of inspection

A.D.O. R.K.Yadav 8. Name of Inspecting Officer

10.		Construction : CROCSSS/I		Provided at	Remarks MR/NMR	
No.	Minim	um Standards on fire prevention and fety U/R 33	Circular dt. 01.03.2011	site	AK/NWIK	
	Access	to building		11.4	MR	
			Accessible	Provided	MR, being old case	
	•	Road width	4.5 m	4.25 m N/A	N/A	
	•	Gate width	N/A	IVA		
	•	Width of internal road	its			
	Numb	er, Width, Type & Arrangement of Ex				
		C trimages		02 no.'s	MR	
	a. Nu	mber of staircases	02 no.'s	N/A	N/A	
	•	Upper Floors	N/A	[N/A		
		Basements idth of staircases			MR	
	b. W	Upper Floor	1.50 m	2.15 m each	N/A	
		nanto	N/A	N/A	1077	
	•	Basements			N/A	
			N/A	N/A		
	c. Pr	otection of exits	N/A	N/A	N/A	
		Fire check door	14/74			
		Pressurization	N/A	N/A	N/A	
		to atoireases to		N/A	N/A	
		o. of continuous staircases to	N/A	.95 & .90 m few cl	ass MR, being old	
	t	errace	1.0 m	rooms with single		
	e. \	Vidth of Corridor		door of 1.0 m		
		Class room Door Size			N/A	
3.	Соп	partmentation	N/A	N/A	N/A	
		Fire check door	N/A	N/A	N/A	
		Sealing of electrical shafts		N/A	N/A	
		Fire Rating of shaft door	N/A	N/A	N/A	
		 Water Curtain 	N/A	N/A	N/A	
		 Fire Dampers 	N/A	1071		
		oke Management System				
4.	Sm	oke Management - 5	N/A	N/A	N/A	
		Decements	14//1			
		• Basements	Required	Natural Ventilation	on MR	
		Upper floors	Required	provided		
		• Оррег поот				
	Tr:	re Extinguishers				
5.	FII		12 No's	Provided	MR	
		Total numbers	ABC/CO ₂ typ	e Provided	MR	
1	1	• Types	ISI marked	ISI marked	MR	

	Į v	1.4		, ,		
6.	First-Aid Hose Reels					
	Total numbers on each floor	N/A	NIA	N/4		
	Length of hose reel hose	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
7.	Automatic fire detection and alarming system		N/A	N/A		
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A				
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	 Hooters' Location 	N/A N/A	N/A N/A	N/A N/A		
3.	MOEFA					
		IN/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
0.	Automatic Sprinkler System					
	Basement	N/A	N/4			
	Ground Floor	N/A N/A	N/A	N/A		
	Sprinkler above false ceiling		N/A	N/A		
1.	Internal Hydrants	N/A	N/A	N/A		
	Size of riser/down-comer N/A N/A					
	 Number of hydrants per floor 	N/A	N/A	N/A N/A		
	Hose Box	N/A	N/A	N/A		
2.	Yard Hydrants					
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A		N/A		
	Standby Pump Head		N/A	N/A		
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level Discharge 6					
	Discharge of pumpHead of the pump	N/A	N/A	N/A		
	Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
	carring of pump	N/A	N/A	N/A		
4.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	21/4		
	Draw-off connection	N/A		N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A N/A	N/A	N/A		
	Overhead Tank capacity		N/A	N/A		
5.	Exit Signage.	N/A	N/A	N/A		
	-	N/A	N/A	N/A		



9.

20.

6.	Provision of Lifts.			(No Lift)			
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	N/A	N/A	N/A		
		iteman s Grounding Switch	N/A	N/A	N/A		
	- Lin Sig	Lift Signage	N/A	N/A	N/A		
17.	Standb	power supply	N/A	N/A	N/A		
18.	Refuge Area.						
	A	Total Area	N/A	N/A	· N/A		
	>	Location	N/A	N/A	N/A		
19.	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
	•	Battery backup	N/A	N/A	N/A		
	•	Building Floor Plans	N/A	N/A	N/A		
20.		Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/1000 dated 10/05/2019 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer 72012

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

18/6/22

Ozero (S/)

- Theter is

rut up

for sign

16/2 pers

14 (4-0 (k2)

M.S. Coff