

423

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6/DFS/MS/EH/2022/SZ | 1178

Dated 15/06/2022

FIRE SAFETY CERTIFICATE

Certified that **M/s Augment Hospitality LLP located at Property No. HS11, GF, Kailash Colony Main Market, New Delhi 110048** in the building comprised of Ground plus 02 upper floor & restaurant running at ground floor only owned/occupied by **Augment Hospitality LLP** have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 14/05/2022 on in the presence of Mr. Sajeevan (Manager) and that the premise is fit for occupancy class **Group-D Assembly Building** (Restaurant running at Ground Floor only) with effect from 15/06/2022 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15/06/2022 at New Delhi by


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Najafgarh Zone, Najafgarh, Delhi-110043 (MHA Portal No. 202204045371 dated 07/04/2022)
2. **M/s Augment Hospitality LLP located at Property No. HS11, GF, Kailash Colony Main Market, New Delhi 110048**

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (l) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

N/4

INSPECTION REPORT

1	Name & Address of the Building	M/s Augment Hospitality LLP located at Property No HS11, GF, Kailash Colony Main Market, New Delhi 110048		
2	Type of Occupancy	Group-D Assembly Building. (Eating House)		
3	Building Comprised of	Ground plus two upper floors, Restaurant at GF only		
4	Type of Case	New Case		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	14/05/2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Sajeevan (Manager)		
10	Year of construction	1980	Restt. Running at Ground floor.	
11	Applicant letter No.	MHA Portal ID 2022040405371 dated 07/04/2022		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL- 2016	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	6 m N/A N/A	Provided N/A N/A	MR N/A N/A
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase	Restaurant at Ground floor		
	➤ Upper floors.	N/A	N/A	N/A
	➤ Basement floor.	N/A	N/A	N/A
	b) Width of Staircase			
	➤ Upper floors	N/A	N/A	N/A
	➤ Basement floor	N/A	N/A	N/A
	c) Protection of exits			
	➤ Fire check door	N/A	N/A	N/A
	➤ Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	N/A	N/A	N/A
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	1.50 mtr each	1.50 & 1.50 mtr (rear side exit through kitchen)	Provided
3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4	Smoke Management system.			
	<ul style="list-style-type: none"> • Basement • Upper floors 	NA NA	N/A N/A	N/A N/A
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI Marking 	06 Nos ABC/CO ₂ ISI marked	06 Nos ABC-04 & CO ₂ -02 Provided	MR MR MR
6	First Aid Hose Reels.			

N-6

	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	N/A	N/A	N/A
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.			
	• Detector system panel.	N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A
	• PA system panel.	N/A	N/A	N/A
	• Battery backup.	N/A	N/A	N/A
	• Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

Keeping in view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is recommend to issue fire safety certificate.

Signature of the Inspecting Officer
 Name: Sh. Rajesh Kumar
 Designation: ADO (BCP)

~~DO (SD)~~

~~Dir~~
23/07/22

~~DeFO (SD)~~

~~Sh~~
10/6

~~C.F.O.~~
14/6/2022

~~Director~~
18/06/22

~~ADO/BCP~~

F.T. is put up for signature, please.

~~Director~~
15/06/22

16/6/22