

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2022/SZ/182

Dated: 17/06/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Big Chill Café Restaurant located at 2nd Floor, Shop No 311- 314, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 in the building comprised of Two tier Basement, Ground plus Two upper Floors owned/occupied by A Unit of Big Chill Café Pvt Ltd, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2019/SZ/977 dated 09/05/2019. The restaurant premise was re-inspected by the officer concerned of this department on 16/06/2022 in the presence of Mr. Aseem Grover and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant running at 2nd Floor only) as above with effect from 17/06/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/06/2022 at New Delhi by


(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016. (Ref. MHA Portal ID No. 2022051610425 dated 17/05/2022)
3. M/s Big Chill Café Restaurant located at 2nd Floor, Shop No 311- 314, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

| | | | | |
|---------------|---|---|--|-------------------------------|
| 1 | Name & Address of the Building | M/s Big Chill Café Restaurant located at Shop No 311- 314, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 | | |
| 2 | Type of Occupancy | Assembly Building "Group-D" Restaurant | | |
| 3 | Building Comprised of | Two tier Basement, Ground plus Two Upper Floor | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F6/DFS/MS/EH/2019/SZ/977 dated 09/05/2019 | | |
| 6 | Fire Safety Directives Letter No | UBBL-2016 | | |
| 7 | Date of Inspection | 16/06/2022 | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Mr. Aseem Grover | | |
| 10 | Year of construction | 2005 | Restaurant running at 2 nd Floor. | |
| 11 | Applicant letter No. | MHA Portal ID 2022040305305 dated 09/04/2022 | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Requirement | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. FSC No.F.6/DFS/MS/Mall/2020/SZ/58 Dated 22/01/2020 of DLF Promenade Mall | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Restaurant within Mall | As above As above As above | MR N/A N/A |
| 2 | Number, width, type and arrangements of exits. | | | |
| | a. Number of Staircase | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 02 Nos N/A | Provided As above | MR N/A |
| | b. Width of Staircase | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 1.50 mtr N/A | 1.50 mtr each As above | MR N/A |
| | c. Protection of exits | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Fire check door • Pressurization | 1.50 mtr N/A | 1.50 mtr each As above | MR N/A |
| | d. No. of continuous staircase to terrace | Required | As above | MR |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | 1.50 mtr each | 1.50 m & 1.50 m | MR |
| 3 | Compartmentation. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. | Required Required N/A N/A N/A | As above As above N/A N/A N/A | MR MR N/A N/A N/A |
| 4. | Smoke Management system. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Basement • Upper floors | N/A Required | As above Mechanical Ventilation | N/A MR |
| 5. | Fire Extinguishers. | | | |
| | <ul style="list-style-type: none"> • Total numbers • Types • ISI Marking | 04 Nos ISI marked | 06 Nos. ABC-04, W.CO ₂ -02 Provided | MR MR MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> • Total numbers on each floor. • Length of hose-reel hose. • Nozzle Diameter | Hose Reel | One in Restaurant 30m 5mm | MR MR MR |
| 7 | Automatic Fire Detection and Alarming system. (Provided & Maintained by DLF Promenade Mall | | | |
| | <ul style="list-style-type: none"> • Type of detectors | Required | Smoke & Heat | MR |

| | | | | |
|-----|--|--|--------------------|-----|
| | <ul style="list-style-type: none"> Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location | Required | As above | MR |
| | | N/A | N/A | N/A |
| | | Required | As above | MR |
| 8. | MOEFA | Required | As above | MR |
| 9. | Public Address System | Required | As above | MR |
| 10. | Automatic Sprinkler System | Required | As above | MR |
| | | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Basement Upper floors Sprinkler above false ceiling | Required | As above | MR |
| | | Required | Provided in Restt. | MR |
| | | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Size of Riser/Down-comer Number of Hydrant per floor Hose box. | Required | As above | MR |
| | | Required | As above | MR |
| | | Required | As above | MR |
| 12. | Yard Hydrants. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Total number of hydrants. 2. Hose box. | N/A | As above | N/A |
| | | N/A | As above | N/A |
| 13. | Pumping arrangements. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Ground Level | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Discharge of main pump. Head of main pump. Number of main pumps. Jockey Pump output. Jockey Pump head. Standby Pump output. Standby Pump head. Auto Starting / Manual Stopping. Access to pump house | 4500 LPM | As above | MR |
| | | 70 mtrs | As above | MR |
| | | Two | As above | MR |
| | | 180 LPM | As above | MR |
| | | 70 mtrs | As above | MR |
| | | 4500 LPM | As above | MR |
| | | 70 mtrs | As above | MR |
| | | Required | As above | MR |
| | | Required | As above | MR |
| | <ul style="list-style-type: none"> Terrace Level | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Discharge of pump. Head of pump. Power supply. Auto starting of pump. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Underground tank capacity. <ul style="list-style-type: none"> Draw-off connection. Fire Service Inlet. Access to tank. Overhead tank capacity. | 4,50,000 Ltrs | As above | MR |
| | | Required | As above | MR |
| | | Required | As above | MR |
| | | Required | As above | MR |
| | | 30,000 Ltrs | As above | MR |
| | | Required | Provided | MR |
| 15. | Exit Signage. | Provided & Maintained by DLF Promenade Mall | | |
| 16. | Provision of Lifts. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car. Fireman's switch. Lift signage. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 17 | Standby Power Supply | Required | Provided (DG Set) | MR |
| 18. | Refuge Area | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Total area Location | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 19. | Fire Control Room. | Provided & Maintained by DLF Promenade Mall | | |
| | <ul style="list-style-type: none"> Detector System Panel. | N/A | As above | N/A |



| | | | | | |
|-----|---|---------------------|-----|----------|-----|
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | Flow Switch Panel. | N/A | As above | N/A |
| | | PA system Panel. | N/A | As above | N/A |
| | | Battery backup | N/A | As above | N/A |
| | | Building floor plan | N/A | As above | N/A |
| | | | N/A | As above | N/A |

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No F6/DFS/MS/EH/2019/SZ/977 dated 09/05/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Sh. Rajesh Kumar
16/06/22

Signature of the Inspecting Officer
Name : Sh. Rajesh Kumar
Designation: ADO (BCP)

~~DO (South)~~

Sh. Rajesh Kumar
16/06/22

~~DO (S)~~

F.F.

Sh. Rajesh Kumar

Solanki

FP letter is put up for signature please

Sh. Rajesh Kumar

~~DO (S)~~

Sh. Rajesh Kumar

M.S. *Sh. Rajesh Kumar*

uploaded

Sh. Rajesh Kumar
17/06/22