

C-67

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.


No.F.6/DFS/MS/School/2021/SZ/708

Dated: 3/9/21

FIRE SAFETY CERTIFICATE

Certified that the building of Govt. Sarvodaya Co-ed Sen. Sec. School, Possangipur, B-1, Janakpuri, New Delhi - 110058, comprised of two block namely Nalanda and Primary block having ground plus three upper floors & MP Hall having ground floor only and three blocks namely Bismil, Ramanujan, and APJ Abdul Kalam having ground plus one upper floor each was issued Fire Safety Certificate by this department vide letter F.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor). The School building was re- inspected by the officer concerned of this department on 09/08/2021 in the presence of Sh. Kamlesh Meena (HOS) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on.....3/9/21..... at New Delhi.



(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

1. The Principal,
Govt. Sarvodaya Co-ed Sen. Sec. School,
Possangipur, B-1, Janakpuri, New Delhi - 110058.
2. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054.

9/9/21

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/29

School building comprises of five blocks: Blocks namely Bismil, Ramanujan, Dr.A.P.J.Abdul Kalam having ground plus one upper floor and Nalanda & Primary block having Ground plus three upper floors and MP Hall having ground floor only (Govt. Sarvodaya Co-ed Senior Secondary School, Possangipur, B-1, Janakpuri, New Delhi - 110058)

INSPECTION REPORT

1. Name & address of the building : Govt. Sarvodaya Co-ed Sen. Sec. School, Possangipur, B-1, Janakpuri, ND - 110058
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor)
5. Fire Safety directives letter No : N/A
6. Date of inspection : 09/08/2021
7. Name of Inspecting Officer : A.D.O. R.K.Yadav
8. Name and designation of officers
From the building side : Sh. Kamlesh Meena (HOS)
9. Year of Construction : Before 2011 & 2016-17
10. Applicant's letter No. : Letter No. 727 dated 06/08/2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible 4.5 m —	09 m provided —	M/R — —
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	10 No's N/A	10 No's N/A	M/R N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.50 m N/A	1.75 m (3 No.'s in Nalanda blk), 1.75 m (1 No. in Prmy blk), 1.37&1.60 in Bismil blk, 1.57 x 2 in APJ blk, 1.40 & 1.64 m in Ramanujan blk N/A	M/R N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A N/A	N/A N/A	N/A N/A
	d. No. of continuous staircases to terrace			
	e. Width of Corridor	Required	Provided	N/A
		1.5 m	1.75 m	M/R
	f. Door Size	1.0 & 2.0 in MP Hall	.97 to 1.12 m (Double Door) & 2.08 (2 No.'s) & 1.35 (4 no.'s) in MP hall	M/R
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	N/A N/A	N/A Natural Ventilation	N/A M/R
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	30 no's ABC/CO ₂ type ISI marked	Provided Provided ISI marked	M/R M/R M/R

School building comprises of Five blocks: Blocks namely Bismil, Ramanujan, Dr. A.P.J. Abdul Kalam having ground plus one upper floor and Nalanda & Primary block having Ground plus three upper floors and MP Hall having ground floor only (Govt. Sarvodaya Co-ed Senior Secondary School, Possangipur, B-1, Janakpuri, New Delhi - 110058)

16.	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor) renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

R.K. Yadav
13/08/2021

Signature of Inspecting Officer
Name:- R.K. Yadav
Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

K. Yadav
13/08/2021

Dy CFO (S2) F.F.

[Signature]

AOP (OKP)

F T letter & put up for sign. please

Dy CFO (S2) *[Signature]* 13/08/2021