

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/WZ/ 8/0

Dated: 4/10 (21

Garg)

Director Delhi Fire Service

FIRE SAFETY CERTIFICATE

Issued on _____ (o [2-1 _____ at New Delhi by

Copy to: -

- 1. The Principal, Govt. Co-ed Sec. School located at J.J. Colony-2, Nangloi, New Delhi-110041.
- 2. The Director of Education, NDMC, Civic Centre, Minto Road, New Delhi.


Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the means of escape/entry/exit shall be herein shall be maintained in good working
 All the fire safety arrangements provided therein shall be maintained in good working
- 2. All the fire safety arrangements provided differences of life or property due to noncondition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This Certificate cannot be treated as regularization of unauthorized construction, if any.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on <u>www.dfs.delhigovt.nic.in</u>.

N1.27

1		INSP	ECTION						
1	Name	& Address of the Building	COVE Concello	Γ					
2		f Occupancy	Govt. Co-ed Sec. School located at J.J. Colony-2, Nangloi, New Delhi-110041.						
3	Duildin	TOccupancy	Group-B, "Educational Building" (School)						
	Tunui	ng Comprised of	Ground plus three upper from (School)						
4	Type o		Ground plus three upper floors New						
5	Details	of Previous NOC	NBC Part-IV						
6	Fire Sa	fety Directives Letter No							
7	Date of	Inspection	Nil 15/09/2021						
8	Name of the Inspecting Officers								
9	Name	& Designation of Officers	ADO Aman Kumar Lathar Mr. Rambir (Estate Manager)						
10	nom u	e Manager)							
		f construction							
11	Applic	ant letter No.	Email date 27/08/2021						
S. No	Minimum standards on Fire Prevention		DOE Circular Provided at Site Remarks						
110	and Fli	re Safety U/R 33	date 17/01/2015	i i ovideu at Site	MR/NMR				
1	Access	to Building.	Requirements		(old case)				
	•	Road width							
		Gate width	6 m	6 m	MR				
		Width of internal road	4.5 m	4.5 m	MR				
2	Numb		-N/A-	-N/A-	-N/A-				
-	a) Nu	er, width, type & arrangement	of exits.						
		mber of Staircase							
		Upper floors Basement floor	2	4	MR				
			-N/A-	-N/A-	-N/A-				
	b) Width of Staircase								
		Upper floor		1^{st} block- 1.35 m × 2,					
			1.50 m	1.40 m × 1& 1.38 m × 1	MR (old case)				
	A	Province of C							
		Basement floor	-N/A-	-N/A-	-N/A-				
		tection of exits							
	A .	Fire check door	-N/A-	-N/A-	-N/A-				
	>	Pressurization	-N/A-	-N/A-	-N/A-				
	d) No. of continuous staircase to		1	1					
ŀ	e) Wid	ace 1th of corridor			MR				
ŀ		or size	1.50 m	1.50 m	MR				
3	Compartmentation.		1.00 m × 2	Provided	MR				
	-								
		Fire check door.	-N/A-	-N/A-	-N/A-				
		Sealing of electrical shafts. Fire rating of shaft door.	-N/A-	-N/A-	-N/A-				
		Water curtain	-N/A-	-N/A-	-N/A-				
		Fire dampers.	-N/A-	-N/A-	-N/A-				
		_	-N/A-	-N/A-					
4.	Smoke	Management system.		- ··· •	-N/A-				
	• 1	Basement	-N/A-	-N/A-	N 1/ -				
	1	Jpper floors	-N/A-	-N/A-	-N/A-				
5.		tinguishers.		-1 N/ A-	-N/A-				
	Fire Ex	eniguistici s.							
		Total numbers	40 pos	80 700					
	•		40 nos	80 nos	MR				
	•	Total numbers	40 nos ABC/CO ₂ ISI Marking	80 nos Provided Provided	MR MR				

1. N. 1970 -



-N/A-

-N/A-

17	Standby Power Supply		1-1-28	
18.	Refuge Area	-N/A-	-N/A-	NI/A
19.	 Total area Location Fire Control Room.	-N/A- -N/A-	-N/A- -N/A-	-N/A-
	Detector System Panel.Flow Switch Panel.	-N/A-	-N/A-	-N/A
	PA system Panel.Battery backupBuilding floor plan	-N/A- -N/A-	-N/A- -N/A-	-N/A
20.	Special Fire Protection System 6	-N/A- -N/A-	-N/A- -N/A-	-N/A -N/A
	the Protection of special Risk, if any.	-N/A-	-N/A-	-N/A

Note: - The Principal submitted undertaking that they will not accommodate more than 40 students in single door rooms.

The fire protection system provided in the building were randomly tested/ checked and found functional at the time of inspection.

The shortcoming issued by this department vide letter No. F/6/DFS/MS/School/2017/220 dated 20/01/2017 has been compiled by the building management.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature please.

23/8/221

122

Signature of the Inspecting Officer Name : Aman Kumar Lather Designation: ADO (JWP)

DO (WD)

Quectos

142

Jon Muy Sur F.T. letter is mit-up for mignature