

947

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/School/2022/SZ/ 699

Dated: 23/06/2022

**FIRE SAFETY CERTIFICATE**

Certified that **Century Public School** located at Opp. Ambedkar Colony, Bijwasan, New Delhi-110061 comprised of ground plus three upper floors (3<sup>rd</sup> Floor two rooms only) **School running at Ground plus two upper floor** owned/occupied by Century Public School, was issued NOC by this department vide letter No. F6/DFS/MS/School/2019/SZ/619 Dated 26-03-2019. The premises was re-inspected by officer concerned of this department on 17/06/2022 in presence of Sh. Yogesh Dagar (Manager) of the school and found that said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. 262-362 dated 17/01/2005 issued by Education Directorate, Govt. of NCT of Delhi and that the premises is fit for occupancy class "**Educational Building**" Group-B with effect from 23/06/2022 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 23/6/2022 at New Delhi by

  
(SUNIL CHAWDHARY)

DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

1. Principal, Century Public School, Opp. Ambedkar Colony, Bijwasan, New Delhi-110061
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

115

### INSPECTION REPORT

1	Name & Address of the Building	Century Public School, Opp. Ambedkar Colony, Bijwasan, New Delhi-110061		
2	Type of Occupancy	Educational, Group-B (School)		
3	Building Comprised of	Ground + 03 upper floors (school running of G+2 Upper Floors Only) 3 <sup>rd</sup> Floor Two Rooms not in used		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/School/2019/SZ/619 Dated 26-03-2019 for ground plus two upper floor		
6	Fire Safety Directives Letter No	DOE Circular No. 262-362 dated 17/01/2005		
7	Date of Inspection	17-06-2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Yogesh Dagar (Manager)		
10	Year of construction	2009		
11	Applicant letter No.	CPS/2022/05/1143 dated 30/05/2022		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	As Per Old NOC	Provided at Site	Remarks MR/NMR
1	<b>Access to Building.</b>			
	• Road width	6 mtr	Provided	MR
	• Gate width	-NA-	-NA-	-NA-
	• Width of internal road	-NA-	-NA-	-NA-
2	<b>Number, width, type &amp; arrangement of exits.</b>			
	<b>a) Number of Staircase</b>			
	➤ Upper floors.	01 No	02 Nos	MR
	➤ Basement floor.	-NA-	-NA-	-NA-
	<b>b) Width of Staircase</b>			
	➤ Upper floors	1.5m / 0.75m	1.05m & 1.04m	MR
	➤ Basement floor	-NA-	-NA-	-NA-
	<b>c) Protection of exits</b>			
	➤ Fire check door	-NA-	-NA-	-NA-
	➤ Pressurization	-NA-	-NA-	-NA-
	<b>d) No. of continuous staircase to terrace</b>	One	Two	MR
	<b>e) Width of corridor</b>	1.5 mtr	Provided	MR
	<b>f) Door size</b>	1 mtr	1m	MR
3	<b>Compartmentation.</b>			
	• Fire check door.	-NA-	-NA-	-NA-
	• Sealing of electrical shafts.	-NA-	-NA-	-NA-
	• Fire rating of shaft door.	-NA-	-NA-	-NA-
	• Water curtain	-NA-	-NA-	-NA-
	• Fire dampers.	-NA-	-NA-	-NA-
4	<b>Smoke Management system.</b>			
	• Basement	30 a/c per hour	-NA-	-NA-
	• Upper floors	12 a/c per hour	-NA-	-NA-
5	<b>Fire Extinguishers.</b>			
	• Total numbers	Required	08 Nos	MR
	• Types	ABC / CO2	ABC & CO2	MR
	• ISI Marking	ISI mark	Provided	MR
6	<b>First Aid Hose Reels.</b>			
	• Total numbers on each floor.	One	Provided	MR
		30m	Provided	MR





N/17

	• Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-


<b>19</b>	<b>Fire Control Room.</b>			
	• Detector system panel.	-NA-	-NA-	-NA-
	• Flow switch panel.	-NA-	-NA-	-NA-
	• PA system panel.	-NA-	-NA-	-NA-
	• Battery backup.	-NA-	-NA-	-NA-
	• Building floor plan.	-NA-	-NA-	-NA-

**20 Special Fire Protection System for the Protection of special Risk, if any.**

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular, the FSC issued vide letter No. F6/DFS/MS/School/2019/SZ/619 Dated 26-03-2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.


Accordingly DFA is put up for approval and signature please.

  
 Signature of the Inspecting Officer  
 Name: Rajesh Kumar  
 Design: ADO (BCP)

~~DO (SD)~~

*Dir P*  
*22/06/22*


~~DO (SD)~~

*F.T.*  


*ADO (BCP)*

*As approved, f.t. letter is put up for your notice pl*

*1/1/22*  
*28/6*

*Dr. Vats*  


*M.S. Ull*