

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/School/2022/ 755

Datedy3 / 7 /2022

FIRE SAFETY CERTIFICATE

Issued on . (.3.17........ at New Delhi by

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph:-011-23414250

Copy to:-

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Govt. Sarvodaya Vidyalaya No-03, (I.D No-1207011) located at Shakti Nagar, Delhi-110007

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

M122 INSPECTION REPORT : Sarvodaya Sarvodaya Vidyalaya School No-3, Shakti Nagar, Delhi-07 Name& address of the building : Educational Type of Occupancy : Single blocks (Ground plus 03 upper floors) 3. Composition of building : Renewal 4. Type of Case : F6/DFS/MS/School/2019/1473 Dated: 18.07.2019 5. Details of previous NOC 6. Fire Safety directives letter No : 02.07.2022 Date of inspection : ADO (RN) 8. Name of the Inspecting Officers 9. Name and designation of officers : Sh. Amit Saini (Principal) from the building side : 1968 10. Year of Construction : GSV.NO.03/22-23/140 dated:21.06.2022 11. Applicant's letter No. No of students---700nos No.of class rooms -22nos. Covered Area:773sqm Plot Area-3122sqm Remarks Provided at site Minimum Standards on fire prevention and **NBC** MR/NMR Requirement fire safety U/R 33 Access to building 1 MR 06m 06m Road width MR 4.5m Gate width 4.5m NA Width of internal road NA NA Number, Width, Type & Arrangement of Exits 2

a. Number of staircases			
Upper Floors	02	02	MR
• Basements	NA	NA	NA
b. Width of staircases			
Upper Floors	1.5 m	2.1m &1.5 m	MR
Basements	NA NA	NA	NA
c. Protection of exits			
Fire check door	NA	NA	NA
 Pressurization 	NA	NA	NA
d. No. of continuous staircases to terrace	NA	NA	NA
e. Width of Corridor	02m	2.46m	MR
f. Door Size	1 m	lm	MR
	1 111	1111	14114
Compartmentation.			
	NA	NA	NA
Fire check door		NIA	NA
 Sealing of electrical shafts 	NA	NA	NA
Fire Rating of shaft door	NA	NA	NA
Water Curtain	NA	NA	NA
Fire Dampers	NA	NA	NA
Smoke Management System.			
Basements	12a/c per hour	NA	NA
 Upper floors 	12 a/c per hour	Natural Ventilated	MR
Fire Extinguishers			
	12nos	12nos	MR
Total numbers	A D C / C - 2	100 07	

ABC/Co2

ABC---27

MR

3

4

5

Types

	H125			Car
		ISI Marked	Provided	MR
	ISI marking	151		
	First-Aid Hose Reels.	0.1	01	MR
6	Total numbers on each floor	01	30m	MR
	• Length of hose reel hose	30m		MR
	Nozzle diameter	5mm	5mm	VIIX
	Nozzle diameter Automatic fire detection and alarming system.		NA	NA
7	Automatic fire detection and unit in g	NA	NA NA	NA
	Type of detectorsLocation of Main Panel	NA	NA NA	NA
		NA	INA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location		NA	NA
8	MOEFA	NA		
9	Public Address System.			
10	Automatic Sprinkler System.		NA	NA
	Basement	NA NA	NA NA	NA
	Upper Floor		NA	NA
	a i ll shave folse ceiling	NA		
	Sprinkler above laise certaing Internal Hydrants			NA
11	c: Griser/down comer	NA	NA	NA NA
	Number of hydrants per floor	NA	NA	NA NA
	Hose Box	NA	NA	NA
	Yard Hydrants.			NA
12	To all weeker of hydrants	NA	NA	
		NA	NA	NA
	Hose Box			
13	Pumping Arrangements.			
	Ground Level		20/4	N/A
	Discharge of main Pump	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	NA	NA	NA
	> Jockey pump head	NA	NA	NA
	> Standby Pump out put		N/A	N/A
	> Standby Pump Head	N/A		
	Auto Starting/ Manual stopping Pump House Access	N/A	N/A	N/A
	Terrace level	N/A	N/A	N/A
	> Discharge of pump			
	> Head of the pump	450lpm	450lpm	MR
	> Power Supply	40m	40m	MR
	> Auto Starting of pump	Required	Provided	MR
		Required	Provided	MR
	Captive Water Storage for fire fighting.			
4		NA	NA	NA
4	 Underground tank canacity 		1	
4	Underground tank capacity Draw-off connection	NA	NA	NA
4	 Underground tank capacity Draw-off connection Fire service inlet 	NA NA	NA NA	NA NA

3	Overhead Tank capacity	10,000ltrs	Provided	MR			
5	Exit Signage.	Required	Provided	MR			
	Provision of Lifts.						
	n wingtion of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift CarFireman's Grounding Switch	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
Refuge Area. Total Area Location	Refuse Area.						
		N/A	N/Λ	N/A			
		N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backupBuilding Floor Plans	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/Λ	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no.249 dated 26.05.2022.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, the FSC issued vide letter of even no.1473 dated 18.07.2019 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer Name: - C.L. Meena Designation:- ADO/RN

s approved F.T. letter is leatup for your