GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No. F6/DFS/MS/School/2022 / 752

Dated: 3 / 7 /2022

FIRE SAFETY CERTIFICATE

Certified that the Radiant Brain Global School located at Khasra No. 246, Gali No.09, Block-B, Pradeep Vihar, Nathupura, Delhi-110084 comprised of Ground floor only owned/ occupied by owned/ occupied by Radiant Brain Global School have complied with the fire prevention and safety requirements in accordance with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and verified by the officer concerned of Fire Service on 04.06.2022 in the presence of Mrs. Ruchi (Principal) and that the building/premises is fit for occupancy "Group B Educational" with effect from for a period of three years, subject to compliance of the conditions mentioned below:

Issued on at New Delhi

Ph: 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Radiant Brain Global School located at Khasra No. 246, Gali No.09, Block-B, Pradeep Vihar, Nathupura, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first of Delhi Fire Service Rules 2010. The form http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: Radiant Brain Global School at Kh. No.-246, Gali No.09, Block-B,

Pradeep Vihar, Nathupura, Delhi-110084.

2. Type of Occupancy

: Educational

3. Composition of building

: Ground Floor Only

4. Type of Case

: New Case

5. Details of previous NOC

: Nil

6. Fire Safety directives letter No

: Director of Education Letter dated 01.03.2011

7. Date of inspection

8. Name of the Inspecting Officers: ADO (RN)

: 04.06.2022

9. Name and designation of officers

from the building side

: Mrs. Ruchi (Principal)

10. Year of Construction

: 2021

od: 23.05.2022 & DES Dairy No. 1661 Dated: 23.05.2022

		d area225sq.yard	No of student	Provided at site	s room =03±01 Remarks			
	Minimum Standards on fire fire safety U/R 3		D 0	Provided at site	MR/NMI			
	ine salety of K	,5	Circular					
	Access to building							
	Road width		06m	06m	MR			
	Gate width		05m	05m	MR			
	Width of internal road		NA	NΛ	NA			
_	Number, Width, Type & Arra	ngement of Exits						
	a. Number of staircases							
	Upper Floors		NA	NA	NA			
	 Basements 		NA	NA	NA			
	b. Width of staircases	_						
	Upper Floors		NA	NA	NA			
	• Basements		NA	NA	NA			
	c. Protection of exits	-						
	Fire check door	-	NA	NA	NA			
	 Pressurization 		NA	NA	NA			
	d. No. of continuous staircases to	terrace	NA	NA	NA			
	e. Width of Corridor		NA	NA	NA			
	f. Door Size		1.20m	1.20m	MR			
	Compartmentation.							
	Fire check door		NA	NA	NA			
	Sealing of electrical shaft	ts	NA	NA	NA			
	Fire Rating of shaft door	-	NA	NA	NA			
	Water Curtain		NA	NA	NA			
	• Fire Dampers		NA	NA	NA			
	Smoke Management System.							
	Basements		12 a/c per hour	No basement	NA			
	Upper floors		12 a/c per hour	Natural Ventilated	MR			
	Fire Extinguishers							



• Types		ABC/Co2	ABC03	MR		
ISI marking		Yes	Yes	MR		
First-Aid Hose Reels.						
L	ach floor	NA	NA	NA		
Total numbers on e Length of hose reel		NA	NA	NA		
	nose		NA	NA		
Nozzle diameter		NA	IVA	INA		
	Automatic fire detection and alarming system NA NA NA					
Type of detectors		NA NA	NA	NA NA		
Location of Main P		NA NA	NA	NA ·		
Location of Repeat						
Alternate source of	power	NA	NA	NA		
Hooters' Location		NA	NA	NA		
MOEFA		NA	NA	NA		
Public Address System.		NA	NA	NA		
Automatic Sprinkler Syste	Automatic Sprinkler System.					
Basement		NA	NA	NA		
Upper Floor		NA	NA	NA		
Sprinkler above fa	lse ceiling	NA	NA	NA		
•		INA	177			
Internal Hydrants		NA	NA	NA		
Size of riser/downNumber of hydran		NA NA	NA NA	NA NA		
Hose Box	15 per 11001	NA	NA	NA		
Yard Hydrants.						
		NA	NA	NA		
Total number of h	ydrants					
Hose Box		NA	NA	NA		
	Pumping Arrangements.					
Ground Level						
Discharge of r		N/A	N/A	N/A		
➤ Head of Main		N/A	N/A	N/A		
Number of maJockey Pump		N/A	N/A	N/A		
Jockey PumpJockey pump		N/A	N/A	N/A		
> Standby Pump		N/A	N/A	N/A N/A		
> Standby Pump	-					
➤ Auto Starting/	Manual stopping	N/A	N/A	N/A		
> Pump House	Access	N/A	N/A	N/A		
• Terrace level		N/A	N/A	N/A		
Discharge of						
➤ Head of the p	•	NA	NA	NA		
> Power Suppl	,	NA	NA	NA		
Auto Starting	g of pump	NA	NA	NA		
		NA	NA			
14 Captive Water Storage for	or fire fighting.	1771	INA.	NA		
	Inderground tank canonity					
> Draw-off connect		NA	NA	NA		
Fire service inlet		NA	NA	NA		
		NA	NA	NA		

MR

NΑ

NA NA NA

NA

NA

		Access to tank	NA	NΛ	NΛ		
		Overhead Tank capacity	NA	NΛ	NA		
15	Exit Sign	age.	NA	NA	NA		
6	Provision of Lifts.						
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
		Pressurization of Lift lobby	N/A	N/A	N/A		
		Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A			
		N/A	N/A	N/A			
17	Standby	power supply	N/A	N/A	N/A		
18	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	4	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
	•	Batter backup	N/A	N/A	N/A		
	•	Building Floor Plans	N/A	N/A	N/A		
20	Special F	ire Protection Systems for n of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Birector of education Circular dated 01.03.2011, fire safety certificate is recommended.

Signature of the Inspecting Officer

Name : C.L. Meena Designation:- ADO/RN

Cent .. Ps.o.