# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/MS/School/WZ/2022 | 76 /

Dated: / 5 / 7/2022

HUTTED C-31

### FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Co-ed Vidyalaya (School ID- 1516104), located at H- Block, Karampura, New Delhi-110015, comprised of Total 4 Blocks, (3 Blocks Ground + 1 & 1 Block Ground Floor Only) A, C & D Block = G + 1 Upper floor & B Block = Ground Floor Only. Owned/Occupied by Govt. Sarvodaya Co-ed Vidyalaya, was issued FSC vide Letter No:- F6/DFS/MS/WZ/2019/1025 Dated 15/05/2019. The premises was reinspected by the officer concerned of this department on 29/06/2022 in the presence of M/s. Rakesh Kumar Sharma (Estate Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 and that the premises is fit for occupancy class "Educational" Group B with effect from  $\frac{1}{2}$  for a period of three years subject to compliance of the conditions mentioned below.

(Dharampal Bhardwaj) Dy. Chief Fire Officer West Zone

#### Copy to:

- 1. The Principal, M/s. Govt. Sarvodaya Co-ed Vidyalaya, (School ID-1516104) located at H-Block, Karampura, New Delhi-110015.
- 2. Director of Education, GNCT of NCT of Delhi, Old Secretariat.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. Fire fighting system which is provided in the building should be working condition for children's safety.

N/20 1 INSPECTION REPORT 1. Name & address of the building : Govt. Sarvodaya Co-ed Vidyalaya, (School ID- 1516104), Located at H- Block, Karampura, New Delhi – 110015. 2. Type of Occupancy : Educational Total 4 Blocks, (3 Blocks Ground + 1 & 1 Block Ground Floor Only) A, C & D Block = G + 1 Upper floor & B -Block = Ground Floor Only. 3. Type of Case : Renewal 4. Details of previous NOC : F6/DFS/MS/WZ/2019/1025 dated 15/05/2019 5. Fire Safety directives letter No : 3298-3398 dated 01/03/2011 6. Date of inspection : 29/06/2022 7. Name of the Inspecting Officers : Sh. Sarabjeet Singh ADO (MN) 8. Name and designation of officers from the building side : Sh. Rakesh Kumar Sharma (Estate Manager) 9. Year of Construction : 1960, D- Block in 2013 as per prev. insp. report dated 06/05/2019 10. Applicant's letter No. : Outdoor Diary No. 2320 dated 09/06/2022 S. Minimum Standards on fire Cr. No.3298-3398 dtd. **Provided** at site Remarks No. prevention and fire safety 01/03/2011/As per prev. MR/NMR U/R 33 insp. report dated 06/05/2019 1 Access to building Road width 6m Provided MR Gate width 4.5 m Provided MR Width of internal road NA NA NA 2 Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Required Provided MR (old case) Basements NA NA NA b. Width of staircases Upper Floors 1.5m A-BLK = 2 X 163 cms, MR (old C-BLK=1X145cms. case) D-BLK.=1X154 cms C & D BLK. are connected with each other through corridor Basements NA NA NA c. Protection of exits NA Fire check door NA NA Pressurization NA NA NA e. Not of continuous staircases to terrace NA NA NA f. Width of Corridor 1.5m Provided MR g. Door Size 1 mtr Provided MR 3 Compartmentation. Fire check door NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4 Smoke Management System. NA **Basements** NA NA NA Upper floors NA NA



14

ap/

5	Fire Extinguishers	22 nos.	29 Provided	MR		
	<ul> <li>Total numbers</li> </ul>	$CO_2$ , ABC type	Provided	MR		
	• Types	ISI marked	Provided	MR		
	IS marking					
6	First-Aid Hose Reels. NA Provided					
	Total numbers on each floor	NA	Provided	NA		
	<ul> <li>Length of hose reel hose</li> </ul>	NA	Provided	NA		
	Nozzle diameter		Tiovided			
7	Automatic fire detection and alarming system.					
	• Type of detectors	NA		NA		
	Location of Main Panel	NA	NA	NA		
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	NA	NA NA		
	• Alternate source of power	NA	NA NA	NA		
	Hooters' Location	NA				
8	MOEFA	NA	NA	NA		
9	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
10		NA	NA	NA		
		NA	NA	NA		
	Upper Floor     Sprinkler above false ceiling	NA	NA	NA		
11	Sprinkler above false ceiling					
11	Internal Hydrants	NA	NA	NA		
	• Size of riser/down-comer	NA	NA	NA		
	• Number of hydrants per floor	NA NA	NA	NA		
	Hose Box					
12	Yard Hydrants.			NA		
	• Total number of hydrants	NA	NA			
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
	Ground Level		·			
	<ul> <li>Discharge of main Pump</li> </ul>	NA	NA	NA		
	Head of Main pump	NA	NA	NA		
	Number of main pumps	NA	NA	NA		
	Jockey Pump out put	NA	NA NA	NA NA		
	> Jockey pump head	NA		NA NA		
	Standby Pump out put	NA	NA NA	NA NA		
	<ul> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> </ul>	NA NA	NA	NA NA		
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>		NA	NA		
		NA	INA	11/1		
	Terrace level	NR	2 x 450 lpm Provided	NR		
	<ul><li>Discharge of pump</li></ul>	INIX	but not functional			
	> Head of the pump	NR	40 m Provided	NR		
	Power Supply	NR	Provided	NR		
	Auto Starting of pump	NR	Provided	NR		

)			Andfika Mahotsav			
14	Captive Water Storage for fire fighting.					
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	NA	NΛ	NΛ		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	<ul> <li>Overhead Tank capacity</li> </ul>	NA	NA	NA		
15		NR	10,000 ltr Provided	NR		
	Exit Signage.	NR	NR	NR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	<ul> <li>Pressurization of Lift lobby</li> </ul>	NA	NA	NA		
	Communication In lift Car	NA	NA	NA		
	<ul> <li>Fireman's Grounding Switch</li> </ul>	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	NR	NR	NR		
18	Refuge Area.					
	> Total Area	NA	NA	NA		
	> Location	NA	NA	NA		
19	Fire Control Room					
	Detector System Panel	NA	NA	NA		
	Flow Switch Panel	NA	NA	NA		
	PA System Panel	NA	NA	NA		
	Batter backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection Systems for	NA	NA	NA		
	Protection of special Risks, if any:					

N122

MR MR MR

## Note: - Fire fighting system which is provided in the building should be working condition for children's safety.

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/WZ/2019/1025 dated 15/05/2019 renewal under DOE Circular no. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Directorate of Education, Govt. OF NCT of Delhi, is recommended.

Ho west 04107/02 Signature of the Inspecting Office r Name: Sarabjeet Singh Designation: ADO (MN) D.O (MEST)/. DATED.0.4/07 is put up for your persual & Another plant. Sir, F.T