

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6/DFS/MS/EH/2022/SZ/ 204

Dated. 13/7/2022

FIRE SAFETY CERTIFICATE

Certified that **M/s Sky High** (A Unit of Tanuk Hospitality Pvt Ltd) located at **TF-11, 3rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070** in the building comprised of Two tier Basement, lower ground, upper ground plus 03 upper floors owned/occupied by Tanuk Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of department on 07/07/2022 in the presence of Sh. Manoj Kumar and that the premise is fit for occupancy class **Group-D Assembly** (Eating House running at 3rd Floor only) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/7/2022 at New Delhi by

(ATUL GARG)
DIRECTOR

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2022061813119 dated 22/06/2022)
3. M/s Sky High (A Unit of Tanuk Hospitality Pvt Ltd) located at TF-11, 3rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

N/A

INSPECTION REPORT

1	Name & Address of the Building	M/s Sky High (A Unit of Tanuk Hospitality Pvt Ltd) located at TF-11, 3 rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	Two tier Basement, lower ground, upper ground plus 03 upper floors (Restaurant running at 3rd floor)		
4	Type of Case	New Case		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2005/2251 dated 28/10/2005 F.6/DFS/MS/Mall/2020/SZ/12 Dated 09/01/2020 (Vasant Square Mall NOC)		
7	Date of Inspection	07/07/2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Manoj Kumar		
10	Year of construction	2005		
11	Applicant letter No.	MHA Portal Id 2022061813119 dated 22/06/2022		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No. F.6/DFS/MS/Mall/2020/SZ/12 Dated 09/01/2020 Vasant Square Mall			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	<ul style="list-style-type: none"> Restaurant within Mall NA 	<ul style="list-style-type: none"> As above As above As above 	<ul style="list-style-type: none"> MR N/A N/A
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Upper floors Basement floor 	<ul style="list-style-type: none"> 08 Nos N/A 	<ul style="list-style-type: none"> Provided * As above 	<ul style="list-style-type: none"> MR N/A
	b. Width of Staircase	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Upper floors Basement floor 	<ul style="list-style-type: none"> 1.50 mtr each N/A 	<ul style="list-style-type: none"> Provided * As above 	<ul style="list-style-type: none"> MR N/A
	c. Protection of exits	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Fire check door Pressurization 	<ul style="list-style-type: none"> Required N/A 	<ul style="list-style-type: none"> Provided * As above 	<ul style="list-style-type: none"> MR N/A
	d. No. of continuous staircase to terrace	08 Required	Provided *	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	1.50 m each	1.50 m & 1.50 m	MR
3	Compartmentation.	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	<ul style="list-style-type: none"> Required Required 2 hrs N/A N/A 	<ul style="list-style-type: none"> Provided * Provided * Provided* N/A N/A 	<ul style="list-style-type: none"> MR MR MR N/A N/A
4.	Smoke Management system.	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Basement Upper floors 	<ul style="list-style-type: none"> N/A Required 	<ul style="list-style-type: none"> As above Exhaust fans provided 	<ul style="list-style-type: none"> N/A MR
5.	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	<ul style="list-style-type: none"> 04 Nos ISI marked 	<ul style="list-style-type: none"> 06 Nos. ABC-04, W.CO₂-02 Provided 	<ul style="list-style-type: none"> MR MR MR
6.	First Aid Hose Reels.	Provided & Maintained by Vasant Square Mall		
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	Hose Reel	<ul style="list-style-type: none"> 02 in Restaurant 30m 5mm 	<ul style="list-style-type: none"> MR MR MR

N/2



7	Automatic Fire Detection and Alarming system. (Provided & Maintained by Vasant Square Mall)			
	• Type of detectors	Required	Smoke & Heat	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided *	MR
	• Hooter's location	Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System	Provided & Maintained by Vasant Square Mall		
	• Basement	Required	As above	MR
	• Upper floors	Required	Provided in Restt.	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.	Provided & Maintained by Vasant Square Mall		
	• Size of Riser/Down-comer	Required	Provided *	MR
	• Number of Hydrant per floor	Required	Provided *	MR
	• Hose box.	Required	Provided *	MR
12.	Yard Hydrants.	Provided & Maintained by Vasant Square Mall		
	• Total number of hydrants.	N/A	As above	N/A
	• 2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.	Provided & Maintained by Vasant Square Mall		
	• Ground Level	Provided & Maintained by Vasant Square Mall		
	➤ Discharge of main pump.	4500 LPM	Provided *	MR
	➤ Head of main pump.	60 mtr	Provided *	MR
	➤ Number of main pumps.	Two	Provided *	MR
	➤ Jockey Pump output.	2 x 180 LPM	Provided *	MR
	➤ Jockey Pump head.	60 mtr	Provided *	MR
	➤ Standby Pump output.	4500 LPM	Provided *	MR
	➤ Standby Pump head.	60 mtr	Provided *	MR
	➤ Auto Starting / Manual Stopping.	Required	Provided *	MR
	➤ Access to pump house	Required	Provided *	MR
	• Terrace Level	Provided & Maintained by Vasant Square Mall		
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Vasant Square Mall		
	• Underground tank capacity.	2,50,000 Ltr	Provided *	MR
	➤ Draw-off connection.	Required	Provided *	MR
	➤ Fire Service Inlet.	Required	Provided *	MR
	➤ Access to tank.	Required	Provided *	MR
	• Overhead tank capacity.	30,000 Ltr	Provided *	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Provided & Maintained by Vasant Square Mall		
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area	Provided & Maintained by Vasant Square Mall		
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19.	Fire Control Room.	Provided & Maintained by Vasant Square Mall		
	• Detector System Panel.	N/A	As above	N/A

N/R

20.	Special Fire Protection System for the Protection of special Risk, if any :	Flow Switch Panel.	N/A	As above	N/A
		PA system Panel.	N/A	As above	N/A
		Battery backup	N/A	As above	N/A
		Building floor plan	N/A	As above	N/A
			N/A	As above	N/A

Note: - * Provided & Maintained by Management of Vasant Square Mall, Vasant Kunj, New Delhi
 The Fire protection systems provided in the building were tested checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

RK
8/7/22

Signature of the Inspecting Officer
 Name: Rajesh Kumar
 Designation: ADO / BCP

Dy. CFO (SZ)

RK
8/7

C.F.O. *RK*
11/7/2022

~~Director *RK*
11/10/22~~

ADO BCP

F.A. letter is put up for signature, please.

~~Director *RK*
11/10/22~~

RK
11/7/22

uploaded