~ M



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

## **NEW DELHI- 110001**

No.F6/DFS/MS/School/2022/SZ/ 788

Dated: 27/7/22

FIRE SAFETY CERTIFICATE

Certified that the West Point Model School, 12, Om Vihar, Phase-III, Uttam Nagar, New Delhi-110059, comprised of ground plus three upper floors was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2019/SZ/1319 dated 20/06/2019. Owned/occupied by West Point Model School. The school building was re-inspected by the officer concerned of this department on dated 08/07/2022 in the presence of Sh. Rajesh Tondon (Manager) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 35 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on  $\frac{27}{7}/\frac{22}{2}$  at New Delhi.

(SUNIL CHAWDHARY)

DY. CHIEF FIRE OFFICER

DELHI FIRE SERVICE

901/-

Copy to:-

1. The Principal,

West Point Model School, 12,Om Vihar, Phase-III, Uttam Nagar, New Delhi-110059.

2. Director of Education,

GNCT of NCT of Delhi, Old Secretariat, Delhi-110054.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: West Point Model School, 12, Om Vihar, Phase-III, Uttam Nagar, New Delhi-110059 Building comprised of ground plus three upper floors. Type of Occupancy Educational Type of Case 4. Renewal 5. Details of Previous NOC F.6/DFS/MS/School/2019/SZ/1319 dated 20/06/2019 6. Fire Safety directives letter No 7. Date of inspection 08/07/2022 8. Name of Inspecting Officer A.D.O. R.K. Yadav Name and designation of officers From the building side Sh. Rajesh Tandon (Manager) 10. Year of Construction 1995-96 (G+I) & 2011-12 (SF & TF) 11. Applicant's letter No. WP/ADM/1147/2022 dated 12/05/2022 Minimum Standards on fire prevention and S. No. Remarks Provided at NBC/BBL fire safety U/R 33 MR/NMR site Requirements 1. Access to building M/R Road width Accessible Provided 4.5 mtrs M/R Gate width 4.8m N/A N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors M/R 02 No.'s Provided Basements N/A N/A N/A b. Width of staircases M/R 1.50 m 1.60 & .92m Upper Floor N/A N/A N/A Basements c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to Required Provided M/R terrace 1.86 m 1.50 m M/R Width of Corridor .90 m 1.0 m M/R, being old case Class room Door Size 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Required Natural ventilation M/R Upper floors provided Fire Extinguishers 14 no's Provided MR Total numbers ABC/CO<sub>2</sub> type Provided MR Types IS marking Provided MR ISI marked First-Aid Hose Reels 01 no. Provided MR Total numbers on each floor 30 mtrs Provided MR Length of hose reel hose 5 mm Provided MR Nozzle diameter Automatic fire detection and alarming system

(West Point Model School, 12, Om Vihar, Phase-III, Uttam Nagar, New Delhi-110059)

5.

6.

7.

1/20

).	➤ Location  Fire Control Room  • Detector System Panel	N/A	N/A N/A	N/A	
	> Location	N/A	N/A	14/71	
			3.1/A		
1	> Total Area	N/A	N/A	N/A N/A	
	Refuge Area.				
	Standby power supply	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
	Fireman's Grounding Switch     Lift Signage	N/A	N/A		
	Communication In lift Car     Communication Switch	N/A		N/A N/A	
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A N/A	N/A N/A	
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A		
	Provision of Lifts.		21/4	No Lift	
	Exit Signage.	Required	Provided	MR No Life	
	Overhead Tank capacity	10000 ltrs	10,000 ltrs.	MR	
	Access to tank	N/A	N/A	N/A	
	Fire service inlet	N/A	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A	
	Underground tank capacity	N/A	N/A	N/A	
	Captive Water Storage for fire fighting				
	Auto Starting of pump	N/A	N/A	IN/A	
	Power Supply	Required	Provided N/A	N/A	
	Head of the pump	40 mtrs	Provided	MR MR	
	<ul><li>Perface level</li><li>Discharge of pump</li></ul>	450 LPM	Provided	MR	
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>			100	
	Duran House Access	N/A	N/A	N/A	
		N/A	N/A	N/A	
	Auto Starting/Manual Stopping	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	N/A	N/A		
	<ul><li>Head of Main pump</li><li>Number of main pumps</li></ul>	N/A	N/A	N/A	
	Discharge of main Pump	N/A		N/A	
	Ground Level	27/4	N/A	N/A	
. P	Pumping Arrangements				
	Hose Box	N/A	N/A	IN/A	
	Total number of hydrants	N/A	N/A	N/A N/A	
. Y	Yard Hydrants			N/A	
	Hose Box	N/A	1 No.	MR	
	<ul><li>Size of riser/down-comer</li><li>Number of hydrants per floor</li></ul>	N/A	1 No.	MR	
. II	Size of riser/down-comer	N/A	100 mm	MR	
	Sprinkler above false ceiling	19/73			
	Ground Floor     The shows false sailing	N/A N/A	N/A	N/A	
	Basement	N/A N/A	N/A	N/A	
. A	Automatic Sprinkler System	N/A	N/A	N/A	
р	Public Address System	N/A	14/21		
N	<b>MOEFA</b>	N/A	N/A N/A	N/A	
	Hooters' Location	N/A	N/A N/A	N/A	
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A N/A	
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A	
	Type of detectors	N/A	N/A	N/A N/A	

Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Battery backup     Class Plans	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/1319 dated 20/06/2019 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Ozefo (\$2)

12/7/22

ANDUND

FT hetter

put up tou

sognatue

18/7/202

DycFd(S2)

M.S.CU