

C-67



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/GH/2022/SZ/ 358

Dated: 26/7/2022

FIRE SAFETY CERTIFICATE

Certified that **M/s Le-Cadre Guest House** located at E-23, East of Kailash, New Delhi-110065 comprised of Basement, Ground + 03 upper floors (Total 28 guest rooms) & Temporary Rooms sealed with brick wall at terrace level owner/occupied by Mr. Pardeep Aggarwal was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/2019/SZ/715 dated 04/04/2019. The premise was re-inspected by the officer concerned of this department on 18/07/2022 in the presence of Mr. Pradeep Aggarwal (Owner) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **“Residential & Lodging”, Group-A** (Guest House) with effect from the date of issue 26/7/2022 for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 26/7/2022 at New Delhi by

(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)

ok

Copy to: -

1. M/s Le-Cadre Guest House located at E-23, East of Kailash, New Delhi 110065.
2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-49.
(Ref. MHA Portal ID 2022070414006 dated 04-07-2022)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. The basement shall be used as per the provisions of BBL /NBC Part- IV.
7. “The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.”
8. The occupancy of 4th floor is not allowed as per the provision contained in clause 7.31 of UBBL-2016.

N/16

INSPECTION REPORT

1	Name & Address of the Building	M/s Le-Cadre Guest House located at E-23, East of Kailash, New Delhi- 110065		
2	Type of Occupancy	Residential, Group-A (Lodging or Rooming House)		
3	Building Comprised of	Basement, Ground + 03 upper floors & Temporary Rooms sealed with brick wall at terrace level.		
4	Type of Case	Renewal		
5	Details of Previous NOC	F 6/DFS/MS/GH/2019/SZ/715 dated 04-04-2019		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	18-07-2022		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Pradeep Aggarwal (Owner)		
10	Year of construction	2009	Basement (storage), Gd. floor (Rec. & 04 rooms), 1 st floor (08 rooms), 2 nd floor (08 rooms) & 3 rd floor (08 rooms). Total 28 Guest Rooms .	
11	Applicant letter No.	MHA Portal ID 2022070414006 dated 04-07-2022		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	12 mtr -NA- -NA-	Provided -NA- -NA-	MR -NA- -NA-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	01 No	Provided	MR (old case)
	➤ Basement floor.	02 Nos	Provided	MR
	b) Width of Staircase			
	➤ Upper floors	1.25 mtr	1.25m	MR (old case)
	➤ Basement floor	1.25 mtr	1.25m & 1.05m	MR (old case)
	c) Protection of exits			
	➤ Fire check door as per clause 7.31 in UBBL- 2016	Required	Provided	MR
	➤ Pressurization	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	One	Provided	MR
	e) Width of corridor	-NA-	-NA-	-NA-
	f) Door size	1m	1m (final exit)	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	-NA- Required -NA- -NA- -NA-	-NA- Provided -NA- -NA- -NA-	-NA- MR -NA- -NA- -NA-
4	Smoke Management system.	As per clause 7.31 in UBBL- 2016		
	<ul style="list-style-type: none"> Basement Upper floors 	30 ACPH 12 ACPH	Exhaust fan provided Exhaust fan provided	MR MR
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	ISI marked	20 Nos ABC & CO2 Provided	MR MR MR
6	First Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	Hose-reel	01 No 30m 5mm	MR MR MR

M/M

7	Automatic fire detection & alarming system.	As per clause 7.31 in UBBL- 2016		
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooter's location 	CO/Detectors	Exhaust fan provided	MR
		Required	Provided	MR
		-NA-	-NA-	-NA-
		Required	Provided	MR
		Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	<ul style="list-style-type: none"> • Basement • Upper floors • Sprinkler above false ceiling 	Required	Provided	MR
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
11	Internal Hydrants.			
	<ul style="list-style-type: none"> • Size of Riser/Down-comer • Number of Hydrant per floor • Hose box. 	100mm	Provided	MR
		01 No	Provided	MR
		01 No	Provided	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> • Total number of hydrants. • Hose box. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
13	Pumping arrangements.			
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main pump. ➤ Head of main pump. ➤ Number of main pumps. ➤ Jockey Pump output. ➤ Jockey Pump head. ➤ Standby Pump output. ➤ Standby Pump head. ➤ Auto Starting/Manual Stopping. ➤ Pump house access. • Terrace Level <ul style="list-style-type: none"> ➤ Discharge of pump. ➤ Head of pump. ➤ Power supply. ➤ Auto starting of pump. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		450 & 180 LPM	450 & 180 LPM	MR
		35m (each)	35m (each)	MR
		Required	Provided	MR
		Required	Provided	MR
14	Captive water storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity. <ul style="list-style-type: none"> ➤ Draw-off connection. ➤ Fire Service Inlet. ➤ Access to tank. • Overhead tank capacity. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		Required	Provided	MR
		-NA-	-NA-	-NA-
		10,000 Ltr	10,000 Ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of lift shaft. • Pressurization of lift lobby. • Communication in lift car. • Fireman's switch. • Lift signage. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> • Total area • Location 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
19	Fire Control Room.			

16	
provided	MR
	MR
	-NA-
	MR
	MR
	MJ
	M

<ul style="list-style-type: none"> • Detector system panel. • Flow switch panel. • PA system panel. • Battery backup. • Building floor plan. 	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.		-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 460 dated 10/06/2022

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/GH/2019/SZ/715 dated 04-04-2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

M
19/3/2022
Signature of Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

DY. CFO (SZ) *F.T.* *M*

~~ADO (BCP)~~

As approved, F.T. letter is forward for your signature pl

M
26/3/2022

Dy CFO/SZ *M*
MS. *M*

uploaded
M
21/3/2022