

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



F6/DFS/MS/GH/SZ/2022/ 3*59*

Dated: 21/7/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Hilson Guest House located at E-240, Main By Pass Road, 1st 60 feet Road, Molarband Extn. Badarpur, New Delhi - 110044, comprised of Basement + Ground + 03 upper floors: Basement - storage, Ground floor- reception, 1st floor - 10 guest rooms + 1 office, 2nd floor- 14 guest rooms + 2 stores, 3rd floor - 14 guest rooms + 2 stores, was inspected by officer concerned of Delhi Fire Service on 11.07.2022 in the presence of Mr. Mahesh and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010. Hence the premises is fit for occupancy of "Residential Sub Division-A-1" for total 38 guest rooms (1st floor - 10 guest rooms, 2nd floor- 14 guest rooms, 3rd floor - 14 guest rooms) with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire

Director

Delhi Fire Service

Copy to:-

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

2. The Licensee, M/s Hilson Guest House located at E-240, Maia By Pass Road, 1st 60 feet Road, Molarband Extn. Badarpur, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- Basement shall be used as per NBC/UBBL 2016.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

	Name	& address	of the building		CTION REPORT				
		ec address	of the building	M/s Hilson Guest House located at E-240, Main By Pass Road, 1 st 60 feet Road, Molarband Extra					
	Building is comprised of				Badarpur, New Delhi. Basement + Ground + 03 upper floors Basement - storage Ground floor - reception 1st floor - 10 guest rooms + 1 office 2nd floor - 14 guest rooms + 2 stores 3rd floor - 14 guest rooms + 2 stores				
	Type of occupancy				Residential Group A-I				
	Type of case				New Case				
,	Details of Previous FSC				Nil				
)	Fire Safety direction letter no.				BC/UBBL-2016				
,	Date of inspection				.07.2022				
3					la ADO (M. Road)				
)	Name	Name of the inspecting officers Name of the designation of officer			r. Manish (Owner				
	from the building side			'*1	i. mamon (Owner	,			
10	Year of construction			20	2019, Year of occupancy - 2022				
11		cant's lette							
				04	04.06.2022.				
S.N			Standards on fire		equirement as	Provided at	Remarks MR/NMR		
0		vention	and fire safety		er NBC/UBBL-	Site	MINIM		
		uirements		20	016				
		ess to bui					MD		
l	A	Road width Gate width		_	6.0 mtrs	6.0 mtrs	MR		
	В				NA	NA	NA		
_	C		f internal road		NA	NA	NA		
2			dth, Type and Arrang	eme	ent of Exits		1		
	Α		er of staircases	4					
			er floor		02 nos.	02 nos.	MR		
			ement	_	02 nos.	02 nos.	NA		
	В		of staircases	-	1.50	1.50			
			er floor	-	1.50 mtrs each	1.50 mtrs each	MR		
			ement on of exits (Required a	- L		1.50 mtrs each	MR		
	C		check door	is pe	Required	Provided	MD		
			surization	\dashv	NA	NA	MR NA		
	D		continuous staircases	to	01 no.	Provided	MR		
		terrace					1411		
	E		corridor		1.80 mtrs	Provided	MR		
	F	Door siz	e		1.50 mtrs	1.50 mtrs (final	MR		
						exits)			
	Co	mpartmei							
3	-	Fire chec	k door		Required in basement	Provided	MR		
3	A				NA	NA	NA		
3	B		f electrical shafts						
3			f electrical shafts g of shaft door		NA	NA	ΝΔ		
3	В		g of shaft door		NA NA	NA NA	NA NA		
3	B C D E	Fire ratin Water cu	g of shaft door rtain pers				NA		
	B C D E	Fire ratin Water cu	g of shaft door rtain		NA NA	NA			
3	B C D E	Fire ratin Water cu	g of shaft door rtain pers agement System.		NA	NA	NA		

5.	2. Charles and the control of the co						
	A	Total numbers	10 nos.	14 nos.	MD		
	В	7,700	CO ₂ & ABC	CO ₂ & ABC	MR		
	C	ISI marking	Required	ISI marked	MR		
6	First-Aid-Hose Reels			131 marked	MR		
	A	Total numbers of each floor	01 no.	01 no.			
	B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR		
	C	Nozzle diameter	5 mm	5	MR		
7	Automatic Fire Detection And Al UBBL 2016).		arming Sustan (D	5 mm	MR		
	UI	BBL 2016).	arming System (Re	quired as per cla	iuse 7.31.vii		
	A	Type of detectors	CO detectors	Description			
	В	Location of main panel	Required	Provided	MR		
	_		Required	At ground floor	MR		
	C	Location of repeater panel	NA	NA	NIA		
	D E	Alternate source of power Hooters	NA	NA	NA NA		
	1	Hooters	Audible in	Provided	MR		
1	MO	DEFA	Entire building	<u> </u>			
)		olic Address System.	Required	Provided	MR		
0	Au	tomatic Sprinkler System.	NA	NA	NA		
	A	Basement					
	В	Upper floor	Required	Provided	MR		
			NA	Provided at all floors	NA		
		Sprinkler above false ceiling	NA	NA	NA		
1	Internal Hydrants			1	INA		
	A	size of riser/down-comer	NA	100 mm	NIA		
	В	Number of hydrants per floor	NA	01 no.	NA NA		
	C Hose box		NA	01 no.			
2	Yar	d Hydrants.		01 110.	NA		
	A Total number of hydrants		NA	NA	1214		
		Hose box	NA	NA	NA		
3	Pun	ping Arrangements.	IVA	INA	NA		
	A	Ground Level					
	\vdash	a Discharge of main Pump	NA	214			
	-	b Head of Main Pump		NA	NA		
	-	Number of main pumps	NA	NA	NA		
	-	Jockey pump out put	NA	NA	NA		
	-		NA °	NA	NA		
		Jockey pump head Standby pump out put	NA	NA	NA		
	-	standey pamp out put	NA	NA	NA		
		Standby pump Head Auto Starting /Manual	NA NA	NA	NA		
		stopping	NA	NA	NA		
	i	Pump house access	NA	NA	NA		
	В	Terrace Level	†***	11/1	INA		
	8	Discharge of pump	450 lpm x 02	Provided	MR		
			nos. or 900 lpm	(900 lpm x 2			
				nos.)			
	-	Head of the Pump	40 mtrs.	40 mtrs.	MR		
	(- suppry	Required	Provided	MR		
1		Auto starting of pump	Required				

M's Hilson Guest House located at E-240, Main By Pass Road, 1st 60 feet Road, Molarband Extr. Badarpur, New Delhi

14	Captive Water Storage for Fire Fighting.								
	A Underground tank capacity	NA	NA	NA					
	B Draw-off connection	NA	NA	NA					
	C Fire service inlet	NA	NA	NA					
	D Access to tank	NA	NA	NA					
	E Overhead tank capacity	15,000 ltrs	15,000 ltrs	MR					
15	Exit Signage.	Required	Provided	MR					
16	Provision of Lifts.								
	A Pressurization of lift shaft	NA	NA	NA					
	B Pressurization of lift lobby	NA	NA	NA					
	C Communication in lift car	Required	Provided	MR					
	D Firemen's grounding switch	Required	Provided	MR					
	E Lift signage	Required	Provided	MR					
17	Standby Power Supply	Required	Provided (DG	MR					
			Set)	2 20					
18	Refuge Area.								
	A Total area	NA	NA	NA					
	B Location	NA	NA	NA					
19	Fire Control Room								
	A Detector system panel	NA	NA	NA					
	B Flow switch panel	NA	NA	NA					
	C PA system panel	NA	NA	NA					
	D Battery backup	NA	NA	NA					
	E Building floor plans	NA	NA	NA					
20	Special Fire Protection Systems For	NA	NA	NA					
	Protection Of Special Risks, If Any:								

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

There is extended mumty on the terrace, however only a small part of it (covering lift and staircase) is under the guest house management and the same is segregated from rest of the extension by a brick wall.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 35 of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

Dy. CFO(SZ)

Déreeles M

Agymm