

भाजादी क अमन महोत्सव

## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 25/

Dated 201.7.12022

## FIRE SAFETY CERTIFICATE

Certified that the M/s The Grand Uddhav located at 4953- 4954 & 4898, Ram Dwara Road, Nehru Bazar, Pahar Ganj, New Delhi comprised of Basement + Stilt + Ground + 03 Upper floors, Basement (storage), stilt (parking + reception), Ground floor (11 guest rooms), 1<sup>st</sup> floor (20 guest rooms), 2<sup>nd</sup> floor (17 guest rooms) and 3<sup>rd</sup> floor (11 guest rooms), total 59 guest rooms, owned/occupied by The Grand Uddav Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/1301 dated 18/06/19. Now, the premises was re-inspected by the officers concerned of this department on 18/07/22 in the presence of Mr Sunil Kakkar and found that the said guest house building having given an under taking and affidavit dated 18.07.2022 & 22.01.2019 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) stilt - parking -Ground floor (11 guest rooms), 1st floor (20 guest rooms), 2nd floor (17 guest rooms) and 3rd floor (11 guest rooms), total 59 guest rooms up to third floor only, with effect from 2.5, 1.2, 2.2, ... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued . 2.0 / 37. 20.2 ..... at New Delhi by.

Dy. Chief Fire Officer **Delhi Fire Service** R

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2022071414561 dated 14.07.2022
- 3. M/s The Grand Uddav 4953, 4953A, 4954 & 4898, Ram Dwara Road, Nehru Bazar, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock. 4
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority. 5.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any. 6.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 7.
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. 8.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

	and the second		(				
		NIM					
		ECTION REPOR					
1. 1	Name & address of the building		and Uddhav at 495 Dwara Road, Nehr				
				u			
		,	r Ganj, New Delhi , Sub Division-A-1				
2. T <u>y</u>	ype of occupancy:-		ilt + Ground + 03 Upp	er floors			
			rage), stilt (parking),	. 10015,			
		Ground floor (	11 guest rooms), 1 <sup>st</sup> flo	oor (20 guest			
		rooms), 2 <sup>nd</sup> flo	or (17 guest rooms) an	d 3 <sup>rd</sup> floor (11			
		guest rooms), t	total 59 guest rooms to	emporary shed at			
		terrace an aff	idavit dated 22.01.20	regarding			
			floor above third flo	01			
	Type of case:-	Renewal	S/GH/NDZ/2019/1	301 dated			
4.	Details of previous FSC:-		S/OH/INDZ/2019/1	JULIANU			
		18/06/19					
	Fire safety directives No	N/A					
	Date of inspection:-	18/07/22	Charle (ADO/CO	N N			
7.	Name of the inspecting officer:	- Sh. Ravinde	r Singh (ADO/CC)	)			
		Sh. Rajinder	r Atwal (DO/CD)				
8.	Name & designation of officer						
	From the building side:-	Manager					
	Year of construction:-	2018	21 Jac - 1 1 4 07 00	<b>1</b> 2			
10.	Applicant's letter No:-		561 dated 14.07.20	Remarks			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	MR/NMR			
ι.	Access to Building						
	1) Road width	09 mtr.	20 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arr	angement of Ex	its				
	A. Number of staircases						
	1. Upper floors	02 Nos.	03 Nos.	MR			
	2. Basements	02 Nos.	02 Nos.	MR			
	B. Width of staircase						
	1. Upper floors	1.5 mtr.	02 nos. 1.5 mtr. 01 Nos. 1.35 mtr.	MR			
	2. Basements	1.0 & 1.5 mtr.	01 nos. 1.5 mtr. 01 Nos. 1.40 mtr.	MR			
	C. Protection of exits						
	1. Fire check door	Required	Provided	MR			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	02	MR			
	staircase to terrace						
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	01 mtr.	01 mtr.	MR			
3.	Compartmentation	1					
	1) Fire check door	Required	Provided	MR			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A N/A	N/A N/A	N/A N/A			
	1 57 The failing of shall door		N/A N/A	N/A N/A			
		$  N / \Delta$					
	4) Water curtain	N/A					
	<ul><li>4) Water curtain</li><li>5) Fire Dampers</li></ul>	N/A N/A	N/A N/A	N/A			
4.	<ul><li>4) Water curtain</li><li>5) Fire Dampers</li><li>Smoke Management System</li></ul>	N/A	N/A	N/A			
4.	<ul><li>4) Water curtain</li><li>5) Fire Dampers</li></ul>						

5.	Fire Extinguishers			
	1) Total numbers	20 Nos.	26 No.	
	2) Types	ABC & CO2	25 Nos.	MR
	3) ISI marking	and the second se	ABC & CO2	MR
6.	First-Aid Hose Reel	Required	Provided	MR
	1) Total number of eachfloor	01	01	
	2) Length of hose reel hose	30 m	01	MR
	3) Nozzle diameter	50 m 5 mm	30 m	MR
7.	Automatic Fire Detection &	3 mm	5 mm	MR
	1) Type of detectors(CO)			
	2) Location of main panel	Required	Provided	MR
	3) Location of repeater panel	Ground floor	Provided	MR
	4) Alternate source of power	N/A December 1	N/A	N/A
	5) Hooter's Location	Required	Provided	MR
8.	MOEFA	Each floor	Provided	MR
<u>o.</u> 9.		Required	Provided	MR
<u>9.</u> 10.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System 1) Basement			
		Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
11.	1) Size of rigor/days			
	1) Size of riser/down-comer	150 mm	150 mm	MR
	2) Number of hydrants per floor	01	01	MR
	3) Hose box	01		
12.	Yard Hydrants	01	01	MR
	1) Total number of hydrants			
	2) Hose box	N/A N/A	N/A	N/A
13.	Pumping Arrangement	IN/A	N/A	N/A
	1) Ground level			
	a) Discharge of main	1620 LPM	1600 1 01 6	
	pump		1620 LPM	MR
	b) Head of main pump	40 mtr.	40 mtr.	MR
	c) Number of main pum	p 01	01	MR
	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	40 mtr.	40 mtr.	MR
	f) Stand by pump output		1620 LPM	MR
	<ul><li>g) Stand by pump head</li><li>h) Auto starting/Manual</li></ul>	40 mtr.	40 mtr.	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	450 1 5		
	b) Head of pump	450 LPM	450 LPM	MR
	c) Power supply	40 mtr.	40 mtr.	MR
	d) Auto starting of pump	Required	Provided	MR
	-, · · ································	Required	Provided	MR
14.	Cantive Wotor St.			
	Captive Water Storage for F 1) Under ground tank capacity			
	a) Draw-off connection	50,000 ltr.	50,000 ltr.	MR
		N/A		

20.	Special Fire Protection Sys Risk, if any:	tem for Protec	tion of special	
	e) Building floor plan	N/A		N/A
			N/A	N/A
	d) Battery backup	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	a) Detector system panel			N/A
9.		N/A	N/A	N/A
	Fire Control Room	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
3.	Refuge Area	N/A		
7.	Stand by Power Supply	Required	N/A	N/A
	<ul> <li>e) Lift signage</li> </ul>	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	lift car	Designed	Provided	MR
	c) Communication in	Required	Provided	MR
	b) Pressurization of lift lobby	N/A		
	shaft	N/A	N/A	N/A
	a) Pressurization of lift	N/A	N/A	N/A
	Provision of Lifts.			
5.	Exit Signage.	Required	Provided	MR
	d) Over head tank capacity	20, 000 ltr.	20,000 ltr.	MR
	c) Access to tank	Required	Provided	MR
	b) Fire service inlet	N/A	N/A	N/A

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection. Further, applicant has submit an undertaking on dated 18.07.2022 that stilt floor shall be used for parking only not for other purpose.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/1301 dated 18/06/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: - Sh. Rajinder Atwal Designation: - DO (CD)

Signature of the Inspecting Officer

Name: - Sh. Ravinder Singh Designation: ADO (CC)

20

F.T. Please

J. Fr

postin

11 Shected c:

MR MR MR

MR 1R

-V.UY DA. SUICIDA

4 . .