



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2022/ 342

Dated: 02/08/2020

FIRE SAFETY CERTIFICATE

Issued on ... at New Delhi by.

Director

Delhi Fire Service

Copy to: -

- 1. The Owner/Occupier, Plot No. 21, North West Avenue, West Punjabi Bagh, New Delhi-110026.
- 2. The Executive Engineer (Bldg.), HQ, Delhi Municipal Corporation, Dr. SPM Civic Centre, 8th Floor, Minto Road, New Delhi- 110002.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

Name & address of the Building - The building located at Plot No. 21, North West Avenue,

West Punjabi Bagh, New Delhi-110026

type of Occupancy Mixed (Mercantile + Residential)

Type of Case

Details of previous NOC Nil

5. Hire Safety directives letter no. F.6/DFS/MS/BP/2022/108 dated 10/03/2022

6. Date of inspection 26/07/2022

7. Name of the Inspecting Officers: DO (West) & ADO (MN)

Name and designation of officers

from the building side : Sh. Gaurav, A.E (MCD), Sh. Ashish, J.E. (MCD), Sh. Anil Kumar Dua (Owner)

9. Year of Construction : 2022

10. Applicant's letter No. : Online MCD portal ID- 10069298

The said building is comprised of basement, stilt, ground plus three upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	UBBL /NBC-IV Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	09 mts	Provided	MR		
	Gate width	06 mts	Provided	MR		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	2	Provided	MR		
	Basements	2	Provided	MR		
	b. Width of staircases					
	Upper Floors	1.5 mts each	Provided	MR		
	Basements	1.5 mts each	Provided	MR		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	Required	Provided	MR		
	d No. of continuous staircases to terrace	02	Provided	MR		
	e. Width of Corridor	1.5 mts	Provided	MR		
	f. Door Size	1.5 mts	Provided	MR		
3	Compartmentation.		*			
.)	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts Fire Rating of shaft door 	Required	Provided	MR		
		N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	12 A/C per hour	Provided	MR		
	Upper floors	12 A/C per hour	Provided	MR		
5	Fire Extinguishers					
	Total numbers	12	Provided	MR		
	Types	ABC/CO ₂	Provided	MR		
	IS marking	Required	ISI marked	MR		
6	First-Aid Hose Reels.					
	Lotal numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30 mtr.	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		

_		system				
7	Automatic fire detection and alarming	N/A	N/A			
	Type of detectorsLocation of Main Panel			N/A		
	r CD mantay Danal	N/A	N/A	N/A		
	11 of names	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement & Stilt Floor	Required	Provided	MR		
	Upper Floor	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11	Internal Hydrants			1471		
	Size of down-comer	100mm	Provided	MR		
	Number of hydrants per floor	01 no.	Provided	MR		
	Hose Box	01 no.				
12		OT no.	Provided	MR		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	2280 LPM	Provided	MR		
	Head of Main pump	40 mts	Provided	MR		
	Number of main pumps	01	Provided	MR		
	Jockey Pump out put	180 LPM	Provided	MR		
	Jockey pump head	40 mts	Provided	MR		
	Standby Pump out putStandby Pump Head	2280 LPM	Provided	MR		
	J - milp 110ma	40 mts	Provided	MR		
	Auto Starting/ Manual stoppingPump House Access	Required	Provided	MR		
		Required	Provided	MR		
	Terrace level Discharge of nump					
	Discharge of pumpHead of the pump	900 LPM	Provided	MR		
	> Power Supply	40 mts	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
1.4	•	Required	Provided	MR		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	1,00,000 ltr	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	Fire service inletAccess to tank	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
	Tank capacity	25,000 Ltr.	Provided	MR		
15	Exit Signage.					
16	Provision of Lifts.	Required	Provided	MR		
	 Pressurization of Lift Shaft 	D				
	Pressurization of Lift lobban	Required	Provided	MR		
	Communication In Life Com	Required N/A	Provided	MR		
	Fireman's Grounding SwitchLift Signage	Required	N/A Provided	N/A		
	- Singe	Required		MR		
		quired	Provided	MR		

	Standby power supply	Required	Provided	MR		
	Refuge Area.					
_	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
)	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	 Flow Switch Panel 	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backupBuilding Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
0	Special Fire Protection Systems for Protection of special Risks, if any:	ABC type fire extinguisher near HT/LT panel	Provided	MR		

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Signature of the Inspecting Officer

Name: - Sarabjeet Singh Name: - M. K. Chattopadhyay Designation: - ADO (MN) Designation: - DO (West)

Necessary Correction has been made. It is mixed occupancy building (Mercantile & regulation)

Director occy of each Kerr occy of each Kerr occy of each Kerr occionation of A 2701-