

FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/SZ/2022/ 837

Dated: 2/8/2022

FIRE SAFETY CERTIFICATE

Certified that the building of Aadarsh World School Located at Sector-12, Phase – 1, Dwarka, New Delhi – 110075 comprised of Ground + 03 Upper Floors was issued FSC by this department vide Letter No. F6/DFS/MS/School/2019/SZ/878, Dated 23/04/2019. The premises was re inspected by the officer concerned of this department on 18/07/2022 in the presence of Sh. Karan Singh (Physical Education Teacher) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class-B “Educational” with effect from 2/8/22 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...2/8/22... at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer
Delhi Fire Service.

Copy to:

1. The Principal Aadarsh World School Located at Sector-12, Phase – 1, Dwarka, New Delhi – 110075.
2. Directorate of Education Old Secretariat Delhi – 110054

Following fire safety directives must be adhered to:-

- 1 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2 Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3 The trained staff should be available round the clock.
- 4 Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5 The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6 The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 7 Basement shall be used strictly as per building bye laws.
- 8 The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Aadarsh World School Located at Sector-12, Phase - 1, Dwarka, New Delhi - 110075.
 2. Type of Occupancy : Educational (Basement + Ground+ 3 Upper Floors)
 3. Type of Case : Renewal (G+3)
 4. Details of previous NOC : F6/DFS/MS/School/2019/SZ/878 Dated 23/04/2019
 5. Fire Safety directives Letter No. : F6/DFS/MS/BP/2005/242 Dated 17/02/2005
- (For G+2)**
- Total Area = 4000 sqm.
 Covered Area = 2000 sqm
 Class rooms = 33
 No. of students = 1112
6. Date of inspection : 18/07/2022
 7. Name of the Inspecting Officer : Udai vir singh, ADO (DWK)
 8. Name and designation of Officer
 from the building side : Sh. Karan Singh (Physical Education Teacher)
 9. Year of Construction : 2005 & 2015
 10. Applicant's letter No. : AWS/Dwk/06/2022/468 Dated 22/06/2022

| S No | Minimum standards on fire prevention and fire safety U/R 33 | As per N/12 | Provided at site | Remarks MR/NMR |
|------|---|-------------|-------------------------------|---------------------|
| 1. | Access of building | | | |
| | • Road width | 06 mtr | Provided | MR |
| | • Gate width | 4.5 mtr | Provided | MR |
| | • Width of internal road. | NA | NA | NA |
| 2. | Number, width, Type & Arrangements of exits | | | |
| | a. Number of staircases | | | |
| | • Upper floors | 2 Nos. | 2 Nos. | MR |
| | • Basements | NA | NA | NA |
| | b. Width of staircases | | | |
| | • Upper floors | 1.5 m each | 1.5 m | MR |
| | • Basements | NA | NA | NA |
| | c. Protection of exits | | | |
| | • Fire check door | NA | NA | NA |
| | • Pressurization | NA | NA | NA |
| | d. No of continuous staircase to terrace | 02 Nos. | Provided | MR |
| | e. Width Of Corridor | 1.5m | 2.30 m | MR |
| | f. Door Size | 01m | 01 mtr (Including door frame) | MR (Being old case) |
| 3. | Compartmentation | | | |
| | • Fire check door | NA | NA | NA |
| | • Sealing of electrical shafts | NA | NA | NA |
| | • Fire Rating of shaft door | NA | NA | NA |
| | • Water Curtain | NA | NA | NA |
| | • Fire Dampers | NA | NA | NA |

(Handwritten signature)


24/22

| | | | | |
|----|--|-------------|---|----|
| 14 | Captive water Storage for fire fighting: | | | |
| | • Under ground tank capacity | NA | NA | NA |
| | ➤ Draw off connection | NA | NA | NA |
| | ➤ Fire service inlet | NA | Provided | NA |
| | ➤ Access to tank | NA | NA | NA |
| | • Overhead Tank capacity | 10,000 ltrs | Provided | MR |
| 15 | Exit Signage | Required | Provided | MR |
| 16 | Provision of Lifts | | | NA |
| | ➤ Pressurization of Lift Shaft | NA | NA | NA |
| | ➤ Pressurization of lift lobby | NA | NA | NA |
| | ➤ Communication in lift Car | Required | Provided | MR |
| | ➤ Fireman's Grounding Switch | Required | Provided | MR |
| | ➤ Lift Signage | Required | Provided | MR |
| 17 | Standby power supply | Required | Provided | MR |
| 18 | Refuge Area | | | |
| | ➤ Total area | NA | NA | NA |
| | ➤ Location | NA | NA | NA |
| 19 | Fire control room | | | NA |
| | ➤ Detector system panel | NA | NA | NA |
| | ➤ Flow Switch Panel | NA | NA | NA |
| | ➤ PA System Panel | NA | NA | NA |
| | ➤ Battery backup | NA | NA | NA |
| | ➤ Building Floor Plans | NA | NA | NA |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any; | Required | ABC, Fire extinguisher provided near electric panel | MR |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter F6/DFS/MS/School/2019/SZ/878 Dated 23/04/2019 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- The basement seen during the visit on 04/05/2022 has been closed (undertaking placed at C/49).


 Signature of the Inspecting Officer
 Name Udai Vir Singh
 Designation ADO/DWK

Do (S.W)

Dyefo (S2)

ADO(DWK)

18/7/22

[Signature]

F.F.