



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F6/DFS/MS/School/2022/NDZ/ 842

Dated: 2/8/22

FIRE SAFETY CERTIFICATE

Certified that Nutan Vidya Mandir School at A.G.C.R. Enclave, Delhi-110092, comprised of basement, ground plus one upper floor, owned/occupied by Nutan Vidya Mandir School was inspected by the officer concerned of this department on dated 24/05/2022 in the presence of Mrs. Rashmi Pillai, Principal and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore complied with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by the Director of Education and that the building/premises is fit for occupancy class 'Educational (Group-B)' with effect from $\frac{2}{2} \frac{1}{2} \frac{1}{2$

Director **Delhi Fire Service**

To,

The Principal Nutan Vidya Mandir School at AGCR Enclave, Delhi-110092,

Copy:-

The Dy. Director of Education, D-Block, Anand Vihar, Delhi-110092

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

1. Name	e & address of the building	: Nu	itan Vidya Mano	dir School		
 Building is comprised of Type of Occupancy Type of Case Details of Previous NOC letter Fire Safety direction letter No Date of Inspection Name of the Inspecting officers 		 Nutan Vidya Mandir School, AGCR Enclave, Delhi-110092 Basement, Ground plus one upper floor only Educational New Nil F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11 24/05/2022 ADO Deepak Kumar 				
from t 10. Year o	and designation of Officer he building side of Construction ant's letter No Minimum Standards on fire	: 198	ail <u>nvm.agcr@g</u>	mail.com dated 04/05/2		
<u>No.</u> 01	prevention and fire safety U/R3 Access to building		DoE Circular Requirement	Provided at Site	Remarks MR/NMR	
02	 Road width Gate width Width of internal road Number, Width, Type and Ar 		06 mtrs N/A N/A	09 mtr. N/A N/A	MR N/A N/A	
	 a. Number of Staircases Upper Floor Basement B. Width of Staircases Upper Floor Basement c. Protection of exits Fire check door 		01 nos. 01 nos. 1.50 mtr 1.50 mtr	02 nos. 02 nos. 1.40 mtr & 1.50 mtr 1.40 mtr & 1.50 mtr	MR MR MR	
	 Pressurization d. No. of continuous staircases to terrace 		N/A N/A 01 nos.	N/A N/A 01 nos.	N/A N/A MR	
	e. Width of Corridor f. Door Size		1.50 mtr. 01 mtr.	02 mtr. 01 mtr.	MR MR	
03	Compartmentation.					

NS.

2

	•			
	Fire check door	N/A	N/A	N/A
	 Sealing of electrical shafts 	N/A	N/A	N/A
	 Fire rating of shaft door 	N/A	N/A	N/A
	Water curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
04	Smoke Management System.			N/A
	Basement	N/A	N/A	NI/A
	Upper floor	N/A	N/A	N/A N/A
				IN/A

N/6

05.	Fire Extinguishers						
	Total numbers	06 nos.	06 nos.	MR			
	• Types	ABC /CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			
06	First-aid-Hose Reels.						
	Total numbers on each floor	01 No.	01 No.	MR			
	 Length of hose reel hose 	30 mtr.	30 mtr.	MR			
	Nozzle diameter	05 mm	05 mm	MR			
07	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	·· N/A	N/A			
	 Alternate source of power 	N/A	N/A ·	N/A			
	 Hooter's location 	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.		•				
	Basement	Required	Provided	MR			
	upper floor	N/A	N/A	N/A			
	 sprinkler above false ceiling 	N/A	N/A	N/A			
11	Internal Hydrants						
	 size of riser/down-comer 	N/A	. N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	 Total number of hydrants 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
3	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	: N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A.	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level			2			
	 Discharge of pump 	450 lpm .	450 lpm	MR /			
	 Head of the Pump 	40 M	40 mtr	MR			
	 Power supply 	Required	Provided	MR			
	 Auto Starting of pump 	Required	Provided	MR			

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	N/A	N/A	N/A
	 Draw-off connection 	N/A	N/A	N/A
	 Fire service inlet 	N/A	N/A	N/A
	 Access to tank 	N/A	N/A	N/A
	Overbaad T	N/A	N/A	N/A
15	Overhead Tank capacity Exit Signage	5,000 Ltr.	6,000 Ltr	MR
16	Provision of Lifts.	Required	Provided /	MR
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	 Firemen's grounding switch 	N/A	N/A	N/A
47	 Lift Signage 	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	100		
	Detector system panel	N/A	N/A	N/A
	 Flow switch panel 	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	 Building Floor Plans 	N/A	N/A	N/A
20	Special Fire Protection systems for	N/A	N/A	N/A
	protection of special Risks, if any:			

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings issued vide letter No. F.6/DFS/MS/School/2022/NDZ/58 dated 10/02/2022 have been rectify now.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rule. It is recommended to grant FSC under rule 35 of the Delhi Fire Service Rule, 2010.

Jup 23/05/2022

Signature of the Inspecting Officer Name :- Deepak Kumar Designation :- A.D.O (Shd)

P.l. & Beak regarding DFA.

106/2022

ADOISheld. Spoken and Re-Submittez DO(ED) on which date your have spoken ? ADOISheld. ADOISheld. ADOISheld. ADOISheld. ADOISheld.