

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 373

## FIRE SAFETY CERTIFICATE

Certified that the Sushree Continental Dx. Guest House located at 3198/XV/1, Opp. MCD Dispensary, Gali Sangatrashan, Paharganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms + office), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (10 guest rooms at each floor) and 4<sup>th</sup> floor (1 staff room), total 32 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/1197 dated 04/06/19. Now, The premises was re-inspected by the officer concerned of this department on 25/07/22 in the presence of (Manager) and found that the said guest house building having 4th floor not in use as per affidavit dated 05.10.2019, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class (Residential, Sub Division-A-1) Ground floor (Reception + 02 guest rooms ), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (10 guest rooms at each floor) 32 guest rooms only up to third floor with effect from -2 + 3 + -2 - --for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 27-8-1-2-2--- at New Delhi by.

6-69

(S.K Dua) Dy. Chief Fire Officer Delhi Fire Service

n

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ID no. 2022040605724 dated 06.04.2022. email id <<u>hotelsushreecontinental@gmail.com</u>> dated 15/07/22.
- The Manager, Sushree Continental Dx. Guest House at 3198/XV/1, Opp. MCD Dispensary, Gali Sangatrashan, Paharganj, New Delhi.

Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

	Л	1)~8							
		NSPECTION RE	EPORT						
1	. Name & address of the build		e Continental Dx. C	Juest House					
			at 3198/XV/1, Opp.	. MCD					
			ary, Gali Sangtrash						
		New De	•						
2	2. Type of occupancy:- Residential, Sub Division-A-1								
		Jpper floors (total 32	Guest rooms)						
	Ground floor (Reception + 02 guest rooms + offi								
		1 <sup>st</sup> floor to	3 <sup>rd</sup> floor (10 guest roon	as at each floor) and					
		4 <sup>th</sup> floor (1 dated 05.1	staff room) not in use	e as per amoavit					
2	. Type of case:-	Renewal							
	Details of previous FSC:-								
-	. Details of previous 1 Se	14/06/19							
5	. Fire safety directives No	N/A							
	. Date of inspection:-	25/07/22							
	Name of the inspection.		der Singh (ADO/C	C)					
	. Name & designation of offic			,					
0	From the building side:-	Manager							
0	. Year of construction:-	1980							
			022040605724 dated 0	6.04.2022. & mail -					
10	. Applicant's letter No:-	id hotelsushreed	ontinental@gmail.com	dated 15.07.2022.					
				Old Case					
S.No.	Minimum Standards on fire	Requirement	Provided at site	Remarks					
5.110.	Prevention and fire safety U/R	Existing	PSS	MR/NMR					
	33	C							
1.	Access to Building								
	1) Road width	N/A	N/A	N/A					
	2) Gate width	N/A	N/A	N/A					
	3)Width of internal road	N/A	N/A	N/A					
2.	Number, Width Type & Arrangement of Exits								
	A. Number of staircases								
	1. Upper floors	01 Nos.	01 Nos.	MR					
	2. Basements	N/A	N/A	N/A					
	B. Width of staircase								
	1. Upper floors	0.80 mtr.	1.30 Mtr.	MR					
	2. Basements	N/A	N/A	N/A					
	C. Protection of exits								
	1. Fire check door	Required	provided	MR					
	2. Pressurization	N/A	N/A	N/A					
	D. No. of continuous								
	staircase to terrace	N/A	N/A	N/A					
	E. Width of corridor F. Door size	N/A N/A	N/A N/A	N/A N/A					
3.	Compartmentation	11/71	11/11	19/71					
э.	-	N/A	N/A	N/A					
-	<ol> <li>Fire check door</li> <li>Sealing of electrical shafts</li> </ol>	N/A N/A	N/A N/A	N/A N/A					
	3) Fire rating of shaft door	N/A N/A	N/A N/A	N/A N/A					
	4) Water curtain	N/A N/A	N/A N/A	N/A N/A					
ŀ	5) Fire Dampers	N/A	N/A N/A	N/A N/A					
	5) The Dampers								
4.	Smoke Management System	I							
	1) Basements	30 ACPH	N/A	N/A					

							1996	4
			M/29					1
	2) Upper floors		12 a/c per		Natural/ Exha	et	1.00	
	2) Opper noois		hour		fan	lusi	MR	
5.	8		1					
	1) Total numbers		08 Nos.		08 Nos.		MR	
	2) Types		ABC & CO2		ABC & CO2		MR	
-	3) ISI marking		Required		Provided		MR	
6.	- not the most need							
	1) Total number of each floor	1	01	_	01		MR	
	<ol> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ol>		30 mtr.	_	30 mtr.		MR	
7.			05 mm		05 mm		MR	
1.	Automatic Fire Detection & 1) Type of detectors CO	. Ala		1	<u> </u>	_		
	2) Location of main panel		Required		Provided		MR	
	3) Location of repeater panel		Ground floor		Provided		MR	
	4) Alternate source of power		N/A Required		N/A Provided		N/A MR	
	5) Hooter's Location		Each floor	$\rightarrow$	Provided		MR	
8.	MOEFA			-				
<u>9.</u>	Public Address System		Required	-+	Provided Provided		MR	
10.	Automatic Sprinkler System		Required	+	Provided	-+	MR	
	1) Basement	1	N/A	+	N/A	-+	N/A	
	2) Upper floors		N/A		N/A		N/A	
	3) Sprinkler above false ceiling	g	N/A		N/A		N/A	
11.		2	1.0.1 1	+	10/1	-	147.	
	1) Size of riser/down-comer		N/A	+	N/A		N/A	
	2) Number of hydrants per floor	or	N/A		N/A		N/A	
	3) Hose box		N/A	-	N/A		N/A	
12.	Yard Hydrants							
	1) Total number of hydrants		N/A	_	N/A		N/A	
17	2) Hose box		N/A	_L'	N/A		N/A	
13.	1 8							
	1) Ground level		//A	-	N/A	N/.	4	
	a) Discharge of main pump		[/A	+	V/A	N/.	-	
	b) Head of main pump	_	/A	+	J/A	N/.	-	
	<ul><li>c) Number of main pump</li><li>d) Jockey pump out put</li></ul>	_	/A /A	-	I/A	N/.		
	e) Jockey pump head	N/		-	I/A I/A	N/.		
	f) Stand by pump output	N/			//A	N/2	-	
	g) Stand by pump head	N/.		-	//A	N/2	-	
	h) Auto starting/Manual	N/.			//A	N//	-	
	stopping	-		-		14/2	ſ	
	2) Terrace level				,			
	a) Discharge of pump	22	5 LPM	22	25 LPM	MF	R	
	b) Head of pump	30	mtr.		0 mtr.	MF		
1	c) Power supply	Re	quired		rovided	MF		
	d) Auto starting of pump		quired		rovided	MF		
4.	Captive Water Storage for Fire I	Figh	iting					
	1) Under ground tank	N/A	A	N/	/A	N//	A	
L	capacity							
	a) Draw-off connection	N/A		N/		N//	1	
	b) Fire service inlet	N/A		N/.		N//	-	
		N/A		N/.		N//	A	
_				25	00 ltr.	MR	2	
5.	Exit Signage.	Rec	quired	Pre	ovided	MR	2	

## MISU

6.	Provision of Lifts.			
	<ul> <li>a) Pressurization of lift shaft</li> </ul>	N/A	N/A	N/A
	<ul> <li>b) Pressurization of lift lobby</li> </ul>	N/A	N/A	N/A
	c) Communication in lift	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System any: One Co <sub>2</sub> fire extinguisher for	for Protection of provided ne	of special Risk, if ear elect, panel.	MR

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/1197 dated 04/06/2019, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the Inspecting Officer Name: - Ravinder Singh Designation: - ADO (CC)

12 20 string flean. old() S.P. win