

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIH FIRE SERVICE: NEW DELIH- 110001



No. F6/DFS/MS/GH/SZ/2022/ 280

Dated: 05 08 2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Batra Holiday Home located at 4, Bhogal Road, Jangpura (Near Rama Tent House), New Delhi-14, comprised of basement, ground floor + 03 upper floors: basement (storage), ground floor (reception and bank), 1st floor (10 guest rooms + 1 office), 2nd floor (11 guest rooms), 3rd floor (02 guest rooms), was granted FSC by this department vide letter no. F6/DFS/MS/GH/2019/SZ/1665 dated 22.08.2019 for 23 guest rooms. The premises was re-inspected by the officer concerned of this department on 03.08.2022 in presence of Mr. Avdesh Singh (Manager) and found that one room at 2nd floor has been converted into store room and the owner has submitted an undertaking stating the floorwise occupancy accordingly. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy of Group 'A(Residential) sub division A-1, having 22 guest rooms (1st floor - 10 guest rooms, 2nd floor - 10 guest rooms, 3rd floor - 2 guest rooms), with effect from 05 08 22 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 05 08 20.22 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer Delhi Fire Service Ole 1

Copy to:-


- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- 2. The Licensee, M/s Batra Holiday Home located at 4, Bhogal Road, Jangpura (Near Rama Tent House), New Delhi-14.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. Basement shall be used as per BBL/UBBL.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

H 21	
MEDECTION	DEDGE

			PECTION REPOR	Т				
1		me & address of the building	M/s Batra Ho Road, Jangpur Delhi-14.	M/s Batra Holiday Home located at 4, Bhogal Road, Jangpura (Near Rama Tent House), New Delhi-14.				
2	Bı	ilding is comprised of	Basement - stor Ground floor	Basement + Ground + 03 upper floors Basement - storage Ground floor - reception & bank 1 st floor - 10 guest rooms + 01 office				
			2 nd floor - 10 gu	2^{nd} floor - 10 guest rooms + 01 store room				
		1	-	3^{rd} floor – 02 guest rooms				
3		pe of occupancy		Residential Group A-1				
4		pe of case		Renewal				
5		tails of previous FSC	F6/DFS/MS/GH	F6/DFS/MS/GH/2019/SZ/1665 dated 22.08.2019.				
6		e safety direction letter no.	Nil					
7		te of inspection	03.08.2022					
8		me of the inspecting officers		hukla, ADO (M. Roa	ad)			
9	fro	me of the designation of office m the building side	er (Manager)	(Manager)				
10		ar of construction	2004					
11	Ap	plicant's letter no.	Online applica 11.07.2022					
S.No	Pr	nimum Standards on fire evention and fire safety quirements U/R 33	Requirement/ Existing fire safety	Provided at Site	Remarks MR NMR			
1	Ac	cess To Building:	arrangements					
-	Road width		6.0 mtrs	12.0 mtrs	MR			
	Gate width		NA	NA	NA			
	Width of internal road		NA	NA	NA			
2	Nı	mber, Width, Type and Arra	angement of Exits:					
	Α	Number of staircases						
		a Upper floor	02 nos.	02 nos.	MR			
		b Basement	02 nos.	02 nos.	MR			
	В	Width of staircases a Upper floor	1.25 mtrs.	1.10 mtrs & 0.82 mtrs.	MR (Old case			
		b Basement	1.25 mtrs.	1.10 mtrs & 0.82 mtrs	MR (Old case			
	С	Protection of exits	1					
		a Fire check door	NA	NA	NA			
	D	b Pressurization No. of continuous staircases	NA 01 no.	NA 01 no.	NA MR			
	E	to terrace Width of corridor	NA	NA	NA			
	F	Door size	1.0 mtrs.	1.0 mtrs.	MR			
3		npartmentation:	no mus.					
	A Fire check door		NA	NA	NA			
	B	Sealing of electrical shafts	NA	NA	NA			
	С	Fire rating of shaft door	NA	NA	NA			
	D	Water curtain	NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
ł	Sm	oke Management System:						
	A	Basement	Natural /Mechanical	Exhaust fan	MR			
	В	Upper floor	Natural /Mechanical	Natural	MR			



H123

11	s Ba	ra rionaay riome located at 4. Bhogal k	load, Jangpura (Near Re	ama Tent House). New I	Delhi-14			
14		Batra Holiday Home located at 4. Bhogal Road, Jangpura (Near Rama Tent House). New Delhi-14 Captive Water Storage For Fire Fighting:						
	A	Underground tank capacity	NA	NA	NA			
	В	Draw-off connection	NA	NA	NA			
	C	Fire service inlet	NA	NA	NA			
	Ð	the second se	NA	NA	NA			
	E	Overhead tank capacity	10,000 ltrs	10,000 ltrs	MR			
15	Exit Signage:		Required	Provided	MR			
16	Provision of Lifts:							
	Α	Pressurization of lift shaft	NA	NA	NIA			
	В	Pressurization of lift lobby	NA	NA	NA			
	C	Communication in lift car	NA	NA	NA			
	D	Firemen's grounding switch	NA	NA	NA			
	E	Lift signage	NA					
17	Standby Power Supply:			NA	NA			
			Required	Provided DG Set	MR			
18	Refuge Area:							
	Α	Total area	NA	NA	NA			
	В	Location	NA	NA	NA			
19	Fire Control Room :							
	A	Detector system panel	NA	NA	NA			
	В	Flow switch panel	NA	NA	NA			
	C	Pa system panel	NA	NA	NA			
	D	Battery backup	NA	NA	NA			
	E	Building floor plans	NA	NA	NA			
20	Sp	ecial Fire Protection Systems Fo		NA	NA			
	Special Risks, If Any:							

Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

The previous FSC was issued to the guest house vide letter No. F6/DFS/MS/GH/2019/SZ/1665 dated 22.08.2019 for 23 guest rooms (1st floor - 10 guest rooms, 2nd floor - 11 guest rooms, 3rd floor - 2 guest rooms). However the guest house has now applied for 22 guest rooms (1st floor - 10 guest rooms, 2nd floor - 10 guest rooms) only. The shortcomings issued vide letter no.F6/DFS/MS/GH/SZ/2022/591dated 18.07.2022 from this department has been rectified by the management. The fire protection system was randomly checked and tested and was found functional at the time of inspection.

In view of above, the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/2019/SZ/1665 dated 22.08.2019 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Accordingly revised FSC is put up in shape of DFA for approval please.

Signature of the Inspecting Officer

Name Rajesh Kumar Shukla Designation ADO (M. Road)

Dy.CFO(SZ)

. cro (2) 11-5.

MR MR MR dated MR MR VA MR

MR MR MR