

432
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/Banq./NDZ/2022/ 42

Dated : 05.08.2022

FIRE SAFETY CERTIFICATE

Certified that the **Rajwada Banquet (A unit of GK Food India) at Plot No. 1 A, at grade level in Star city mall Mayur Vihar-1, Delhi-92** comprises of **Basement + Ground + 02 Upper floor** respectively owned/occupied by Rajwada Banquet, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on **11/07/2022** in the presence of Mr. Ravi and found that the building/ premises is fit for occupancy "**Assembly Building**" (**Rajwada Banquet at Ground floor only**) with effect from 05/08/2022 for period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 05/8/2022 at New Delhi by.

(Atul Garg)
Director

Delhi Fire Service

Copy to:-

1. The Joint Commissioner of Police,
1st floor, Police Station, Defence Colony, New Delhi – 110024.
Online application id no. 2022060412046.
2. The Dy. Health Officer,
MCD (Health Deptt.), Shadhra Zone, Karkardooma, Shadhra, Delhi.
3. Sh. Satish Kapoor,
Rajwada Banquet (A unit of GK Food India),
Star city Mall, Mayur Vihar-1, Delhi-92.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building Rajwada Banquet (A unit of GK Food India) at Plot No. 1 A, at grade level in Star city Mall Mayur Vihar-1, Delhi-92
2. Type of occupancy:- Assembly Building (Community Hall) (Ground floor Only)
3. Type of case:- New Case
4. Details of previous FSC:- F6/DFS/MS/GH/NDZ/2021/376 dated 05/08/2021(FSC issued to the mall)
5. Fire safety directives No.- N/A
6. Date of inspection:- 11/07/2022
7. Name of the inspecting officer:- Sh. A.K. Jaiswal (DO/ED) & Sh. Manoj Kumar Sharma (ADO/LN)
8. Name & designation of officer From the building side:- Mr. Ravi
9. Year of construction:- 2006
10. Applicant's letter No:- 2022060412046 dated 11/06/2022

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC Part-IV/ BBL	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	12 mtr.	13 mtr.	MR
	2) Gate width	4.5 mtr.	6 mtr.	MR
	3) Width of internal road	6 mtr.	06 mtr	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases	Common for star city mall building		
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	2.0 m 81.5 M	2.0 m 8 1.5 MV	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	N/A	N/A	N/A
	2) Upper floors (Gr. floor)	Required	Provided	MR
5.	Fire Extinguishers			
	1) Total numbers	04 Nos.	06 Nos.	MR
	2) Types	ABC & WCO2	Provided	MR
	3) ISI marking	Required	Provided	MR

6.	First-Aid Hose Reel			
	1) Total number of each floor	02 nos.	02 nos.	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	5 mm	5 mm	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Heat & smoke	Provided	MR
	2) Location of main panel	Control Room	Basement	MR
	3) Location of repeater panel	Reception	Provided	MR
	4) Alternate source of power	Battery & DG set	Provided	MR
	5) Hooter's Location	Strategic location	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors (Gr. floor)	Required	Provided	MR
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	150 mm	150 mm	MR
	2) Number of hydrants per floor	02 nos.	02 nos.	MR
	3) Hose box	02 nos.	02 nos.	MR
12.	Yard Hydrants			
	1) Total number of hydrants	Required	Provided	MR
	2) Hose box	Required	Provided	MR

13.	Pumping Arrangement	Common for star city mall building		
	1) Ground level	Required	Provided	MR
	a) Discharge of main pump	4500 LPM	4500 LPM	MR
	b) Head of main pump	50 mtrs.	50 mtrs.	MR
	c) Number of main pump	02	02	MR
	d) Jockey pump out put	450 LPM	450 LPM	MR
	e) Jockey pump head	50 mtrs.	50 mtrs.	MR
	f) Stand by pump output	4500 LPM	4500 LPM	MR
	g) Stand by pump head	50 mtrs.	50 mtrs.	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level	All above pumps on terrace		
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting	Common for star city mall building		
	1) Under ground tank capacity	2,00,000 ltr.	2,00,000 ltr.	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	2,50,000 ltr.	2,50,000 ltrs.	MR
15.	Exit Signage.	Required	Provided	MR

16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	Required	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

Note: FSC already issued to Star City Mall building.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/NDZ/2022/BNQT/08 dated 24/01/2022 have been rectified.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended please.

msh

Signature of the Inspecting Officer

Name :- M.K. Sharma
Designation :- ADO (LN)

A.K. Jaiswal
22/7/2022

Signature of the Inspecting Officer

Name :- A.K. Jaiswal
Designation :- DO (ED)

Dy. CFO (NDZ)

width of exits is not mentioned in report.

DO (ED)

Need fullon done.

Dy. CFO (NDZ)

Riv
29/07/22

C.F.O.
29/7/2022

Director

1/08/22

A.K. Jaiswal
28/07/2022

FF PS

DO/ED