

45
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6/DFS/MS/EH/2022/SZ/ 231

Dated. 18/8/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Limitless located at Unit No TF 10, 3rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070 in the building comprised of Two tier Basement, lower ground, upper ground plus 03 upper floors owned/occupied by Unit of Gold Petals Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of department on 12/08/2022 in the presence of Sh. Mahesh Kumar and that the premise is fit for occupancy class **Group-D Assembly** (Eating House running at 3rd Floor only) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 18/8/2022 at New Delhi by

(ATUL GARG)
DIRECTOR

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2022071514632 dated 16/07/2022)
3. M/s Limitless located at Unit No TF 10, 3rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

| | | | | |
|---------------|---|--|--|------------------------------|
| 1 | Name & Address of the Building | M/s Limitless (A unit of Gold Petals Hospitality Pvt Ltd) Unit No TF 10, 3 rd Floor, Vasant Square Mall, Vasant Kunj, New, Delhi-110070 | | |
| 2 | Type of Occupancy | Assembly Building "Group-D" Restaurant | | |
| 3 | Building Comprised of | Two tier Basement, lower ground, upper ground plus 03 upper floors (Restaurant running at 3rd floor) | | |
| 4 | Type of Case | New Case | | |
| 5 | Details of Previous NOC | Nil | | |
| 6 | Fire Safety Directives Letter No | F.6/DFS/MS/BP/2005/2251 dated 28/10/2005 F.6/DFS/MS/Mall/2020/SZ/12 Dated 09/01/2020 (Vasant Square Mall NOC) | | |
| 7 | Date of Inspection | 12/08/2022 | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Mr. Mahesh Kumar | | |
| 10 | Year of construction | 2008 | | |
| 11 | Applicant letter No. | MHA Portal Id 2022071514632 dated 16/07/2022 | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Requirement/ Existing Fire Protection | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. FSC No. F.6/DFS/MS/Mall/2020/SZ/12 Dated 09/01/2020 Vasant Square Mall | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Restaurant within Mall NA | As above As above As above | MR N/A N/A |
| 2 | Number, width, type and arrangements of exits. | | | |
| | a. Number of Staircase | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 08 Nos N/A | Provided * As above | MR N/A |
| | b. Width of Staircase | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 1.50 mtr each N/A | Provided * As above | MR N/A |
| | c. Protection of exits | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Fire check door • Pressurization | Required N/A | Provided * As above | MR N/A |
| | d. No. of continuous staircase to terrace | 08 Required | Provided * | MR |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | 1.50 m each | 1.50 m & 1.50 m | MR |
| 3 | Compartmentation. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. | Required Required 2 hrs N/A N/A | Provided * Provided * Provided* N/A N/A | MR MR MR N/A N/A |
| 4. | Smoke Management system. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Basement • Upper floors | N/A Required | As above Exhaust fans provided | N/A MR |
| 5. | Fire Extinguishers. | | | |
| | <ul style="list-style-type: none"> • Total numbers • Types • ISI Marking | 04 Nos ISI marked | 06 Nos. ABC-04, W.CO ₂ -02 Provided | MR MR MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> • Total numbers on each floor. • Length of hose-reel hose. • Nozzle Diameter | Hose Reel | 02 in Restaurant 30m 5mm | MR MR MR |

N/2

| | | | | |
|-----|--|--|--------------------|-----|
| 7 | Automatic Fire Detection and Alarming system. (Provided & Maintained by Vasant Square Mall) | Required | Smoke & Heat | MR |
| | <ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location | Required | As above | MR |
| | | N/A | N/A | N/A |
| | | Required | Provided * | MR |
| | | Required | Provided * | MR |
| 8. | MOEFA | Required | Provided * | MR |
| 9. | Public Address System | Required | Provided * | MR |
| 10. | Automatic Sprinkler System | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Basement Upper floors Sprinkler above false ceiling | Required | As above | MR |
| | | Required | Provided in Restt. | MR |
| | | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Size of Riser/Down-comer Number of Hydrant per floor Hose box. | Required | Provided * | MR |
| | | Required | Provided * | MR |
| | | Required | Provided * | MR |
| 12. | Yard Hydrants. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Total number of hydrants. 2. Hose box. | N/A | As above | N/A |
| | | N/A | As above | N/A |
| 13. | Pumping arrangements. | | | |
| | <ul style="list-style-type: none"> Ground Level | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> ➤ Discharge of main pump. ➤ Head of main pump. ➤ Number of main pumps. ➤ Jockey Pump output. ➤ Jockey Pump head. ➤ Standby Pump output. ➤ Standby Pump head. ➤ Auto Starting / Manual Stopping. ➤ Access to pump house | 4500 LPM | Provided * | MR |
| | | 60 mtr | Provided * | MR |
| | | Two | Provided * | MR |
| | | 2 x 180 LPM | Provided * | MR |
| | | 60 mtr | Provided * | MR |
| | | 4500 LPM | Provided * | MR |
| | | 60 mtr | Provided * | MR |
| | | Required | Provided * | MR |
| | | Required | Provided * | MR |
| | <ul style="list-style-type: none"> Terrace Level | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> ➤ Discharge of pump. ➤ Head of pump. ➤ Power supply. ➤ Auto starting of pump. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Underground tank capacity. <ul style="list-style-type: none"> ➤ Draw-off connection. ➤ Fire Service Inlet. ➤ Access to tank. Overhead tank capacity. | 2,50,000 Ltr | Provided * | MR |
| | | Required | Provided * | MR |
| | | Required | Provided * | MR |
| | | Required | Provided * | MR |
| | | 30,000 Ltr | Provided * | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car. Fireman's switch. Lift signage. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 17 | Standby Power Supply | Required | Provided (DG Set) | MR |
| 18. | Refuge Area | | | |
| | <ul style="list-style-type: none"> Total area Location | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 19. | Fire Control Room. | Provided & Maintained by Vasant Square Mall | | |
| | <ul style="list-style-type: none"> Detector System Panel. | N/A | As above | N/A |

11/3

| | | | | |
|--|---|----------|----------|-----|
| <ul style="list-style-type: none"> • Flow Switch Panel • PA system Panel. • Battery backup • Building floor plan | N/A | As above | N/A | |
| | N/A | As above | N/A | |
| | N/A | As above | N/A | |
| | N/A | As above | N/A | |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | N/A | As above | N/A |

Note:- * Provided & Maintained by Management of Vasant Square Mall, Vasant Kunj, New Delhi
 The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

RK
15/10/22

Signature of the Inspecting Officer
 Name: Rajesh Kumar
 Designation: ADO / BCP

Dy. CFO (SZ)

[Signature]
16/11

CFO *[Signature]*
17/11/2022

~~Director *[Signature]*~~
10/10/22

Place the copy of NOC of mall in twi's file also

ADMBD

[Signature]
10/10/22

F.T. is put up
 signature, please

~~Director *[Signature]*~~
10/10/22

uploaded
18/11/22