

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIL HEADQUARTERS: DELIH FIRE SERVICE: NEW DELIH- 110001

अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2022/ 897

Dated:

#### FIRE SAFETY CERTIFICATE

Certified that the St. Michael's Primary School, Hospital Road, Jangpura New Delhi-110013, comprised of Ground floor was granted Fire Safety Certificate by this department vide letter no.- F6/DFS /MS/School/2018/SZ/2118 dated 17.09.2018. The school building was reinspected by Assistant Divisional Officer (M. Road) from this department on 02.08.2022 in the presence of Principal and found that the school building has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building (Ground floor) is fit for occupancy of Group B "Educational Building" with effect from 1.7. 3. 2022. renewed for a 

(Sunil Chawdhary)

Dy. Chief Fire Officer Delhi Fire Service

#### Copy to:-

- 1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- 2. The Principal, St. Michael's Primary School, Hospital Road, Jangpura New Delhi-110013.

### Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

		INSP	ECTION REPORT	r			
1	N	ame & address of the building	-				
			St. Michael's Primary School, Hospital Road Jangpura New Delhi-110014.				
2	I B	uilding is comprised of	Ground floor	Demi-110014.			
3	1	ype of occupancy	Group B- Educa	tional building			
4		spe of case	Renewal	tional building			
5	- 1	etails of previous FSC		1/2010/67/2110			
	or brevious ESC		F6/DFS/MS/School/2018/SZ/2118 dated				
6	Fire safety direction letter no.		17.09.2018				
		re safety direction letter no.	F16/Estate/CC/Fire Safety/2011/3298 to 3398				
7	D	ata of in	dated 01.05.2022				
8		ate of inspection	02.08.2022		•		
		ame of the inspecting officers		nukla, ADO (M. Ro	ad)		
9		ame of the designation of	Principal				
	_	ficer from the building side					
10	Y	ear of construction	1924				
11	Α	oplicant's letter no.	Outdoor Diary No.3390 dated 14.07.2022				
S.No		inimum standard of fire	Requirement as	Provided at site	Remarks		
	pı	evention and fire safety U/R	per DOE		MR/NMR		
	33	·	Circular dated				
			01.03.2011				
1	Access to Building:						
	A	Road width	6.0 mtrs	7.0 mtrs	MR		
	В	Gate width	NA	NA	NA		
	C	Width of internal road	NA	NA	NA		
2	N	ımber, Width, Type and Arra	ingement of Exits:				
	A	Number of staircases					
		a Upper floor	NA	NA	NA		
		b Basement	NA	NA	NA		
	В	Width of staircases					
		a Upper floor	NA	NA	NA		
		b Basement	NA	NA	NA		
	C	Protection of exits	NA	NA	NA		
		a Fire check door	NA	NA	NA		
	D	No. of continuous	NA NA	NA NA	NA		
	D	staircases to terrace	INA	NA	NA		
	E	Width of corridor	NA	NA	NA		
-	F	Door size	1.0 mtrs.	1.20 mtrs.	MR		
		npartmentation:	no mas.	1.20 mas.	IVIIX		
	A		NA	NA	NA		
	В			NA	NA		
	C			NA	NA		
-	D	9		NA	NA		
-	E				NA		
:	Smo	ke Management System:					
	4		NA	NA	NA		
-							

5.	. Fi	re Extinguisher:			
	A	Total numbers	02 nos.	02 nos.	MR
	В	Types	CO2& ABC	CO2 & ABC	MR
	C	ISI marking	ISI Marked	Provided	MR
6	Fi	rst-Aid-Hose Reel:			TVIIC .
	A	Total numbers of each floor	NΛ	NA	NA
	В	Length of hose reel hose	NΛ	NΛ	NA
	C	Nozzle diameter	NA	NA	NA
7	At	itomatic Fire Detection and Al	arming System:		
	A	Type of detectors	NA	NA	NA
	В	Location of main panel	NA	NA	NA
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	NΛ	NA	NA
	E	Hooters	NA	NA	NA
8	M	OEFA:	NA	NA	NA
9	Pu	blic Address System:	NA	NA	NA
10	Au	tomatic Sprinkler System:			
	A	Basement	NA	NA	NA
	В	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	Int	ernal Hydrants:			1
	A	Size of riser/down-comer	NA	NA	NA
	В	Number of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	NA
12	Ya	rd Hydrants:			
	A	Total number of hydrants	NA	NA	NA
	В	Hose box	NA	NA	NA
13	Pur	nping Arrangements:			
A	G	round level			
	a)	Discharge of main pump	NA	NA	NA
	<b>b</b> )	Head of main pump	NA	NA	NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual stopping	NA	NA	NA
	i)	Pump house access	NA	NA	NA
3	Ter	race Level			
	a)	Discharge of pump	NA	NA	NA
	b)	Head of the pump	NA	NA	NΛ
	c)	Power supply	NA	NA ·	NA
	d)	Auto starting of pump	NA	NA	NA

St. Michael's Primary School, Hospital Road, Jangpura New Delhi-110013.

4	fichael's Primary School, Hospital Road, Jangpura New Dellu-110013.  Captive Water Storage for Fire Fighting:					
	A	Underground tank capacity	NA	NΛ	NA	
	B	Draw-off connection	NΛ	NA	NA	
	C	Fire service inlet	NA	NA	· NA	
	D	Access to tank	NA	NA	NA	
	E	Overhead tank capacity	NA	NA	NA	
15	Exi	t Signage:	NA	NA	NA	
16	Provision of Lifts:					
	A	Pressurization of lift shaft	NA	NA	NA	
	В	Pressurization of lift lobby	NA	NA	NA	
	C	Communication in lift car	NA	NA	NA	
	D	Firemen's grounding switch	NA	NA	NA	
	E	Lift signage	NA	NA	NA	
17		ndby Power Supply:	NA	NA	NA	
18	Refuge Area:					
	A	Total area	NA	NA	NA	
	В	Location	NA	NA	NA	
19	Fire Control Room:					
	A	Detector system panel	NA	NA	NA	
	В	Flow switch panel	NA	NA	NA	
	C	PA system panel	NA	NA	NA NA	
	D	Battery backup	NA	NA	NA NA	
	E	Building floor plans	NA	NA	NA NA	
20	Special Fire Protection systems for		NA		INA	
		otection of special Risks, if any:				

# Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated 01.03.2011, the FSC issued vide letter no.F6/DFS /MS/School/2018/SZ/2118 dated 17.09.2018 is recommended to be renewed.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

Dy.CFO (\$Z)

K /

DIMBO

Dy. cro (82)

r signatures ple

m < //