

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/NDZ/2022/ 389

Dated :.../.../2022

## **FIRE SAFETY CERTIFICATE**

Yours faithfully,

DIRECTOR Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Center, Minto Road, New Delhi.

2. M/S Aggarwal House, 4/14 A, Asaf Ali Road, New Delhi - 110002.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

Hlun

## **INSPECTION REPORT**

1. Name & address of the building M/S Aggarwal House located at 4/14A,

Asaf Ali Road, New Delhi

2. Type of occupancy:- Mixed Occupancy (Residential, Mercantile

& Business) B + Gr. + 04 Upper floors

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/2019/NDZ/1646 dated

20/08/19.

5. Fire safety directives No.- N/A

6. Date of inspection: 29/08/22

7. Name of the inspecting officer:- Sh. Rajinder Atwal DO/CD &

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Smt. Darshita Aggarwal

9. Year of construction:-

10. Applicant's letter No:- No. Nil dated 08.08.2022.

	ripphoant 3 letter 140	140. 1411 dai	cu 00.00.2022.	
	1			Old Case
S.No.	Minimum Standards on fire	Requirement	Provided at site	1
	Prevention and fire safety	Existing fire		MR/NMR
	U/R 33	safety		
		arrangements		
1.	Access to Building			
	1) Road width	09 mtr.	More than 09 mtr.	MR
	2) Gate width	4.5 mtr.	Directly accessible from the road	MR
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Art	rangement of E	xits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR (Being old construction)
	2. Basements	02	03	MR
	B. Width of staircase			
	1. Upper floors		1.10 Mtr.	MR
	2. Basements		1.10, 1.22 & 1.30 Mtr.	MR
	C. Protection of exits			1.00
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	01	01	MR
	staircase to terrace		12111	NI/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			) (D
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	·N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		- L (F	MR
	1) Basements	30 ACPH	Exhaust Fan	
	2) Upper floors	12 a/c per hour	Natural	MR
5.	Fire Extinguishers		10.31	MD
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR

Mlys

	2) 101			
6.	3) ISI marking	Required	Provided	MR 🙀
0.	First-Aid Hose Reel	Los		
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
7	3) Nozzle diameter  Automatic Fire Detection &	05 mm	05 mm	MR
7.				
	1) Type of detectors	Required Gr. Floor	Provided	MR
	2) Location of main panel 3) Location of repeater panel	·N/A	Provided	MR
		Required	N/A	N/A
	4) Alternate source of power 5) Hooter's Location	Every Floor	Provided	MR
	,		Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	100 mm	MR
	2) Number of hydrants per	01	01	MR
	floor			
	3) Hose box	01	01	MR
12.	Yard Hydrants			
	1) Total number of hydrants	·N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
	pump			1
	<ul> <li>d) Jockey pump out put</li> </ul>	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	900 & 180	900 & 180 LPM	MR
		LPM		
	b) Head of pump	40 mtr.	40 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
				Ц
14.	Captive Water Storage for Fi	re Fighting	DI/A	N/A
	Under ground tank	N/A	N/A	IN/A
	capacity	121/4	21/4	N/A
	a) Draw-off connection	N/A	N/A	MR
	b) Fire service inlet	Required	Provided	IVIIC

	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	50,000 ltr.	50,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			IVIK
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MD
	e) Lift signage	Required	Provided	MR MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System if any: One ABC fire extinguisher f	m for Protection	on of special Risk,	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issue vide letter no. F6/DFS/MS/2019/NDZ/1646 dated 20/08/19. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name :- Rajinder Atwal Designation :- DO (CD)

 $\overline{MR}$ 

MR MR MR

MR MR

1R

Signature of the Inspecting Officer

Name :- Ravinder Singh Designation :- ADO (CC)

Dycho (noz)

CFO. Mugh 31 81 son

DOT C

is put up for

49/22